TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48088295
Order No. / Reference: 26824680
Inspection date: 12 Oct 2026

Manufacturer: Seat	Model: Tarraco 2.0 TDI SCR DSG Style
VIN: VSSZZZKN8RW005045	





Vehicle details

Manufacturer / Type / Model / Equipment	
Seat Tarraco 2.0 TDI SCR DSG Style	
Vehicle Identification number	VSSZZZKN8RW005045
Mileage (Read)	174,834 km
First registration	15 Nov 2023
Number of holders	1
Next periodical technical inspection	11/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Urano Grau
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	497 Tag(e)
Last service on / at	09/2026 at 173,756 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV880698
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / AOR 03860		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,270 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 100V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/55 R18 100V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/65 R17 99H	Winter tyres on Light alloy	Pirelli	2mm / 3mm
2)	215/65 R17 99H	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	145/85 R18 103M	Summer tyres on Steel	Sonstige	7 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12V socket at the front
- Storage pocket on the back of the front seats
- Automatic coming-home and leaving-home function
- Electrically adjustable, folding and heated exterior mirrors
- Turn signals and welcome light integrated into the exterior mirrors
- Black headliner
- Diesel particulate filter and SCR catalyst
- Tachometer
- Third brake light
- Electronic parking brake including auto-hold function
- Electric windows front and rear
- Gear recommendation display
- luggage compartment cover
- Illuminated glove compartment
- Rear window wiper and rear window heater
- ISOFIX child seat restraint system
- Air conditioning
- Black radiator grille
- Steering wheel: Multifunction steering wheel in leather
- Light sensor with automatic headlight control
- Fatigue detection
- LED fog lights with cornering light function
- Upholstery: Cloth
- Rain sensor
- Wheels: 4 "Dynamic" alloy wheels
- paddle shifters on the steering wheel
- Electromechanical power steering
- Seats: Comfort seats
- Seats: Lumbar support for driver and front passenger
- Seats: Front seats with height adjustment
- Sun visors with illuminated makeup mirror
- Start-stop technology
- Front Assist area monitoring system with City Emergency Braking function
- Virtual Cockpit
- Electronic immobilizer
- Central locking, including tailgate, with remote control
- Storage compartment for glasses
- Airbags
- Adaptive Cruise Control (ACC) up to 210 km/h
- Exterior mirror housings in body color
- Owner's manual holder under the driver's seat
- Chrome applications in the interior
- Roof rails in black
- Electronic differential lock (XDS)
- Three-point automatic seat belts, front and rear
- Rear parking sensors
- Electronic Stability Control (ESC)
- Footwell lighting
- luggage compartment, illuminated
- Transmission: 7-speed DSG automatic transmission
- LED taillights
- Interior mirror automatically dimming
- Body covers on the wheel arches
- Headrests, 2 front, 3 rear
- Paint finish: Solid
- Reading lights, 2 in the front and 2 in the rear
- Center console with integrated storage compartment, center armrest, cup holders
- Emergency call service
- Radio: Media System Plus
- Tire pressure monitoring system
- Wheels: Tyre fit
- SEAT CONNECT
- Seats: Front passenger seat backrest can be folded down completely
- Seats: Rear bench seat longitudinally adjustable and asymmetrically split and foldable
- Lane departure warning system
- LED daytime running lights
- Variable luggage compartment floor
- Lashing eyes in the luggage compartment
- Full LED headlights
- thermal insulation glazing

Extra equipment

- Swiveling towbar with electric release
- Package: Storage package (storage compartment under the passenger seat - comfort storage tray in the headliner - luggage compartment net)
- Package: Winter (STYLE) (Heated front seats)
- Wheels: 4 "Performance" light alloy wheels, diamond-turned (7J x 18", tires 235/55 R18)
- Luggage partition net (including remote release for folding down the rear seat backrest)
- Package: Business Package NAVIGATION (Navigation system with 9.2" color touchscreen, voice control - Full Link: Android Auto, Apple CarPlay - Wireless charger in the storage compartment of the center console - Spare wheel as emergency wheel)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	2nd wheel set	2 tyres - does not meet manufacturer specifications - No deduction
2	Sill - left side	Sill - Scratch(es) - Smart repair
3	Rear bumper	Rear bumper - Scratch(es) - Smart repair

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view




Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Damage 1: 2nd wheel set: 2 tyres - does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres - does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres - does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres - does not meet manufacturer specifications - No deduction



Damage 1: 2nd wheel set: 2 tyres - does not meet manufacturer specifications - No deduction




Damage 2: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 2: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Rear bumper: Rear bumper - Scratch(es) - Smart repair