TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48621811
Order No. / Reference: 27204705
Inspection date: 4 Nov 2026

Manufacturer: Ford	Model: Transit 350 L4H3 Lkw HA Trend Kasten
VIN: WF0EXXTTRERR71901	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L4H3 Lkw HA Trend Kasten	
Vehicle Identification number	WF0EXXTTRERR71901
Mileage (Read)	62,678 km
First registration	25 Nov 2024
Number of holders	1
Next periodical technical inspection	11/2026
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Rear drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	4 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
Type of use	rental car
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	20,000 km
Last service on / at	12/2024 at 10 km		
Key is / should be	1 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB847279
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	8566 / BNG 10877		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	All-season tyres on Steel rim with wheel cover	Sonstige	0mm / 0mm
2)	235/65 R16 121R	All-season tyres on Steel rim with wheel cover	Sonstige	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- Rubberized floor, entire vehicle length
- On-board computer
- Double-leaf rear doors with a 256° opening angle (without windows)
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area lighting
- MyKey key system
- Particulate filter: diesel particulate filter
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Sliding door: Sliding door, right
- Rear mud flaps
- Low side paneling
- Seat belts
- Seats: Seat package 13
- Rear bumper with integrated step
- Partition wall (plastic) with window
- Immobiliser
- Central locking with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- Battery: Battery life, programming of battery life to 10 minutes
- roof, high
- Tachometer
- Third brake light
- Windows: Sliding windows, right and left (at the height of the 2nd row of seats)
- Ford Easy Fuel
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Emergency call assistant
- Wheels: Wheel trims
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Seats: Rear seat package 2
- Start-stop system
- Daytime running light
- Lashing eyes
- Heat-insulating glazing, lightly tinted
- Front overhead storage compartment

Extra equipment

- Airline rails 2
- Cargo area protection package 2
- Central locking (second key, foldable with remote control including central locking)
- KEP parcel
- Wheels/Tires: Spare wheel, steel wheel
- Wheels: All-season tires (suitable for winter use)
- Package: Technology Package 10 (Heated windscreen, rain-sensing wipers - Front and rear parking sensors, active emergency braking assist (camera-based) - Lane Keeping Assist with Driver Alert and High Beam Assist; additionally with Lane Departure Warning - Automatic Headlights with Day/Night Sensor - Cruise Control - Rearview Camera with image transmission of the rear view on the multifunction display - LED Downlights - Fog Lights - Ford Audio System with 4" multifunction display)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Engine	Engine - Functional / admissibility - Perform diagnosis
2	Wing mirror - left side	Mirror glass (Unten) - Broken / torn - Replace
3	Boot lid / rear door	Rear door - right side - dent(s) - Smooth repair work
4	Door - front right side	Door - Scratch(es) - Smart repair
5	Front axle	Axles / undercarriage (Reifen einseitig abgefahren) - Malposition - Set / adjust
6	Braking system	Braking system - Functional / admissibility - Perform diagnosis
7	Wheel / tyres	Tyre - front (Einseitig abgefahren) - Worn - Replace
8	Rear bumper	Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace
9	Seat - front	Seat cover - left side (+ Polster) - Broken / torn - Replace
10	Vehicle glazing	Windscreen (Rissbildung, Sichtfeld) - Stone chips - Replace

Missing parts

Description
Wheel / tyres - Spare wheel
Equipment - Vehicle key with remote control

Accident damages

No.	Accident
1	Front

Repainting

No.	Repainting
1	Boot lid / rear door, Professionally carried out, Invoice of repair done Non-existent
2	Mudguard - left side, Professionally carried out, Invoice of repair done Non-existent
3	Mudguard - right side, Professionally carried out, Invoice of repair done Non-existent
4	Bonnet, Professionally carried out, Invoice of repair done Non-existent
5	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
6	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent
7	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
8	Door - front left side, Professionally carried out, Invoice of repair done Non-existent
9	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Boot lid / rear door	151 µm	Mudguard - left side	176 µm
Mudguard - right side	174 µm	Bonnet	169 µm
Side panel - rear left side	168 µm	Side panel - rear right side	167 µm
Door - rear right side	152 µm	Door - front left side	147 µm
Door - front right side	160 µm		

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

- Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Damage 1: Engine: Engine - Functional / admissibility - Perform diagnosis



Damage 2: Wing mirror - left side: Mirror glass (Unten) - Broken / torn - Replace



Damage 2: Wing mirror - left side: Mirror glass (Unten) - Broken / torn - Replace



Damage 3: Boot lid / rear door: Rear door - right side - dent(s) - Smooth repair work



Damage 3: Boot lid / rear door: Rear door - right side - dent(s) - Smooth repair work



Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 4: Door - front right side: Door - Scratch(es) - Smart repair



Damage 5: Front axle: Axles / undercarriage (Reifen einseitig abgefahren) - Malposition - Set / adjust



Damage 5: Front axle: Axles / undercarriage (Reifen einseitig abgefahren) - Malposition - Set / adjust



Damage 5: Front axle: Axles / undercarriage (Reifen einseitig abgefahren) - Malposition - Set / adjust



Damage 6: Braking system: Braking system - Functional / admissibility - Perform diagnosis



Damage 7: Wheel / tyres: Tyre - front (Einseitig abgefahren) - Worn - Replace



Damage 7: Wheel / tyres: Tyre - front (Einseitig abgefahren) - Worn - Replace



Damage 7: Wheel / tyres: Tyre - front (Einseitig abgefahren) - Worn - Replace



Damage 7: Wheel / tyres: Tyre - front (Einseitig abgefahren) - Worn - Replace




Damage 8: Rear bumper: Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace



Damage 8: Rear bumper: Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace



Damage 8: Rear bumper: Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace



Damage 8: Rear bumper: Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace



Damage 8: Rear bumper: Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace



Damage 8: Rear bumper: Rear bumper (verformt, Innen+Außenteil+Rückstrahler) - Scratched - Replace




Damage 9: Seat - front: Seat cover - left side (+ Polster) - Broken / torn - Replace



Damage 9: Seat - front: Seat cover - left side (+ Polster) - Broken / torn - Replace



Damage 10: Vehicle glazing: Windscreen (Rissbildung, Sichtfeld) - Stone chips - Replace




Damage 10: Vehicle glazing: Windscreen (Rissbildung, Sichtfeld) - Stone chips - Replace



Missing part 1: Wheel / tyres: Spare wheel - Missing - Replace



Missing part 2: Equipment: Vehicle key with remote control - Missing - Replace



Accident 1: Front



Accident 1: Front




Accident 1: Front



Accident 1: Front



Accident 1: Front



Accident 1: Front



Repainting 1: Boot lid / rear door



Repainting 2: Mudguard - left side



Repainting 3: Mudguard - right side



Repainting 4: Bonnet



Repainting 5: Side panel - rear left side



Repainting 6: Side panel - rear right side



Repainting 7: Door - rear right side



Repainting 8: Door - front left side



Repainting 9: Door - front right side