TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig


Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

# Expertise

Protocol number: 48201912
Order No. / Reference: 26926677
Inspection date: 15 Oct 2026

| | |
|---|---|
| Manufacturer: Skoda | Model: Octavia 2.0 TDI DSG Style |
| VIN: TMBAJ8NX3PY047881 | |




## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Skoda Octavia 2.0 TDI DSG Style | |
| **Vehicle Identification number** | TMBAJ8NX3PY047881 |
| **Mileage** (Read) | 68,824 km |
| **First registration** | 28 Mar 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** | 06/2028 |
| (Report on hand) | |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,968 ccm / 4 |
| **Power** | 110 kW |
| **Gearbox / Number of gears** | Automatic / 7 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Saloon car |
| **Colour / colour code** | Lava-Blau Metallic (W5Q) |
| **Doors / Seats** | 5 / 5 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Beige-Anthracite |
| **Re-import** | no |
| **Vehicle with smoke odor** | no |
| **readiness to drive** | Roadworthy |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 8,100 km |
| **Last service on / at** | 07/2026 at 62,631 km | | |
| **Key is / should be** | 2 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GQ550201 |
| **Previous damage / Accident** | Detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **readiness to drive** | Roadworthy | | |
| **Manufacturer key number/ type code number** | 8004 / AWG 00521 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 1,987 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 225/45 R18 91Y | Summer tyres on Light alloy | Goodyear | 4mm / 4mm |
| 2) | 225/45 R18 91Y | Summer tyres on Light alloy | Goodyear | 5mm / 5mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 205/60 R16 92H | Winter tyres on Light alloy | Goodyear | 6mm / 6mm |
| 2) | 205/60 R16 92H | Winter tyres on Light alloy | Goodyear | 8mm / 8mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| | Tirefit | Expiration date 03/2030 | | |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag for driver and front passenger (passenger airbag can be deactivated)
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Ambient lighting (dashboard, front trim strips and footwell with selectable color climate) in the interior as well as logo projector on the outside)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors with memory function (boarding spots in the exterior mirrors as well as memory function and mirror lowering)
- Hill start assist including auto-hold function
- Glasses compartment in the headliner
- Decorative strip in silver finish with ambient lighting
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant (Coming Home / Leaving Home function)
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Removable boot cover
- Headrests (5) front and rear height adjustable
- Paint finish: Solid
- LED fog lights
- LED license plate lights
- LED headlights with LED daytime running lights
- Steering wheel: height and reach adjustable
- Manual headlight range adjustment
- Rear center armrest with pass-through option
- Front center armrest, including storage compartment
- Engine drag torque control (MSR)
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Rain sensor
- Tire mobility kit (tire repair spray incl. compressor)
- Electromechanical power steering
- Seat belts (Three three-point seat belts in the rear)
- Seats: Heated front seats
- Seats: Height-adjustable driver and passenger seats (including lumbar support)
- Storage compartments (Four roof grab handles, rear with coat hooks; holder for the warning vest under the driver's seat; storage compartments in the front door panels with 1.5l bottle holders; storage compartments in the rear door panels with 0.5l bottle holders; ticket holder on the windshield; coat hooks on the B-pillars; storage compartments in the doors with felt lining)
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Center section of the dashboard with fabric covering
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Hydraulic brake assist (HBA)
- Grey headliner
- Diesel particulate filter
- Tachometer
- Electronic parking brake
- Electronic Stability Control (ESC)
- Driving profile selection
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Tinted windows
- Heated rear window
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Climatronic air conditioning (2-zone) (fully automatic, separately adjustable for driver and front passenger and anti-allergen filter & activated carbon filter - air-conditioned and illuminated glove compartment)
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters (leather steering wheel and gearshift lever with leather elements - infotainment and driver assistance system operation)
- Front and rear parking sensors
- Radio: Bolero music system with capacitive 10" color display
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink (Apple CarPlay - Android Auto)
- Tire pressure monitoring
- Wheels: 17" alloy wheels Rotare AERO (7J x 17, ET 46 with tires 205/55 R17)
- Safety lights in the front side doors
- Seats: Electrically adjustable front seats with memory function
- Seats: Rear seat backrest split 60:40, foldable
- Speed limiter
- Lane keeping assistant (Lane Assist)
- Lane change and parking assist as well as exit warning
- 12V socket in the trunk

- SKODA Care Connect (SOS emergency call function (eCall+ including automatic activation in the event of an accident with airbag deployment) - Mobility service (connection option for rapid assistance in case of breakdown) - Information service (connection option to the hotline for all questions relating to vehicle functions) - Free remote vehicle access for 1 year (Remote Access) with access to vehicle data and functions via smartphone, e.g. parking position, activating hazard warning lights, current fuel level)
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Phone: Wireless SmartLink for Apple CarPlay
- Lashing eyes in the trunk
- Immobiliser
- Central locking including remote control integrated into the key and EASY Start

### Extra equipment

- Dashboard in beige
- Comfort opening with electric tailgate operation
- Package: Infotainment Columbus Plus (Columbus navigation system - Infotainment Online (3-year term) - Head-Up Display)
- Decorative trim in piano black
- Paint finish: Metallic
- Wheels: 18" Perseus alloy wheels, silver polished (7.5J x 18, ET 48 with 225/45 R18 tires)
- Heated windscreen

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |
| readiness to drive | The vehicle was roadworthy at the time of inspection. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Seat - front | Seat cover - left side - Soiled - Clean |
| 2 | Side panel - rear left side | Side panel - dent(s) - Smooth repair work |
| 3 | Door - rear left side | Door - Scratch(es) - Smart repair |
| 4 | Mudguard - right side | Mudguard - right side - Scratch(es) - Smart repair |
| 5 | Front bumper | Front bumper - Scratch(es) - Smart repair |
| 6 | Rear bumper | Rear bumper - Scratch(es) - Paint |

## Wear and tear

| No. | Component group | Description |
|---|---|---|
| 1 | Vehicle glazing | Windscreen - Stone chips - No deduction |
| 2 | Door - front left side | Door (Auslegen polieren) - Scratch(es) - No deduction |
| 3 | Wheel / tyres | Alloy rim - front right side - Scratch(es) - No deduction |

The vehicle shows signs of wear and tear commensurate with its age and use.

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Rear, Provided by user / customer, from 16 Sept 2025 | 2.131,22 € |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

## Comments

- Der beiliegende Winterradsatz ist kein Bestandteil der Auslieferungsumfangs.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front




**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel



**Figure 9:** Cargo area





**Figure 10:** VIN



**Figure 11:** Mounted tyres




**Figure 12:** Documents




**Figure 13:** Documents




**Figure 14:** Documents



**Figure 15:** Additional tyres





**Figure 16:** Navigation




**Figure 17:** Misc.



**Figure 18:** Misc.



**Figure 19:** Misc.



**Figure 20:** Misc.




**Figure 21:** Misc.




**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.



**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.




**Damage 1:** Seat - front: Seat cover - left side - Soiled - Clean



**Damage 1:** Seat - front: Seat cover - left side - Soiled - Clean




**Damage 2:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work



**Damage 2:** Side panel - rear left side: Side panel - dent(s) - Smooth repair work




**Damage 3:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 3:** Door - rear left side: Door - Scratch(es) - Smart repair



**Damage 4:** Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair



**Damage 4:** Mudguard - right side: Mudguard - right side - Scratch(es) - Smart repair




**Damage 5:** Front bumper: Front bumper - Scratch(es) - Smart repair




**Damage 5:** Front bumper: Front bumper - Scratch(es) - Smart repair




**Damage 6:** Rear bumper: Rear bumper - Scratch(es) - Paint




**Damage 6:** Rear bumper: Rear bumper - Scratch(es) - Paint



**Damage 6:** Rear bumper: Rear bumper - Scratch(es) - Paint




**Wear and tear 1:** Vehicle glazing: Windscreen - Stone chips - No deduction




**Wear and tear 1:** Vehicle glazing: Windscreen - Stone chips - No deduction



**Wear and tear 2:** Door - front left side: Door (Auslegen polieren) - Scratch(es) - No deduction



**Wear and tear 2:** Door - front left side: Door (Auslegen polieren) - Scratch(es) - No deduction



**Wear and tear 2:** Door - front left side: Door (Auslegen polieren) - Scratch(es) - No deduction