Audi

VIN: WAUZZZF33M1096688



Description

Registration number 2AEK374	**First registration date** 09/03/2021	**Odometer** 133218 km
Color Gris Nano Métallisé	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
Engine displacement 1498	**Gearbox type** Automatic	**Engine type** Combustion
Number of gears 7	**Drivetrain** Front Wheel Drive (FWD)	**Max power** 110 KW

Vehicle Equipments

Rain-sensitive wipers	Automatic headlights	Climate control
Alloy wheel rims	Hydraulic tail board	Cruise control
Electrically foldable door mirrors	Heated door mirrors	SATNAV

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 22/10/2026	**Inspection approval date** 23/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

Defects & corrections

#	Element	Defect	Correction
001	Refill emergency kit / -	Missing	Replace


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




002	Windscreen / - Camera : Yes / Rain sensor : Yes	Broken	Replace




003	Door / Back Left	Dent	Acceptable

004	Bumper / Back Painted : Yes	Scratched	Acceptable





005	Tailgate / Boot door / - [1]	Dent	Smart repair









006	Rear windscreen / Back Tinted window : No	Sticker	Removal



007	Interior complete / -	Stained	Cleaning

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.





[1] 3x sous réserve

Loose Items

- [x] Conformity certificate
- [x] Registration certificate
- [x] Registration certificate owner
- [x] Card key
- [x] Spare Key
- [x] Rear parcel shelf
- [ ] Refill tyre repair kit

Main set of tyres


Front Left	SEMPERIT	215/65/17 Winter	6 mm
Front Right	SEMPERIT	215/65/17 Winter	6 mm
Back Left	SEMPERIT	215/65/17 Winter	8 mm
Back Right	SEMPERIT	215/65/17 Winter	8 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.


Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment


Front right




Odometer



Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other




Other



Refill emergency kit / - / Missing



Refill emergency kit / - / Missing




Windscreen / - / Broken



Windscreen / - / Broken



Door / Back Left / Dent



Door / Back Left / Dent



Bumper / Back / Scratched



Bumper / Back / Scratched



Bumper / Back / Scratched




Tailgate / Boot door / - / Dent



Tailgate / Boot door / - / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Tailgate / Boot door / - / Dent




Tailgate / Boot door / - / Dent



Tailgate / Boot door / - / Dent



Tailgate / Boot door / - / Dent



Tailgate / Boot door / - / Dent



Rear windscreen / Back / Sticker



Interior complete / - / Stained



Interior complete / - / Stained



Interior complete / - / Stained

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.