TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48395218
Order No. / Reference: 27190967
Inspection date: 29 Oct 2026

Manufacturer: Opel	Model: Grandland 1.5 D Automatik GS
VIN: W0VZCYHZ5P6036621	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Grandland 1.5 D Automatik GS	
Vehicle Identification number	W0VZCYHZ5P6036621
Mileage (Read)	86,516 km
First registration	11 Sept 2023
Number of holders	1
Next periodical technical inspection	09/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Quarz Silber Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	5 Monat(e)
Last service on / at	03/2026 at 77,230 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY721257
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1844 / AHG 00268		
Permitted total weight	2,000 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/55 R18 102V XL	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/55 R18 102V XL	Summer tyres on Light alloy	Michelin	4mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaautomatik

Standard equipment

- 2 ignition keys, both foldable
- Driver and passenger side airbags
- Airbag: Front and side airbags
- Airbag: Head airbags, front and rear outer
- Ambient lighting, center console and in the front door pockets
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Automatic activation of the hazard warning lights (and unlocking of the doors after deployment of the airbag and seatbelt tensioner)
- Hill Start Assist
- Roof in Diamond Black
- Decor: Opel Vizor with chrome frame
- Decorative trim strips, Dax/Palladium Medium
- Third brake light
- Electronic brake force distribution (EBD)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- luggage compartment cover
- Cruise control with intelligent speed limiter (The intelligent speed limiter, in conjunction with traffic sign recognition, allows for rapid speed adjustment)
- Interior lighting, front and rear (with reading lights front and rear - luggage compartment lighting)
- Dual-zone automatic climate control including rear footwell heating (with separate temperature control for driver and front passenger - manual recirculation - automatic air distribution - sun sensor - particle and odor filter)
- Leather steering wheel, flat-bottomed, with steering wheel remote control
- Illuminated makeup mirror in sun visor, for driver and front passenger
- Package: Comfort package (Park pilot, front and rear parking aid with acoustic warning signal - electrically folding exterior mirrors)
- Radio accessories: Digital radio reception DAB+ (Offers a wider selection of radio programs. Digitally broadcast radio stations and traffic information can be received.)
- Rain sensor
- Tire pressure warning
- Wheels: Light alloy 7.5 J x 18 with 5 double spokes in bicolor/high-gloss black (with tires 225/55 R 18)
- Wheels: Tire repair kit (with tire sealant and 12-volt compressor (without jack))
- Speed-sensitive power steering
- Seats: Ergonomic active seat with AGR seal of approval, driver (length, height and backrest angle manually adjustable - seat tilt electrically adjustable - lumbar support electropneumatically adjustable in height and length - extendable thigh support, manually adjustable - pocket on front seat back - all seats in Track Black fabric)
- Storage compartments (storage compartment in the instrument panel, driver's side - storage compartment in the center console, front - storage compartment in the front doors, suitable for 1.5-liter beverage bottles - storage compartment in the rear doors, suitable for 1.0-liter beverage bottles - illuminated glove compartment with cooling and heating function - bag hooks, on the side in the luggage compartment - lashing eyes in the luggage compartment)
- Exterior mirrors, electrically adjustable and heated, electrically folding (exterior mirror housing in black)
- On-board computer
- Decor: Opel Blitz, "Grandland" lettering on the rear and high-gloss black surround for air intakes
- Diesel particulate filter with SCR and oxidation catalyst
- Electric parking brake
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning (with automatic emergency braking, pedestrian detection, active lane keeping assist, traffic sign recognition, driver drowsiness detection)
- Transmission: 8-speed automatic
- Heated rear window
- rear window wiper
- Interior rearview mirror, automatically dimming
- Child safety lock in the rear doors, manual
- Rear headrests (3), height adjustable
- Front headrests, height adjustable
- Paint finish: Metallic Ruby Red
- LED headlights (LED taillights - LED front turn signals - manual headlight range control - high beam assist)
- Steering wheel, height and reach adjustable
- Center armrest, sliding, front, including storage compartment and cup holder
- Front and rear parking sensors
- Quickheat heating system
- Radio: Multimedia Radio Pro (with 10" touchscreen and fully digital 12" driver information display - Bluetooth audio streaming - Automatic music recognition - Hands-free system - Phonebook and call list display - Smartphone integration via Apple CarPlay and Android Auto - Display and operation of selected apps and functions via the 7" touchscreen or voice control, e.g., navigation, music, telephone - Text message reading and dictation - Steering wheel controls - 6 speakers, 4 x 20 watts, FM/AM - USB - Dual tuner - Graphic equalizer)
- Seat belts (three-point seat belts in all seats - height-adjustable seat belts, front - belt force limiters, front and rear outer seats - double belt tensioners, front - belt tensioners, rear outer seats - warning tone and light for unfastened seat belts, front and rear)
- Seats: Rear seat backrest split 40:60 and foldable
- Solar Protect heat-insulating glazing (heavily tinted, in the rear)
- Start/Stop System (Reinforced starter motor - High-performance battery - Switch to deactivate the start/stop function)

- Lane departure warning (warning in case of unintentional lane departure from 60 km/h via warning tone and indicator light in the driver information display)
- 12-volt power outlet (in the center console, front)
- Underride protection look, front and rear, in high-gloss black
- Immobiliser
- Central locking with remote control and interior switches
- Pre-wiring for ISOFIX child seat mounting system, including top tether attachment points, rear outer (and for ISOFIX child seat mounting system on the front passenger seat)

Extra equipment

- Detachable trailer hitch (trailer stability program)
- IntelliLux LED Matrix Light (Adaptive LED matrix headlights with individual light distribution and the following functions: - City light - Highway light - Country road light - Static cornering light - Turning light - Parking light - High beam assist: traffic-dependent dimming taking into account preceding and oncoming traffic - Automatic headlight range control - Fog lights)
- Package: Technology Package (Keyless locking and starting system "Keyless open & start" - Electric tailgate)
- Paint finish: Metallic
- Radio: Multimedia Navi Pro incl. OpelConnect (with 10" color touchscreen display and voice control for audio, telephone and navigation - Navigation: with integrated memory, European road map, 3D map display, dynamic route guidance via map and/or arrow display, GPS module - Display and readout of emails - USB interfaces - High-gloss black shark fin antenna - Bluetooth audio streaming - Hands-free system - Smartphone integration, Apple CarPlay, Android Auto - Radio)
- Front collision warning (with automatic emergency braking, pedestrian detection, active lane keeping assist, traffic sign recognition, driver drowsiness detection, automatic speed assist with stop function)
- Park & Go Premium (360-degree camera (degrees displayed in the infotainment system's color screen, with steering guidelines) - Automatic parking assistant (detection of parallel and perpendicular parking spaces at speeds below 20 km/h, exiting parallel parking spaces, automatic steering of the vehicle), including park pilot, front and rear parking aid with audiovisual warning - Electrically folding exterior mirrors - Blind spot warning in both exterior mirrors (active between 12 km/h and 140 km/h))
- Seats: Ergonomic active seats with AGR seal of approval, driver and front passenger (leather, black, partially perforated, including seat contact surface, seat bolsters in leather (headrest, door trim, outer seat bolsters in leatherette)). Driver's seat 8-way electrically adjustable (length, height, backrest, seat tilt), memory function. Front passenger seat 6-way manually adjustable (length, height, backrest tilt). Electrically adjustable seat tilt. Electrically adjustable lumbar support (height and length). Extendable thigh support, manually adjustable. Pocket on front seat back. Seat valve. Winter exterior including heated front seats and heated windshield.

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	C-pillar - trim - interior, right side - Scratch(es) - Loss in value
2	Mudguard - right side	Mudguard - right side - dent(s) - Smart repair
3	Bonnet	Bonnet (Mit Steinschlag) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Front bumper	Front bumper - Scratched - No deduction
3	Wing mirror - left side	Mirror housing - Scratch(es) - No deduction
4	Wing mirror - right side	Mirror housing - Scratch(es) - No deduction
5	Vehicle glazing	Windscreen - Stone chips - No deduction
6	Door - front right side	Door edge - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 2 Jul 2026	3.493,06 €

Repainting

No.	Repainting
1	Mudguard - left side, Door - rear left side, Door - front left side
2	Bumper rear

Paint coat thickness measurement

Mudguard - left side	159 µm	Door - rear left side	151 µm
Door - front left side	131 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN




Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Damage 1: Trim / covers: C-pillar - trim - interior, right side - Scratch(es) - Loss in value



Damage 1: Trim / covers: C-pillar - trim - interior, right side - Scratch(es) - Loss in value



Damage 2: Mudguard - right side: Mudguard - right side - dent(s) - Smart repair




Damage 2: Mudguard - right side: Mudguard - right side - dent(s) - Smart repair



Damage 3: Bonnet: Bonnet (Mit Steinschlag) - Scratch(es) - Paint



Damage 3: Bonnet: Bonnet (Mit Steinschlag) - Scratch(es) - Paint




Damage 3: Bonnet: Bonnet (Mit Steinschlag) - Scratch(es) - Paint



Damage 3: Bonnet: Bonnet (Mit Steinschlag) - Scratch(es) - Paint



Damage 3: Bonnet: Bonnet (Mit Steinschlag) - Scratch(es) - Paint



Damage 3: Bonnet: Bonnet (Mit Steinschlag) - Scratch(es) - Paint



Repainting 1: Mudguard - left side, Door - rear left side, Door - front left side



Repainting 1: Mudguard - left side, Door - rear left side, Door - front left side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Repainting 1: Mudguard - left side, Door - rear left side, Door - front left side