TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48513448
Order No. / Reference: 27213510
Inspection date: 30 Oct 2026

Manufacturer: Opel	Model: Mokka 1.2 DI Turbo Automatik Elegance
VIN: VXKUSHNSSNW057699	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Mokka 1.2 DI Turbo Automatik Elegance	
Vehicle Identification number	VXKUSHNSSNW057699
Mileage (Read)	130,276 km
First registration	8 Sept 2022
Number of holders	1
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Jade Weiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	19,100 km
Last service on / at	09/2026 at 129,462 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ694881
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / ADB 00031		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,740 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/60 R17 100V	All-season tyres on Light alloy	Pirelli	5mm / 5mm
2)	215/60 R17 96H	All-season tyres on Light alloy	Kleber	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 08/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 ignition keys, both foldable
- Adaptive brake light
- Airbag: Front and side airbags
- Actively controlled air intakes (Active Aero Shutter)
- Exterior mirrors in black
- Exterior mirrors, electrically adjustable and heated, manually foldable
- Headliner, Grey
- Decorative strips, silver
- Third brake light
- Electronic Stability Program Plus (ESP Plus)
- Front collision warning with automatic city emergency braking and pedestrian detection
- Transmission: 8-speed automatic
- rear window wiper
- Child safety lock in the rear doors, manual
- Front headrests and 3 rear headrests, height adjustable
- LED headlights
- Steering wheel: Leather steering wheel, flattened at the bottom with paddle shifters
- Makeup mirror in sun visor, driver and front passenger
- Multi-collision brake
- Otto particulate filter
- Upholstery: Fabric/Premium leather look
- Radio: Multimedia Radio
- Wheels: Light alloy (4) 5 double spokes 6.5 J x 17 in BiColor Black
- Side impact protection
- Seat belts
- Seats: Passenger seat 6-way manually adjustable
- Seats: Comfort seats, front
- Seats: Pre-installation for ISOFIX child seat mounting system, front passenger seat and rear outer seats
- 12-volt power outlet
- Ambient lighting
- Traffic sign recognition
- Tinted heat-insulating glazing
- Storage compartments
- Driver and passenger side airbags
- Airbag: Head airbags, front and rear outer
- Anti-lock braking system (ABS) with cornering brake control and brake assist
- Hill Start Assist
- Roof design line in chrome
- Roof spoiler, black
- Tachometer
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Pedestrian protection
- Cruise control with intelligent speed limiter
- Heated rear window
- Rear shelf
- automatic climate control
- LED fog lights
- Steering wheel: Heated leather steering wheel
- Steering column, height and tilt adjustable
- Reading lights, front
- Center armrest, front
- Fatigue detection
- Parkpilot, rear parking aid, with acoustic warning signal when reversing.
- Tire pressure warning
- Wheels: Tire repair kit
- "Mokka" lettering on the rear in chrome
- Speed-sensitive power steering
- Visibility equipment
- Seats: Driver's seat 6-way manually adjustable
- Seats: Rear seat backrest foldable in a 60:40 ratio
- Lane Keeping Assist
- Start/Stop System
- Traction control with engine and brake intervention TC Plus
- Underride protection look, front and rear, in silver
- Immobiliser
- Central locking with remote control

Extra equipment

- Roof and A-pillar in carbon black
- Paint finish: Solid Arctic White
- Radio: Multimedia Navi (with 7" color touchscreen display and fully digital 7" driver information display - Navigation with integrated memory - European road map - 3D map display - Dynamic route guidance via map and/or arrow display - Display of points of interest - Trip plan. - OpelConnect GPS module, including LIVE navigation services: - Map updates. - Voice control for audio, telephone and navigation. - Radio, Bluetooth, DAB+, USB, hands-free.)
- Double boot floor
- Park & Go (Park Pilot, front and rear parking aid with audiovisual warning - 180-degree panoramic reversing camera - blind spot warning and side protection - electrically folding exterior mirrors - ambient lighting)
- Keyless locking and starting system "Keyless Open & Start" (Keyless unlocking for driver's door and luggage compartment - engine start button)
- Seats: Heated seats, multi-stage, driver and front passenger

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Screen cleaning	Wiper arm - rear (Abdeckung) - Missing - Replace
2	Equipment	Tirefit filler - Expired - Replace
3	Wing mirror - left side	Cap - Scratch(es) - Smart repair
4	Door - front left side	Door edge - Scratch(es) - Smart repair
5	Wheel / tyres	Tyre - front right side - Porous / cracked - Replace
6	Wheel / tyres	Tyre - front left side - Porous / cracked - Replace
7	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
8	Wheel / tyres	Alloy rim - front left side - Scratch(es) - Replace
9	Rear bumper	Spoiler - Scratch(es) - Paint
10	Interior	Interior - Scratch(es) - Loss in value
11	Mudguard - right side	Mudguard - right side (Farbflecken) - Paint defect - Paint
12	Side panel - rear right side	Side panel - Dent / paintcoat damage - Repair and paint
13	Door - rear left side	Door - Scratch(es) - Paint
14	Boot lid / rear door	Boot lid - Scratch(es) - Paint
15	Roof	Roof - Scratch(es) - Paint
16	Body	Body - Damage by hail - repair according to calculation

Wear and tear

No.	Component group	Description
1	Sill - right side	Sill - Abrasion - No deduction
2	Side panel - rear left side	Side panel - Abrasion - No deduction
3	Front bumper	Front bumper - Abrasion - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Service book
Documents - Log book
Equipment - Tirefit compressor

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 9 Sept 2026	4.797,23 €

Repainting

No.	Repainting
1	Door - rear right side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - rear right side	185 µm	Door - front right side	176 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.




Figure 27: Misc.



Damage 1: Screen cleaning: Wiper arm - rear (Abdeckung) - Missing - Replace



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 3: Wing mirror - left side: Cap - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace




Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace




Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 5: Wheel / tyres: Tyre - front right side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - front left side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - front left side - Porous / cracked - Replace



Damage 6: Wheel / tyres: Tyre - front left side - Porous / cracked - Replace




Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 8: Wheel / tyres: Alloy rim - front left side - Scratch(es) - Replace



Damage 9: Rear bumper: Spoiler - Scratch(es) - Paint



Damage 9: Rear bumper: Spoiler - Scratch(es) - Paint



Damage 9: Rear bumper: Spoiler - Scratch(es) - Paint



Damage 9: Rear bumper: Spoiler - Scratch(es) - Paint



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 10: Interior: Interior - Scratch(es) - Loss in value



Damage 11: Mudguard - right side: Mudguard - right side (Farbflecken) - Paint defect - Paint



Damage 11: Mudguard - right side: Mudguard - right side (Farbflecken) - Paint defect - Paint



Damage 11: Mudguard - right side: Mudguard - right side (Farbflecken) - Paint defect - Paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 12: Side panel - rear right side: Side panel - Dent / paintcoat damage - Repair and paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 13: Door - rear left side: Door - Scratch(es) - Paint



Damage 14: Boot lid / rear door: Boot lid - Scratch(es) - Paint



Damage 14: Boot lid / rear door: Boot lid - Scratch(es) - Paint




Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 15: Roof: Roof - Scratch(es) - Paint



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation




Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Damage 16: Body: Body - Damage by hail - repair according to calculation



Missing part 2: Documents: Log book - Missing - Replace



Repainting 1: Door - rear right side, Door - front right side

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum



Repainting 1: Door - rear right side, Door - front right side