TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48451373
Order No. / Reference: 27178369
Inspection date: 2 Nov 2026

Manufacturer: Mercedes-Benz	Model: E 300 e T 9G-TRONIC AMG Line
VIN: W1KZH5DB6PB114436	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 300 e T 9G-TRONIC AMG Line	
Vehicle Identification number	W1KZH5DB6PB114436
Mileage (Read)	113,195 km
First registration	28 Oct 2022
Number of holders	1
Next periodical technical inspection	11/2027
(Report on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,991 ccm / 4
Power	155 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	SCHWARZ
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	8 Tag(e)
Last service on / at	11/2025 at 91,911 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM967144
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ATK 00109		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,755 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	275/40 R18 103V	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R18 100Y	Summer tyres on Light alloy	Pirelli	7 mm
	245/45 R18 100Y	Summer tyres on Light alloy	Pirelli	7 mm
2)	275/40 R18 103Y	Summer tyres on Light alloy	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- Premium ambient lighting with 64 colors and 3 color zones
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Third brake light
- EASY-PACK cargo cover including EASY-PACK safety net
- Electronic Stability Program (ESP)
- Chassis: Air suspension on the rear axle with level control
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- rear window wiper
- Instrument panel and door sills in ARTICO man-made leather
- THERMATIC automatic climate control
- Charging cable for household socket, 5m, smooth
- Charging system: AC charging system 7.4 kW
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Center console piano black finish
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: AMG Line Exterior
- Package: Seating comfort
- PRE-SAFE system
- Radio: MBUX multimedia system
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Windscreen wipers with rain sensor
- Seats: i-Size child seat attachment
- Seats: Front sports seats
- Touchpad
- Electronic immobilizer
- Central locking
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Acoustic environmental protection
- AMG floor mats in black with AMG lettering
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Attention Assist
- Basic services
- On-board computer
- Tachometer
- DYNAMIC SELECT
- EASY-PACK tailgate
- Chassis: AGILITY CONTROL chassis with selective damping system
- Transmission: 9-speed automatic, 9G-TRONIC
- Heated rear window with timer
- Black fabric headliner
- KEYLESS START
- Climate: Pre-conditioning
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Steering wheel: Multifunction sports steering wheel in black Nappa leather
- Mercedes-Benz emergency call system
- Center console with on-the-fly storage compartment
- Navigation: Hard disk navigation
- Package: Storage compartment (for plug-in hybrid)
- Package: Public Charging
- Upholstery: ARTICO leatherette/DINAMICA microfiber
- Radio: Extended MBUX functions
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Remote Services Plus
- Power steering
- Seats: Rear seat backrests foldable, 40/20/40 split
- Power outlet: 12V socket in the cargo area
- High-visibility vest for drivers
- Green, heat-insulating glass all around
- Decorative elements: aluminum with longitudinal brushing, light finish

Extra equipment

- Towbar with ESP trailer stabilization (fully electrically foldable and retractable)
- Package: Driving Assistance Package (Active Distance Assist DISTRONIC incl. Active Speed Limit Assist, Extended Automatic Restart on Highways, Route-Based Speed Adaptation with Traffic Jam Function (only when selecting Parking Packages), Active Steering Assist incl. Active Emergency Stop Assist with SOS Function, Emergency Lane Radio, Active Brake Assist incl. Turning and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist incl. Exit Warning, Pedestrian Warning Radio, PRE-SAFE PLUS)
- Package: Mirrors (both exterior mirrors electrically foldable (button in the driver's door control panel) - automatic lowering of the passenger-side mirror glass to parking position when reverse gear is engaged - interior mirror and driver's side exterior mirror automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area)
- Wheels: Winter complete set of M+S tires, 4-piece set, 45.7 cm (18") alloy wheels in 5-spoke design (black painted and polished, front axle 245/45 R18 on 8 J x 18 ET 43, rear axle 275/40 R18 on 9 J x 18 ET 52.5)
- Wheels: Complete winter wheel sets fitted at the factory
- Sunroof: Panoramic electric sunroof in glass design (with comfort and automatic rain closing, PRE-SAFE closing function, electric sunshade and anti-pinch protection)
- Paint finish: Special solid colors
- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration (Apple CarPlay and Android Auto) - Preparation for Digital Key Handover - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - Fuel Tank with 66 Liter Capacity (916) (60l for Diesel Plug-in Hybrids).)
- Package: Parking package with reversing camera (The parking package with reversing camera makes it easier to find and select parking spaces, as well as to park and exit in parallel and perpendicular parking spaces or garages. The active parking assistant steers the vehicle into parking spaces, including speed control and automatic gear changes.)
- Upholstery: Leather
- Radio accessories: Burmester surround sound system (13 high-performance speakers - 9-channel DSP amplifier with a total output of 590 W - Frontbass technology with woofers integrated into the body shell for powerful bass reproduction - Sound optimization for the front and rear seats - Noise cancellation (VNC) - Sound preset: Surround function to generate a virtual surround sound - Multi-channel format support for true surround sound)
- Seats: Heated seats for driver and front passenger (selectable in three stages - Intelligent and comfortable: The seat heating switches off automatically)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Sill - left side	Sill - Scratch(es) - Smart repair
3	Door - front right side	Door edge - Dent / paintcoat damage - Smart repair
4	Mudguard - left side	Mudguard - left side (Und kratzer) - Stone chips - Paint
5	Mudguard - right side	Mudguard - right side (Steinschläge) - Scratch(es) - Paint
6	Side panel - rear left side	Side panel - Scratch(es) - Paint
7	Bonnet	Bonnet (Mehrere) - Stone chips - Paint
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Front bumper	Front bumper (+ Steinschläge) - Scratched - Paint
10	Door - rear right side	Door - Dent / paintcoat damage - Paint
11	Door - rear left side	Door - Dent / paintcoat damage - Paint

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.




Figure 40: Misc.





Figure 41: Misc.



Figure 42: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 2: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 2: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 3: Door - front right side: Door edge - Dent / paintcoat damage - Smart repair



Damage 3: Door - front right side: Door edge - Dent / paintcoat damage - Smart repair



Damage 3: Door - front right side: Door edge - Dent / paintcoat damage - Smart repair



Damage 3: Door - front right side: Door edge - Dent / paintcoat damage - Smart repair



Damage 3: Door - front right side: Door edge - Dent / paintcoat damage - Smart repair




Damage 3: Door - front right side: Door edge - Dent / paintcoat damage - Smart repair




Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint




Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint



Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint




Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint



Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint




Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint



Damage 4: Mudguard - left side: Mudguard - left side (Und kratzer) - Stone chips - Paint



Damage 5: Mudguard - right side: Mudguard - right side (Steinschläge) - Scratch(es) - Paint



Damage 5: Mudguard - right side: Mudguard - right side (Steinschläge) - Scratch(es) - Paint



Damage 5: Mudguard - right side: Mudguard - right side (Steinschläge) - Scratch(es) - Paint




Damage 5: Mudguard - right side: Mudguard - right side (Steinschläge) - Scratch(es) - Paint




Damage 6: Side panel - rear left side: Side panel - Scratch(es) - Paint




Damage 6: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint




Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 7: Bonnet: Bonnet (Mehrere) - Stone chips - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint




Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint




Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint



Damage 9: Front bumper: Front bumper (+ Steinschläge) - Scratched - Paint




Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint




Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 10: Door - rear right side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint