APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	FORD
Model / version:	PUMA
Vin:	WF02XXERK2PL31380
Plate:	2EAX510
Mileage:	70545
First registration:	10/08/2023
Color:	Desert Islan

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES


















































VIN INFORMATION

Radio	Radio avec lecteur CD	Radio avec lecteur MP3
Système navigation	Ecran tactile	10 Haut-parleurs
Bluetooth	Boîte manuelle	6 rapports
Pommeau de levier de vitesses cuir	Projecteurs antibrouillard	Bouclier avant sport
Bouclier arrière sport	Matière : alliage	Diamètre avant 18
Diamètre arrière 18	Largeur avant 7,0	Largeur arrière 7,0
Diamètre avant 18	Diamètre arrière 18	Hauteur avant 50
Hauteur arrière 50	Indice de vitesse avant W	Indice de vitesse arrière W
Largeur avant 215	Largeur arrière 215	Climatisation automatique
Essence	998 cm3	1.00 litre
92 kw	125 ch	Métallisée vernissée
Rétroviseurs avec éclairage du sol	Siège avant gauche chauffant	Sièges avant chauffants

Siège avant gauche réglable en hauteur	Sièges avant réglable en hauteur	Siège avant gauche à réglage lombaire
Sièges avant à réglage lombaire	Garnitures tissu et cuir	Volant sport
Volant chauffant	Aide au stationnement avant	Aide au stationnement arrière
Assistance au parking	Caméra arrière de recul	Régulateur et limiteur de vitesse
Pare-brise acoustique	Pare-brise chauffant	détecteur de pluie essuie-vitre
Airbag rideaux avant	Airbag rideaux arrière	Assistant maintien de la voie
depuis 05.23 PL	radio digitale	intégration Smartphone
Ford SYNC 3	Mild Hybrid System	éclairage habitacle avec LED
combiné instruments avec moniteur digital 12,3"	phares LED Matrix	série 34 (ST-Line X)
système de chargement sans fil pour Smartphone	998 cc (1,0 L) 92 KW	grille de calandre active
enjoliveurs bas de caisse dans la couleur du véhicule		

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm			Summer		?
Front right	5 mm			Summer		?
Rear left	5 mm			Summer		?
Rear right	5 mm			Summer		?

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Seat cover FL	Teared
2	Boot lid covering R	Missing
5	Door RR	Scratch(es)
6	Door FR	Scratch(es)
7	Outer sill R	Scratch(es)
8	Alloy rim FR polished	Scratch(es)
9	Alloy rim FL polished	Scratch(es)

Total: 7

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
3	Wing FL	Dent(s) and scratch(es)	✓	✗	✗
4	Bodywork	Dent(s) and scratch(es)	✓	✗	✗


Total: 2

DAMAGES DETAILS

1 - Seat cover FL - Teared




2 - Boot lid covering R - Missing



5 - Door RR - Scratch(es)





6 - Door FR - Scratch(es)






7 - Outer sill R - Scratch(es)







8 - Alloy rim FR polished - Scratch(es)





9 - Alloy rim FL polished - Scratch(es)








3 - Wing FL - Dent(s) and scratch(es) - Renta®






4 - Bodywork - Dent(s) and scratch(es) - Renta®











SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

14/10/2026 17:01

