TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48587885
Order No. / Reference: 27112133
Inspection date: 5 Nov 2026

Manufacturer: Volkswagen	Model: Touran 1.5 TSI ACT OPF DSG Comfortline
VIN: WVGZZZ1TZMW037992	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen Touran 1.5 TSI ACT OPF DSG Comfortline	
Vehicle Identification number	WVGZZZ1TZMW037992
Mileage (Read)	107,767 km
First registration	7 Sept 2021
Number of holders	1
Next periodical technical inspection	01/2027
(Report on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	1,498 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Deep Black Perleffekt
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,900 km
Last service on / at	08/2026 at 91,640 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GC371029
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CJB 00184		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,120 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96V	Summer tyres on Light alloy	Bridgestone	4mm / 4mm
2)	205/60 R16 96V	Summer tyres on Light alloy	Bridgestone	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Dunlop	7mm / 7mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Bridgestone	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports on the front
- Storage compartments in the overhead console
- Airbag for driver and front passenger
- Electrically adjustable and heated exterior mirrors
- third brake light
- black roof rails
- Decorative inlays "Piano Black"
- Parking assistance
- Electronic Stability Program (ESP) with counter-steering support
- luggage compartment cover
- Height-adjustable luggage compartment floor
- Transmission: 7-speed DSG
- Rear window heated
- Interior lights with delayed shut-off and dimming function, 2 reading lights front and rear
- Front headrests
- Steering wheel: Leather
- Illuminated makeup mirrors in the sun visors
- Multifunction display "Plus"
- Non-smoking version
- Emergency call service
- Upholstery: Cloth
- Radio accessories: 8 speakers
- Tire pressure monitoring system (passive)
- Wheels: Tire Mobility Set (12-volt compressor and tire sealant)
- Drawers under the front seats
- Seat belts: 3 three-point automatic seat belts in the rear
- Seats: Front passenger seat backrest folds down completely
- Seats: Lumbar support in the front
- Start-stop system
- Bumpers in body color
- Textile floor mats
- Warning tone and light for unfastened seat belts front and rear
- Central locking without safe locking, with remote control and 2 remote folding keys
- Storage compartment with lid on the instrument panel
- Active Cylinder Technology ACT
- Airbag, head airbag system for front and rear passengers
- Exterior mirror housings and door handles in body color
- Headliner in Storm Grey
- Decorative inlays “New Brushed Design”
- Tachometer
- Electronic parking brake including auto-hold function
- Windscreen in heat-insulating glass
- Baggage management package
- Additional luggage compartment lighting
- Speed limiter
- Glove compartment with cooling option
- Rear window wiper with intermittent function
- ISOFIX mounting points on rear seats
- Headrests (3) in the 2nd row of seats
- Black radiator grille with chrome strips on the slats
- Headlight range control
- front center armrest
- Fatigue detection
- Emergency braking assistant "Front Assist"
- Otto particulate filter
- Proactive occupant protection system in conjunction with "Front Assist"
- Wheels: Light alloy (4) "Karlstad" 6.5 J x 16 (tires 205/60 R 16)
- Gearshift knob in leather
- electromechanical power steering
- Seats: 3 individual seats in the 2nd row
- Seats: Folding tables on the backs of the front seats
- Seats: Comfort seats in the front
- Seats: Front seats are height-adjustable
- 12V power outlet on the rear of the center console
- Daytime running light
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Green thermal insulation glazing
- Black trim strips on the side windows

Extra equipment

- Adaptive Cruise Control ACC "stop & go" up to 210 km/h and Emergency Brake Assist "Front Assist" (Adaptive Cruise Control ACC "stop & go", with speed limiter - Emergency Brake Assist "Front Assist" (for Adaptive Cruise Control ACC up to 210 km/h))
- Paint finish: Pearl effect
- LED headlights (LED headlights with daytime running lights - dynamic headlight range control)
- Navigation system "Discover Pro" incl. "Streaming & Internet" (App-Connect incl. App-Connect Wireless for Apple CarPlay - screen diagonal 23.4 cm - touchscreen - FM radio reception - dual tuner with phase diversity - MP3 - USB-C with Apple compatibility - output power 4x20 watts - map with 2D display - traffic sign display - telephone interface - 3-way sound control - voice control - digital radio reception DAB+)
- Package: Mirror package (electrically folding exterior mirrors, auto-dimming on the driver's side, ambient lighting and passenger-side exterior mirror lowering - automatic headlight control with daytime running lights, "Leaving home" function and manual "Coming home" function - automatically dimming interior mirror - rain sensor)
- "Comfort" telephone interface with inductive charging function (hands-free system)
- Reversible luggage compartment mat, foldable and removable
- Tailgate with electric opening and closing
- Air conditioning "Air Care Climatronic" (with active combination filter, rear controls and 3-zone temperature control)
- Steering wheel: Multifunction steering wheel in leather, with paddle shifters (with control options for multifunction display, radio and telephone)
- Fog lights and cornering lights
- Package: Business Premium (Air Care Climatronic, combination filter - ACC stop & go, speed limiter, Front Assist - lumbar support front, driver's side electrically adjustable with massage function - multifunction leather steering wheel, paddle shifters - cargo net partition - heated windshield washer nozzles - headlight cleaning system - drawer under right front seat - microfleece seat center panels - heated top comfort seats front - emergency braking assistant "Front Assist" - height-adjustable front seats, ergoActive seat on the driver's seat - washer fluid warning light.)
- Rear View reversing camera (displays the rear of the vehicle in real time on the radio/navigation system display)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - front left side	Door edge - Scratch(es) - Smart repair
3	Wing mirror - right side	Cap - Scratch(es) - Smart repair
4	Door - front left side	Door - dent(s) - Smooth repair work
5	Side panel - rear right side	Sill - Scratch(es) - Smart repair
6	Roof	Roof rail - right side - Scratch(es) - Loss in value
7	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
8	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
9	Wheel / tyres	Alloy rim - rear right side - Scratched - Loss in value
10	Rear bumper	Rear bumper - Scratched - Paint
11	Door - rear left side	Door - Dent / paintcoat damage - Repair and paint
12	Front bumper	Front bumper - Scratched - Repair and paint
13	Roof	Roof - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Door - front right side	Door edge - Scratch(es) - No deduction
3	Trim / covers	Boot lid - interior trim (Innenverkleidung) - Scratch(es) - No deduction
4	Sill - left side	Sill - Scratch(es) - No deduction
5	2nd wheel set	1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction
6	2nd wheel set	1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction
7	2nd wheel set	1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 27 Feb 2024	578,76 €

Repainting

No.	Repainting
1	Side panel - rear right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear right side	176 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Der beiliegende Winterradsatz ist kein Bestandteil des
Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel




Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.




Figure 38: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 3: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 4: Door - front left side: Door - dent(s) - Smooth repair work




Damage 4: Door - front left side: Door - dent(s) - Smooth repair work




Damage 4: Door - front left side: Door - dent(s) - Smooth repair work



Damage 5: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 5: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 5: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 6: Roof: Roof rail - right side - Scratch(es) - Loss in value




Damage 6: Roof: Roof rail - right side - Scratch(es) - Loss in value



Damage 6: Roof: Roof rail - right side - Scratch(es) - Loss in value




Damage 7: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 7: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 7: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 7: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work




Damage 7: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Side panel - Scratch(es) - Smart repair



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value



Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value




Damage 9: Wheel / tyres: Alloy rim - rear right side - Scratched - Loss in value




Damage 10: Rear bumper: Rear bumper - Scratched - Paint




Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint




Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 10: Rear bumper: Rear bumper - Scratched - Paint




Damage 10: Rear bumper: Rear bumper - Scratched - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint




Damage 12: Front bumper: Front bumper - Scratched - Repair and paint




Damage 12: Front bumper: Front bumper - Scratched - Repair and paint




Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 12: Front bumper: Front bumper - Scratched - Repair and paint



Damage 13: Roof: Roof - Scratch(es) - Paint




Damage 13: Roof: Roof - Scratch(es) - Paint



Damage 13: Roof: Roof - Scratch(es) - Paint




Damage 13: Roof: Roof - Scratch(es) - Paint



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 1: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 2: Door - front right side: Door edge - Scratch(es) - No deduction



Wear and tear 2: Door - front right side: Door edge - Scratch(es) - No deduction



Wear and tear 3: Trim / covers: Boot lid - interior trim (Innenverkleidung) - Scratch(es) - No deduction



Wear and tear 3: Trim / covers: Boot lid - interior trim (Innenverkleidung) - Scratch(es) - No deduction



Wear and tear 3: Trim / covers: Boot lid - interior trim (Innenverkleidung) - Scratch(es) - No deduction



Wear and tear 3: Trim / covers: Boot lid - interior trim (Innenverkleidung) - Scratch(es) - No deduction



Wear and tear 4: Sill - left side: Sill - Scratch(es) - No deduction



Wear and tear 4: Sill - left side: Sill - Scratch(es) - No deduction



Wear and tear 5: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction



Wear and tear 5: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction



Wear and tear 5: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction



Wear and tear 6: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction



Wear and tear 6: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction




Wear and tear 7: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction



Wear and tear 7: 2nd wheel set: 1 alloy rim (Nicht Bestandteil der Ausstattung) - Scratched - No deduction



Repainting 1: Side panel - rear right side



Repainting 1: Side panel - rear right side