ARVAL
BNP PARIBAS GROUP

2BHT464

INSPECTION REPORT

End of contract

GENERAL INFO

File	322108
License plate	2BHT464
Vehicle identification number	WVWZZZ3CZNE027345
Dossier	2021018134
Make	Volkswagen Pass.Var.TSI GTE DS
Mileage	98509
First registration	30/11/2021
client availability date	23/09/2026
inspectionDate	05/10/2026










CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	




B
2 - BHT - 464
JELCAR

DAMAGES


Damages	Type	Acceptable
184	Wing Rear Right // Repair & Painting	N
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	N
12	Bumper Front // Smart Repair Large	N
31	Front Bonnet // Smart Repair Small	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
197	Door Rear Right / Trim / Replace	Y
201	Rocker Panel Right // Smart Repair Medium	N
233	Wing Front right // Painting	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures






Wheel Two Tone Front Left // Repair-Chemical reaction


Wing Front right // Painting-scratch





Front Bonnet // Smart Repair Small-dent








Rocker Panel Right // Smart Repair Medium-scratch + dent




Rear Bonnet / Rear Window / Replace-scratch

Door Rear Right / Trim / Replace-scratch





Wheel Two Tone Front Right // Repair-scratch




Wheel Two Tone Rear Left // Repair-scratch




Door Rear Left // Painting-scratch








Wing Rear Left // Painting-scratch





Bumper Front // Smart Repair Large-scratch






Door Front Left // Smart Repair Small-scratch








Rocker Panel Left // Smart Repair Medium-scratch






Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Bumper Rear // Painting-scratch



Rear Bonnet // Polish-scratch



Door Rear Right // Painting-scratch









Door Front Right // Painting-scratch







Wing Rear Right // Repair & Painting-scratch + dent