TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48570841
Order No. / Reference: 27230066
Inspection date: 5 Nov 2026

Manufacturer: Mercedes-Benz	Model: B 180 d 8G-DCT Entry
VIN: W1K4F1AB3RJ613975	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz B 180 d 8G-DCT Entry	
Vehicle Identification number	W1K4F1AB3RJ613975
Mileage (Read)	73,458 km
First registration	23 Jul 2024
Number of holders	1
Next periodical technical inspection	07/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	85 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Mountaingrau Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	71 Tag(e)
Last service on / at	01/2026 at 49,407 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB183286
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AXA 00073		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,075 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91W	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	205/55 R17 91W	Summer tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	5mm / 5mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Hankook	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowering (with this chassis variant the body is lowered by 15 mm)
- Speed Limit Assistant
- Rear lights with taillights and brake lights using LED light guide technology
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Rear headrests (3)
- Cargo area cover
- Steering column mechanically adjustable in height and length
- Mercedes-Benz emergency call system
- Package: Seating comfort
- Package: USB Package Plus
- Upholstery: ARTICO leatherette/Bertrix fabric
- Radio: MBUX multimedia system
- Radio accessories: Central Media Display
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Rear view camera
- Seats: Comfort seats
- Heated seats for driver and front passenger
- Bumpers in body color
- TIREFIT with tire inflation compressor
- Electronic immobilizer
- Decorative elements Star Pattern
- ADAPTIVE BRAKE with hill start assist, HOLD function, pre-filling and drying braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Traction control (ASR)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Brake assist, active
- Third brake light in LED technology
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Velour floor mats
- Transmission: 8G-DCT automatic
- Rear window wiper with intermittent function
- Heated rear window with timer
- ISOFIX child seat attachment with top tether in the rear
- THERMATIC automatic climate control
- Front headrests are height-adjustable
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Navigation: MBUX Navigation Premium (hard drive navigation - high-resolution navigation with satellite view - live traffic information and Car-to-X communication - fast online route calculation - map data updates: via Mercedes me connect with automatic over-the-air update via USB stick at a Mercedes-Benz dealer - navigation services: local search, online search, ads)
- Remote Services
- Seat belts B-Class
- Seats: Rear seat backrests foldable in a 40/20/40 ratio
- Lane Keeping Assist, active
- Cruise control
- Pre-installation for digital key handover
- Central locking with remote control

Extra equipment

- Elimination of type designation
- Package: Winter Package Plus with 40.6 cm (17") winter complete wheels (Winter Package - 43.2 cm (17") light alloy wheels in 5-twin-spoke design, aerodynamically optimized, vanadium silver painted with 215/65 R17 on 6.5J x 17 ET44)
- Paint finish: Metallic (according to sample card)
- Traffic Sign Assistant
- Wheels: 43.2 cm (17") alloy wheels, 4-piece set in 5-twin-spoke design (aerodynamically optimized, painted black and polished with 205/55 R17 tires on 6.5J x 17 ET44 rims)
- Wheels: Complete summer wheel sets fitted at the factory
- Fully digital instrument display (Experience the full range of digital display options. The large, high-resolution 10.25" display can be individually configured – for example, classically with speedometer on the left and tachometer on the right.)
- Package: Advanced (LED High Performance headlights - EASY-PACK tailgate - Mirror package (automatically dimming interior mirror, electrically folding exterior mirrors) - Parking package with reversing camera (Active Parking Assist with PARKTRONIC) - 4-way lumbar support - Adaptive Highbeam Assist)
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Separation net

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction

Wear and tear

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Vehicle glazing	Windscreen - Stone chips - No deduction
5	Door - rear right side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres



Figure 12: Documents



Figure 13: Documents



Figure 14: Additional tyres




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 1: Rear bumper: Rear bumper - Scratch(es) - No deduction



Wear and tear 5: Door - rear right side: Door - Scratch(es) - No deduction



Wear and tear 5: Door - rear right side: Door - Scratch(es) - No deduction



Wear and tear 5: Door - rear right side: Door - Scratch(es) - No deduction