TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48563653
Order No. / Reference: 27218734
Inspection date: 9 Nov 2026

Manufacturer: Opel	Model: Corsa 1.2 Direct Injection Turbo GS
VIN: VXKUPHNE9R4126537	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Corsa 1.2 Direct Injection Turbo GS	
Vehicle Identification number	VXKUPHNE9R4126537
Mileage (Read)	11,835 km
First registration	15 Jul 2024
Number of holders	1
Next periodical technical inspection	07/2027
(Report not on hand)	
Fuel type	Petrol
Engine displacement / Cylinder	1,199 ccm / 3
Power	74 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	TYPE HABILLAGE EXTERIEUR PLATE STANDARD
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	13,500 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB463516
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2525 / AAP 00005		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,620 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Adaptive brake light
- Airbag system
- Electrically adjustable and heated exterior mirrors for driver and passenger side
- On-board computer
- Roof design line, in black
- Decorative strip Silent Black/Liquid Palladium
- Electronic brake force distribution (EBD)
- Driver information display 7", color
- Front collision warning with automatic emergency braking and pedestrian detection
- Back window, heater
- Heating and ventilation system with pollen filter
- Child safety lock in the rear doors, manual
- Air conditioning
- Paintwork: Roof in contrasting black
- LED headlights
- Steering column, height and reach adjustable
- Front reading lights
- Make-up mirror, sun visor for driver and front passenger
- Fatigue detection
- Otto particulate filter
- Parkpilot, rear parking aid
- Radio: Multimedia radio with 10" color touchscreen display
- Wheels: Alloy wheels (8 spokes) in black 6.5 J x 16
- Power steering
- Seats: Passenger seat, 4-way manually adjustable
- Seats: Rear seat backrest split 60:40 and foldable
- Lane Keeping Assist
- 12V power outlet in the center console, front
- Blind spot warning system
- Exterior door handles, in car color
- Traffic sign recognition
- Pre-wiring for child seat mounting system "ISOFIX"
- Heat-insulating glazing, tinted
- Ignition key (2)
- Active Aero Shutter: Radiator grille with actively controlled air intake
- Anti-lock braking system (ABS)
- B-pillars in high-gloss black
- Hill Start Assist
- third brake light
- Headliner, Black
- Tachometer
- Electronic Stability Program Plus (ESP Plus)
- Electric windows front and rear
- Intelligent speed control and limiter
- Transmission: 6-speed manual transmission
- rear window wiper
- Upshift recommendation via display in the driver information display
- Headrests (5)
- LED taillights
- Steering wheel made of vegan synthetic leather, flattened at the bottom
- Headlight range adjustment, manual
- Center armrest with storage compartment in front
- Opel Connect with telematics services
- Package: Corsa Tech Package
- Radio: Digital radio reception DAB+
- Tire pressure warning
- Wheels: Tire repair kit
- Seat belts: Three-point seat belts in all seats
- Seats: Driver's seat, 6-way manually adjustable
- Seats: Front sports seats
- Start/Stop System
- Sporty-looking bumpers, front and rear
- Traction Control (TC) Plus
- Ambient lighting
- Pre-installation for ISOFIX child seat mounting system
- Immobiliser
- Central locking with remote control

Extra equipment

- Automatic climate control (recirculation mode, manual - automatic air distribution - sun position sensor - activated carbon filter - rear footwell heating)
- Upholstery: Alcantara trim, black (seat contact surfaces and inner side bolsters in Alcantara - headrests, door panels and outer side bolsters in premium leather look - comfort driver's seat with massage function, 6-way manually adjustable (length, height, backrest angle) - electro-pneumatic lumbar support (length, height) - comfort passenger seat, 6-way manually adjustable (length, height, backrest angle) - pocket on front seat back - multi-stage seat heating for driver and passenger, and steering wheel heating)
- Paint finish: Solid
- LED fog lights
- Package: Infotainment package (Navigation system - Park & Go digital (Park Pilot - front and rear parking aid, 180-degree panoramic reversing camera with rear view and top view) - Keyless locking and starting system - LED ambient lighting - Wireless charging - Electric parking brake - Single-zone automatic climate control - Solar Protect heat-insulating glass, heavily tinted, in the rear)
- Wheels: Alloy wheels (8 spokes) in black 6.5 J x 16 (all-weather tires - 195/55 R16)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Smart repair
2	Sill - left side	Sill - Dent / paintcoat damage - Smart repair
3	Door - front right side	Door edge - Scratch(es) - Smart repair
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents




Figure 15: Documents




Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.




Figure 21: Misc.



Figure 22: Misc.




Figure 23: Misc.





Figure 24: Misc.



Figure 25: Misc.




Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair



Damage 2: Sill - left side: Sill - Dent / paintcoat damage - Smart repair




Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 3: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value