TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48571835
Order No. / Reference: 27234397
Inspection date: 9 Nov 2026

Manufacturer: Ford	Model: Focus Turnier 1.0 EcoBoost Hybrid Aut. ST-LINE X
VIN: WF0PXXGCHPSK53515	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Focus Turnier 1.0 EcoBoost Hybrid Aut. ST-LINE X	
Vehicle Identification number	WF0PXXGCHPSK53515
Mileage (Read)	21,195 km
First registration	10 Nov 2025
Number of holders	1
Next periodical technical inspection	11/2028
(Report not on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	999 ccm / 3
Power	114 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Agate Black Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	31 %
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HN238010
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BUE 00177		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,005 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/40 R18 95Y	All-season tyres on Light alloy	Hankook	5mm / 5mm
2)	235/40 R18 95Y	All-season tyres on Light alloy	Hankook	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2029		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Passenger airbag deactivation
- Anti-lock braking system (ABS) with electronic brake force distribution (EBD)
- Hill start assist
- Roof rails, black
- Digital instrument panel 12.3" (31.2 cm screen diagonal)
- Tachometer
- Electronic Shifter
- Lane keeping assist including lane keeping assist
- Electric windows front and rear
- Ford Easy Fuel
- FordKeyFree system including Ford Power start function
- luggage compartment cover
- Cruise control
- Rubber mats
- Illuminated glove compartment
- rear window wiper
- Interior mirror, automatically dimming
- Isofix mount
- Knee pads on the center console
- LED taillights
- ST-Line design steering wheel
- Make-up mirrors in driver and passenger sun visors
- Center console "Premium" front
- Fatigue warning
- Emergency call assistant
- Otto particulate filter
- Upholstery: Cloth
- Pre-Collision Assist
- Tire Pressure Monitoring System (TMPS)
- Windscreen wipers with rain sensor (sensitivity adjustable)
- Side windows from the 2nd row of seats and rear window, dark tinted.
- Seats: Passenger seat, 2-way adjustable
- Seats: Rear seat backrest
- Sport body kit
- 12-volt socket
- Carpet floor mats front and rear, velour
- Black trim around the side windows
- Lashing eyes in the luggage compartment
- Electronic immobilizer
- Central locking with remote control and remote luggage compartment release
- Ambient lighting, front
- Exterior mirrors painted in body color, electrically adjustable, heated and foldable
- Black woven fabric headliner
- Roof spoiler painted in car color
- Dual exhaust system
- Third brake light
- Electronic Safety and Stability Program (ESP)
- Chassis: Sport-tuned
- Electric parking brake with auto-hold function
- Ford ECO-Coach
- FordPass Connect including live traffic information
- Speed limiter
- Transmission: 7-speed PowerShift automatic transmission
- Back window, heater
- Interior lighting with LED technology
- Intelligent security system
- Air conditioning with automatic temperature control
- Headrests: 2 front and 3 rear, height adjustable
- LED headlights
- Adjustable steering column
- Armrest - centre, rear
- MyKey key system (individually programmable second key)
- Navigation: Ford SYNC 4 including Ford navigation system with AppLink, 13.2" touchscreen and DAB/DAB+
- Front and rear parking pilot system
- Post-Collision Assist
- Tire repair kit
- Rear view camera
- Headlight assistant with day/night sensor
- Selective driving mode switch
- Electromechanical speed-dependent power steering
- Seats: Driver's seat height adjustable
- Seats: Front sports seats with enhanced lateral support
- Start-stop system
- Phone accessories: Inductive charging station for mobile devices
- 2 USB ports in the center console, rear
- Warning system for unfastened seat belts for the 1st and 2nd rows of seats

Extra equipment

- Towbar preparation kit (including trailer stabilization function)
- Tires: 8 J x 18 light alloy wheels (4) with 235/40 R 18 (in 5x3-spoke Y-design, in pearl grey premium paint finish, diamond-turned)
- Package: Easy Parking (Active Parking Assist with parking and exiting function (in conjunction with 8-speed automatic transmission including semi-automated vehicle guidance) - Door edge protection - Rearview camera with "Split View" technology)
- Package: ST-Line styling package (red painted brake calipers - large roof spoiler painted in body color - pedals with aluminum covers - front door sill trims, ST-Line design)
- Package: Winter (heated windscreen - heated steering wheel - individually and variably heated front seats)
- Radio: B&O Sound System (675 Watt premium sound system with 10 speakers, including subwoofer - based on the renowned sound and design expertise of Bang & Olufsen)
- Mounting points behind the 1st row of seats (according to ISO 27955, required for the installation of the safety partition available as an accessory from your Ford partner)
- eCall
- Paint finish: Metallic
- Package: Driver Assistance Package (for automatic transmission) (Drive Assist, Intelligent Adaptive Cruise Control, Lane Keeping Assist, Traffic Jam Assist with Stop&Go function, Traffic Sign Recognition System, Wrong-Way Driver Warning, Evasive Steering Assist, Distance Display and Distance Warning, High Beam Assist (in conjunction with adaptive LED matrix headlights with glare-free high beam assist), Blind Spot Assist with Cross Traffic Alert including emergency braking function (when reversing out of parking spaces) and trailer detection, Rearview camera with split view)
- Cigarette lighter and ashtray

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyre - front left side - Broken / torn - Replace
2	Wheel / tyres	Tyre - front right side - Broken / torn - Replace
3	Side panel - rear left side	Elbow - Scratch(es) - Smart repair
4	Front axle	Axles / undercarriage (wegen der beschädigten Felgen) - Specify findings - Measure
5	Wheel / tyres	Alloy rim - front left side (Materialabtrag) - Scratched - Replace
6	Wheel / tyres	Alloy rim - front right side - Scratched - Replace

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents




Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Damage 1: Wheel / tyres: Tyre - front left side - Broken / torn - Replace




Damage 1: Wheel / tyres: Tyre - front left side - Broken / torn - Replace




Damage 2: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 2: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 2: Wheel / tyres: Tyre - front right side - Broken / torn - Replace



Damage 3: Side panel - rear left side: Elbow - Scratch(es) - Smart repair



Damage 3: Side panel - rear left side: Elbow - Scratch(es) - Smart repair




Damage 5: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 5: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 5: Wheel / tyres: Alloy rim - front left side (Materialabtrag) - Scratched - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 6: Wheel / tyres: Alloy rim - front right side - Scratched - Replace