TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48467702
Order No. / Reference: 26945745
Inspection date: 2 Nov 2026

Manufacturer: Skoda	Model: Octavia Combi 2.0 TDI DSG Style
VIN: TMBJJ8NX5PY022366	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Octavia Combi 2.0 TDI DSG Style	
Vehicle Identification number	TMBJJ8NX5PY022366
Mileage (Read)	73,073 km
First registration	10 Oct 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	10/2027
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Blau Race Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Not roadworthy / moveable

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	13,400 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GN414451
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	8004 / AWL 00201		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,990 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91V	Summer tyres on Light alloy	Michelin	5mm / 5mm
2)	205/55 R17 91V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/60 R16 96H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/60 R16 96H	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in the luggage compartment with cargo element
- Airbag, driver's knee airbag
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Center section of the dashboard with fabric covering
- Electrically adjustable and heated exterior mirrors
- Electrically folding exterior mirrors
- Hill start assist including auto-hold function
- Hydraulic brake assist (HBA)
- Grey headliner
- Decorative strip in silver finish with ambient lighting
- Digital instrument cluster (Virtual Cockpit) 10.2"
- Third brake light
- Electronic transverse differential lock (XDS+)
- Driving light assistant
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Cruise control system
- Tinted windows
- Heated rear window
- Rear window wiper including windshield washer system
- ISOFIX preparations on the front passenger seat and the outer rear seats including top tether anchorage
- Climatronic air conditioning (2-zone)
- Headrests (5) front and rear height adjustable
- LED taillights in crystal glass look and animated turn signals
- Remote release of the rear seat backrests in the trunk
- Steering wheel: Leather steering wheel with multifunction buttons and paddle shifters.
- Front center armrest, including storage compartment
- Front and rear parking sensors
- Radio: Bolero music system with capacitive 10" color display
- Radio accessories: Bluetooth hands-free system
- Radio accessories: SmartLink
- Rain sensor
- Tire mobility kit
- Electromechanical power steering
- Safety lights in the front side doors
- Seats: Electrically adjustable front seats with memory function
- SKODA Care Connect
- Lane keeping assistant (Lane Assist)
- 12V socket in the trunk
- Phone: Wireless SmartLink for Apple CarPlay
- Lashing eyes in the trunk
- Central locking including remote control integrated into the key and EASY Start
- Storage compartments
- Airbag, driver and passenger
- Airbag, head airbags
- Ambient lighting
- Traction control (ASR)
- Automatically dimming exterior mirror (driver's side)
- Exterior mirrors with memory function
- Heated windshield washer nozzles including 5l washer fluid reservoir
- Glasses compartment in the headliner
- Roof rails, anodized
- Diesel particulate filter
- Tachometer
- Electronic parking brake
- Electronic Stability Control (ESC)
- Driving profile selection
- Front radar assistant including city emergency braking function and pedestrian and cyclist detection
- Transmission: 7-speed dual-clutch transmission (DSG)
- Green tec: Start/stop system including brake energy recuperation
- Interior mirror automatically dimming
- Kessy, keyless entry and start-stop system
- Child safety lock for the rear doors and windows
- Removable boot cover
- LED fog lights
- LED license plate lights
- LED headlights with LED daytime running lights
- Steering wheel: height and reach adjustable
- Manual headlight range adjustment
- Rear center armrest with pass-through option
- Engine drag torque control (MSR)
- Upholstery: Cloth
- Radio accessories: 2 USB-C ports on the front
- Radio accessories: 8 speakers
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Voice control
- Tire pressure monitoring
- Wheels: 17" Rotare AERO alloy wheels
- Seat belts
- Seats: Heated front seats
- Seats: Height-adjustable driver and passenger seats
- Seats: Rear seat backrest split 60:40, foldable
- Speed limiter
- Lane change and parking assist as well as exit warning
- Telephone: Phonebox with inductive charging function (connection via external antenna)
- Immobiliser

Extra equipment

- Trailer hitch preparation including trailer stabilization
- Faux leather upholstery on the backs of the front seats
- Paint finish: Metallic
- Package: Comfort Plus (Combi) (3-zone Climatronic - Sunset (dark tinted rear window and rear side windows) - acoustic glazing in the front side windows - heated front and outer rear seats - heated steering wheel - 230 V socket and 3 x USB charging ports - sunshades in the rear doors - multi-function storage compartment in the boot - sleeping headrests in the rear - semi-automatic luggage compartment cover)
- Panoramic sunroof, electric (deletion of the glasses compartment in the headliner)
- Heated windscreen
- Anti-theft alarm system including safe system with interior monitoring and tilt sensor
- Package: Infotainment Columbus Plus (Columbus navigation system - Infotainment Online (3-year term) - Head-Up Display)
- Package: Parking & Lighting (for Sportline, Style) (cornering lights in the fog lights - headlight cleaning system - matrix headlights - reversing camera - parking assist)
- Package: Travel Plus (DSG) (Traveller assistance system: - Traffic sign recognition - Predictive and adaptive cruise control (pACC) - Adaptive lane keeping assist - Emergency and traffic jam assist (with DSG) - Capacitive steering wheel with hands-off detection - Adaptive cruise control (ACC) (control range 210 km/h) - Driver fatigue detection - Driving profile selection - Adaptive chassis control (DCC) - Automatically dimming exterior mirror (driver's side))

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Mudguard - right side	Mudguard - right side - Scratch(es) - Cover / polish
3	Side panel - rear right side	Side panel - Scratch(es) - Cover / polish
4	Seat - rear	Back seat - Soiled - Clean
5	Wheel / tyres	Tyre - rear right side (205 55 17 s) - Worn - Replace
6	Bonnet	Bonnet - dent(s) - Smooth repair work
7	Door - front right side	Door handle - outside - Scratch(es) - Smart repair
8	Side panel - rear right side	Sill - Scratch(es) - Smart repair
9	Side panel - rear right side	Side panel - Scratch(es) - Smart repair
10	Door - front left side	Door - Dent / paintcoat damage - Repair and paint
11	Door - rear left side	Door - Scratch(es) - Paint
12	Door - rear right side	Door - Dent / paintcoat damage - Repair and paint
13	Door - front right side	Door - Dent / paintcoat damage - Repair and paint
14	Rear bumper	Rear bumper - Scratch(es) - Paint
15	Mudguard - left side	Mudguard - left side - Dent / paintcoat damage - Repair and paint
16	Front bumper	Front bumper - Dent / paintcoat damage - Repair and paint
17	Side panel - rear left side	Side panel - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear left side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 20 Dec 2022	1.477,42 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Documents



Figure 16: Documents



Figure 17: Additional tyres



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.




Figure 29: Misc.




Figure 30: Misc.



Figure 31: Misc.




Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.




Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Mudguard - right side: Mudguard - right side - Scratch(es) - Cover / polish




Damage 2: Mudguard - right side: Mudguard - right side - Scratch(es) - Cover / polish




Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Damage 3: Side panel - rear right side: Side panel - Scratch(es) - Cover / polish



Damage 4: Seat - rear: Back seat - Soiled - Clean



Damage 4: Seat - rear: Back seat - Soiled - Clean




Damage 4: Seat - rear: Back seat - Soiled - Clean



Damage 5: Wheel / tyres: Tyre - rear right side (205 55 17 s) - Worn - Replace



Damage 5: Wheel / tyres: Tyre - rear right side (205 55 17 s) - Worn - Replace




Damage 6: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 6: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 6: Bonnet: Bonnet - dent(s) - Smooth repair work



Damage 7: Door - front right side: Door handle - outside - Scratch(es) - Smart repair




Damage 7: Door - front right side: Door handle - outside - Scratch(es) - Smart repair




Damage 8: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 8: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Sill - Scratch(es) - Smart repair




Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 9: Side panel - rear right side: Side panel - Scratch(es) - Smart repair




Damage 10: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - front left side: Door - Dent / paintcoat damage - Repair and paint



Damage 10: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 10: Door - front left side: Door - Dent / paintcoat damage - Repair and paint




Damage 11: Door - rear left side: Door - Scratch(es) - Paint




Damage 11: Door - rear left side: Door - Scratch(es) - Paint




Damage 11: Door - rear left side: Door - Scratch(es) - Paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint



Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 12: Door - rear right side: Door - Dent / paintcoat damage - Repair and paint




Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint




Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 13: Door - front right side: Door - Dent / paintcoat damage - Repair and paint



Damage 14: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 14: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 14: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 14: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 14: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 14: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 15: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint




Damage 15: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint




Damage 15: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage 15: Mudguard - left side: Mudguard - left side - Dent / paintcoat damage - Repair and paint



Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint




Damage 16: Front bumper: Front bumper - Dent / paintcoat damage - Repair and paint



Damage 17: Side panel - rear left side: Side panel - Scratch(es) - Paint




Damage 17: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 17: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 17: Side panel - rear left side: Side panel - Scratch(es) - Paint



Damage 17: Side panel - rear left side: Side panel - Scratch(es) - Paint



Wear and tear 1: Side panel - rear left side: Sill - Scratch(es) - No deduction