TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

# Expertise

Protocol number: 48567308
Order No. / Reference: 27286968
Inspection date: 9 Nov 2026

| Manufacturer: Ford | Model: Transit Custom 300 L2H1 LKW VA Trend |
|---|---|
| VIN: WF0YXXTTGYKM34928 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Ford Transit Custom 300 L2H1 LKW VA Trend | |
| **Vehicle Identification number** | WF0YXXTTGYKM34928 |
| **Mileage** (Read) | 48,462 km |
| **First registration** | 13 May 2020 |
| **Number of holders** | 1 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,995 ccm / 4 |
| **Power** | 79 kW |
| **Gearbox / Number of gears** | Manual / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Van |
| **Colour / colour code** | Polar-Silber Metallic |
| **Doors / Seats** | 4 / 3 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black |

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | Available / complete | **Next maintenance in** | 35,000 km |
| **Last service on / at** | 05/2026 at 45,811 km | | |
| **Key is / should be** | 2 / 4 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | FR767805 |
| **Previous damage / Accident** | Detectable | **Repainting** | Detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8566 / BSF 00187 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 3,000 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R16 109T | Winter tyres on Steel rim with wheel cover | Falken | 6 mm |
| | 215/65 R15 104T | Summer tyres on Steel rim with wheel cover | Continental | 6 mm |
| 2) | 215/65 R15 104T | Summer tyres on Steel rim with wheel cover | Continental | 6mm / 6mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R16 109T | Winter tyres on Steel | Falken | 6 mm |
| | 215/65 R15 104T | Winter tyres on Steel | Continental | 6 mm |
| 2) | 215/65 R16 109R | Winter tyres on Steel | Continental | 6mm / 6mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| E | 215/65 R15 104T | Summer tyres on Steel | Continental | 7 mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Double-leaf rear door with 180° opening angle (without window)
- Front electric windows
- Ford Easy Fuel
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Cargo area lighting with activatable switch-off delay
- Steering column, adjustable in height and reach
- Package: Style-Color Package
- Particulate filter: diesel particulate filter
- Wheels/Tires: Spare wheel, steel wheel
- Headlights: Halogen projector headlights
- Sliding door: Sliding door, right
- Mud flaps front and rear
- Low side paneling
- Seat belts
- Power outlet: 12-volt connection
- Lashing eyes 8
- Heat-insulating glazing, lightly tinted
- Auxiliary heater, electric
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Headliner in driver's cab
- Tachometer
- Electronic Stability Program (ESP) with Traction Control System (TCS)
- FordPass Connect
- Generator, 240 A
- Cruise control including leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Cargo area floor: Vinyl floor covering, sealed, "Easy Clean"
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Wheel trims
- Wheels: Steel wheels 6.5 J x 15 with 215/65 R 15 tires
- Sliding door entry light automatically illuminates when the door is opened
- Side protection strips
- Power steering
- Start-stop system
- Front bumper in body color
- Immobiliser
- Central locking with remote control
- Second key with remote control

### Extra equipment

- 3rd and 4th keys
- Radio: Audio System 24: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation system. (Radio (FM/AM) 8" touchscreen multifunction display (20.32 cm), 4 speakers, FordPass Connect Wi-Fi hotspot, integrated control panel and audio remote control on the steering wheel, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, Android Auto and Apple CarPlay support, capacitive touchscreen technology,...), dynamic navigation, lane guidance, road map for Western Europe)
- Paint finish: Metallic
- Seats: Seat Package 15 - Partition (load-through hatch), without window (Custom Truck Trend) (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (fold-out) - Heated driver's seat - Heated passenger seat (outer seat) - Inner armrest for driver - Manual lumbar support (driver's seat) - TREND seat cover: fabric - Partition without window with load-through hatch)
- Parking heater, programmable, with remote control

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Bonnet | Bonnet - Stone chips - Smart repair |
| 2 | Wing mirror - right side | Cap - Scratch(es) - Smart repair |
| 3 | Boot lid / rear door | Rear door - left side - dent(s) - Smooth repair work |
| 4 | Wheel / tyres | Tyre - front left side (Winter 16" statt Sommer 15" / Mischprofil auf Antriebsachse) - Differs from the original configuration - Replace |

## Missing parts

| Description |
|---|
| Equipment - Vehicle key (2x) |

## Previous damages

| No. | Previous damage | Extent of damage (Net) |
|---|---|---|
| 1 | Side - left, Side right, Professionally repaired, Invoice of repair done Non-existent | |

## Repainting

| No. | Repainting |
|---|---|
| 1 | Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side, Professionally carried out, Invoice of repair done Non-existent |

## Paint coat thickness measurement

| | | | |
|---|---|---|---|
| Mudguard - right side | 262 µm | Side panel - rear right side | 195 µm |
| Door - rear right side | 255 µm | Door - front left side | 180 µm |
| Door - front right side | 222 µm | | |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

Professionally repaired previous damages were found at the vehicle.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel

**Figure 9:** Interior 360° view (Online Link)




**Figure 10:** Cargo area




**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents





**Figure 15:** Documents





**Figure 16:** Documents



**Figure 17:** Additional tyres



**Figure 18:** Additional tyres




**Figure 19:** Navigation



**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.



**Figure 23:** Misc.



**Figure 24:** Misc.




**Figure 25:** Misc.




**Figure 26:** Misc.



**Figure 27:** Misc.



**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.




**Figure 31:** Misc.




**Figure 32:** Misc.



**Figure 33:** Misc.





**Figure 34:** Misc.




**Figure 35:** Misc.



**Damage 1:** Bonnet: Bonnet - Stone chips - Smart repair



**Damage 1:** Bonnet: Bonnet - Stone chips - Smart repair



**Damage 2:** Wing mirror - right side: Cap - Scratch(es) - Smart repair




**Damage 3:** Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



**Damage 3:** Boot lid / rear door: Rear door - left side - dent(s) - Smooth repair work



**Damage 4:** Wheel / tyres: Tyre - front left side (Winter 16" statt Sommer 15" / Mischprofil auf Antriebsachse) - Differs from the original configuration - Replace




**Missing part 1:** Equipment: Vehicle key (2x) - Missing - Replace




**Repainting 1:** Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side




**Repainting 1:** Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side




**Repainting 1:** Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side




**Repainting 1:** Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side




**Repainting 1:** Mudguard - right side, Side panel - rear right side, Door - rear right side, Door - front left side, Door - front right side