TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48439674
Order No. / Reference: 27217260
Inspection date: 28 Oct 2026

Manufacturer: Ford	Model: Transit 350 L4 VA Trend Kofferaufbau mit Ladebordwand
VIN: WF0AXXTTRAMD38626	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L4 VA Trend Kofferaufbau mit Ladebordwand	
Vehicle Identification number	WF0AXXTTRAMD38626
Mileage (Read)	177,323 km
First registration	4 Apr 2022
Number of holders	1
Next periodical technical inspection (Report not on hand)	07/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frost-Weiß
Doors / Seats	2 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	0 Tag(e)
Last service on / at	01/2026 at 154,228 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GL232452
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	8566 / 000 000		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 121R	All-season tyres on Steel rim with wheel cover	Continental	7mm / 7mm
2)	235/65 R16 115S	Winter tyres on Steel rim with wheel cover	Goodyear	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2025		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Headliner in driver's cab
- Tachometer
- Front electric windows
- Ford Easy Fuel
- Cruise control including leather steering wheel
- Lockable glove compartment with lid
- Front air conditioning
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Fog light
- Flatbed: Standard flatbed (wide)
- Wheels: Tire repair kit
- Headlights with delayed shut-off
- Seat belts
- Start-stop system
- recirculation mode
- Heat-insulating glazing, lightly tinted
- Second key, foldable, with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Roof, overhead storage compartment at the front
- Roof marker lights
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Generator, high-performance version
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Fuel tank 70 l
- leather steering wheel
- MyKey key system
- Particulate filter: diesel particulate filter
- Radio: Audio system 13
- Headlights with static cornering lights
- Power steering
- Seats: Seat package 13
- Daytime running light
- Immobiliser
- Central locking with remote control

Extra equipment

- Airbag (passenger side)
- Exterior mirror, long arm (with integrated turn signals)
- Battery: AGM deep-cycle high-performance battery (2 batteries (95 Ah), deep dischargeable, incl. isolating relay - standard battery is replaced by AGM)
- Tire Pressure Monitoring System (TPMS)
- Wheels: Steel wheels 6.5 J x 16, winter tires, suitable for all seasons (replace standard tires) (with 235/65 R 16 tires)
- Dülmer construction
- Battery: Extended battery life, battery life can be programmed to 30 minutes
- Application of decals including installation
- Package: Visibility Package I (electrically adjustable and heated exterior mirrors - heated windshield - washer fluid sensor)
- Telematics Moove incl. installation
- TÜV approval of the Dülmer body

Retrofitted equipment

- Rear parking sensors
- Reversing camera, side cameras
- Front camera

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Additional lamp	Additional lamp (Dach links) - Non-operational - Replace
2	Additional lamp	Additional lamp (Begrenzungsleuchte hinten rechts) - Broken / torn - Replace
3	Equipment	Tirefit filler - Expired - Replace
4	Electronic systems	Rear view camera (Display) - Loose - Un- / install
5	Wing mirror - left side	Chassis (Materialabtrag) - Scratched - Loss in value
6	Boot lid / rear door	Seal (Links/rechts) - Broken / torn - Replace
7	Misc.	Inspection / maintenance - Due - Perform
8	Front bumper	Front bumper (unpainted) - Scratched - Replace
9	Boot lid / rear door	Boot lid (Oberteil) - Broken / torn - Repair and paint
10	Body	Body - Glued / labelled - De-glue / neutralise
11	Door - rear right side	Door - Deformed - Repair and paint
12	Drive train	Sleeve prop shaft - front right side (Fett tritt aus) - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Documents	Service book - Missing - No deduction
2	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Kofferaufbau mit Ladebordwand Firma Dülmer.

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Navigation



Figure 15: Misc.



Figure 16: Misc.




Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Damage 1: Additional lamp: Additional lamp (Dach links) - Non-operational - Replace



Damage 1: Additional lamp: Additional lamp (Dach links) - Non-operational - Replace




Damage 1: Additional lamp: Additional lamp (Dach links) - Non-operational - Replace



Damage 2: Additional lamp: Additional lamp (Begrenzungsleuchte hinten rechts) - Broken / torn - Replace



Damage 2: Additional lamp: Additional lamp (Begrenzungsleuchte hinten rechts) - Broken / torn - Replace




Damage 3: Equipment: Tirefit filler - Expired - Replace



Damage 4: Electronic systems: Rear view camera (Display) - Loose - Un- / install




Damage 4: Electronic systems: Rear view camera (Display) - Loose - Un- / install



Damage 5: Wing mirror - left side: Chassis (Materialabtrag) - Scratched - Loss in value



Damage 5: Wing mirror - left side: Chassis (Materialabtrag) - Scratched - Loss in value



Damage 5: Wing mirror - left side: Chassis (Materialabtrag) - Scratched - Loss in value




Damage 6: Boot lid / rear door: Seal (Links/rechts) - Broken / torn - Replace



Damage 6: Boot lid / rear door: Seal (Links/rechts) - Broken / torn - Replace



Damage 6: Boot lid / rear door: Seal (Links/rechts) - Broken / torn - Replace




Damage 6: Boot lid / rear door: Seal (Links/rechts) - Broken / torn - Replace



Damage 7: Misc.: Inspection / maintenance - Due - Perform



Damage 7: Misc.: Inspection / maintenance - Due - Perform



Damage 8: Front bumper: Front bumper (unpainted) - Scratched - Replace



Damage 8: Front bumper: Front bumper (unpainted) - Scratched - Replace



Damage 8: Front bumper: Front bumper (unpainted) - Scratched - Replace



Damage 8: Front bumper: Front bumper (unpainted) - Scratched - Replace



Damage 8: Front bumper: Front bumper (unpainted) - Scratched - Replace




Damage 9: Boot lid / rear door: Boot lid (Oberteil) - Broken / torn - Repair and paint




Damage 9: Boot lid / rear door: Boot lid (Oberteil) - Broken / torn - Repair and paint



Damage 11: Door - rear right side: Door - Deformed - Repair and paint



Damage 11: Door - rear right side: Door - Deformed - Repair and paint



Damage 11: Door - rear right side: Door - Deformed - Repair and paint



Damage 12: Drive train: Sleeve prop shaft - front right side (Fett tritt aus) - Broken / torn - Replace



Damage 12: Drive train: Sleeve prop shaft - front right side (Fett tritt aus) - Broken / torn - Replace



Damage 12: Drive train: Sleeve prop shaft - front right side (Fett tritt aus) - Broken / torn - Replace