AUDI Q4 SPORTBACK E-TRON

Vehicle information








Make:	**AUDI**	License:	**2CMF397**
Gearbox:		Body color:	
Model:	**Q4 SPORTBACK E-TRON**	VIN:	**WAUZZZFZ8NP055881**
Fuel type:		Power:	**125 kW**
Version:	**BEV 55KWH 35 ADVANCED AUTO**	First registration	**14/09/2022**
Mileage:	**129773 km**	N° of doors:	


Damage summary

Front	1
Interior	3
Left	1
Rear	1
Right	3
Roof & others	1


Commercial pictures














VIN equipment according to manufacturer information


Airbag	Central consol	Distance control	Electric adjustable mirrors
GPS	Headlight sprinkler	Isofix	Power steering
Rims alloy	Roof bars	Seats F heated (ECS&B)	Steering wheel leather
Steering wheel multifunctional	Telephone	Windows electric functioning	

Options according to the inspector

GPS	**Yes**

Damages


Bodywork
Damaged
Acceptable
Roof & others





Bumper F
Dent(s) and scratch(es)
Paint
Front








Charging cable (normal)
Missing
Check
Rear



Door FR
Repaired
No repair
Right



Door RR
Repaired
No repair
Right



Ignition key
Missing
Replace
Interior



Inner door sill FR
Dent(s) and scratch(es)
Smart repair
Right





Interior
Damaged
Acceptable
Interior

















Seat cover FR
Stain
Cleaning
Interior



Tyre FL
Tear
Replace
Left





Tyres

Front Left
Summer
Aluminium
255/50/19/103/T
Pirelli
5.0 mm
Front Right
Summer
Aluminium
255/50/19/103/T
Pirelli
4.0 mm
Rear Left
Summer
Aluminium
255/50/19/103/T
Pirelli
5.0 mm
Rear Right
Summer
Aluminium
255/50/19/103/T
Pirelli
6.0 mm

Checks

Category	**Passenger Car**	Certificate of Conformity	**Yes**
Compressor	**N/A**	Emergency spare wheel	**N/A**
Jack	**N/A**	Maintenance	**OK**
Maintenance	**9/2026**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**2**	Number of keys total	**1**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**Yes**
Repair kit	**N/A**	Reset to factory settings	**No, not possible**
Runflat	**N/A**	Spare wheel	**N/A**
State of Health	**91.0**	Type of Maintenance book	**Digital maintenance**

VIN detail - *If the description in the language of your choice is not available, the French description is shown*

2 ports USB-C à l'avant	ABS	Accoudoir central AV
Acoustic Parking System (APS) à l'arrière	Airbag central à l'avant	Airbag conducteur
Airbag passager	Airbags latéraux intégrés aux sièges à l'avant	Airbags rideaux
Allumage / extinction automatique des feux	Audi Drive Select	Boitiers des rétroviseurs extérieur dans la couleur carrosserie
Ciel de toit en tissu gris	Climatisation électronique 3 zones	Contours de fénêtres en aluminium
Désactivation manuelle de l'airbag passager	Direction assistée	Dossier de la banquette arrière rabattable en 2 parties (40:60)
Eclairage intérieur	Encarts décoratifs en noir laqué 'Soft touch'	ESP (système électronique de stabilité)
Feux arrière LED	Feux de jour AV	Fixation pour siège-enfant ISOFIX pour le siège du passager avant
Fixations ISOFIX et Top Tether sièges arrière	Fonction coming home - leaving home	Garantie 3 ans/120.000 km
Gilet de sécurité	Haut-parleurs à l'avant (4)	Hayon à ouverture et fermeture électrique
Interface Bluetooth (téléphonie et audio)	JAV 5 branches design 'W-Aero' gris graphite 8Jx19''+235/55 R19 101T & 255/50 R19 103T	Kit Navigation: MMI GPS Plus+Virt.cock.+rec.pann.
Lave-phares	Limiteur de vitesse	Outillage de bord
Pack Business Plus	Pack Business Plus (convention A/B/C/D/E/F/H/P)	Pack interior S line (tissu/similicuir-noir)
Pare-brise en vitrage isolant	Passages de roues et pare-chocs teinte carrosserie	Peinture unie
Phares avant à technologie DEL Matrix avec feux arrière LED et clignotants dynamiques avant/arrière	Phares avant LED	Prise 12V à l'arrière
Radio numérique (DAB)	Railing de toit façon aluminium	Reconnaissance des panneaux routiers
Rétroviseur intérieur jour/nuit manuelle	Rétroviseurs extérieurs électriques et chauffants	Sièges avant chauffants
SONOS Premium sound system	Suspension confort	Système de contrôle de la pression des pneus
Tapis de sol complémentaires avant et arrière	Tissu 'Index'	Transponder (ATR1)
Trousse de secours	Trousse de secours avec triangle présignalisation	Version non-fumeur
Vitrage isolant	Vitres des portes avant avec vitrage acoustique	Vitres électriques avant et arrière
Vitres latérales (à partir montant B) et lunette arrière assombris	Volant gainé de cuir	Volant multifonctions
Volant multifonctions Plus en cuir à 4 branches avec basculeurs (+/-) aplati en bas et en haut		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.