TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48054639
Order No. / Reference: 26981579
Inspection date: 23 Sept 2026

Manufacturer: Volvo	Model: V60 B4 D Geartronic Momentum Pro
VIN: YV1ZWK5VDN2495893	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volvo V60 B4 D Geartronic Momentum Pro	
Vehicle Identification number	YV1ZWK5VDN2495893
Mileage (Read)	155,212 km
First registration	3 Jun 2022
Number of holders	1
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,969 ccm / 4
Power	145 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Station wagon
Colour / colour code	Pine Grey Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	220 Tag(e)
Last service on / at	05/2026 at 141,543 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GJ549879
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	9101 / BTH 00013		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,280 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 98V	Summer tyres on Light alloy	Michelin	4mm / 4mm
2)	225/50 R17 98V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/50 R17 94H	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	225/50 R17 94H	Winter tyres on Light alloy	Pirelli	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 04/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ABS - Anti-lock Braking System (with EBV)
- Driver and front passenger airbags with two-stage deployment system (side airbags for driver and front passenger and head/ shoulder airbags (IC) for all occupants)
- Attachment system for carrier bags in the luggage compartment
- LED turn signals integrated into the exterior mirrors
- On-board computer with vehicle control functions
- City Safety (automatic emergency braking system with detection of vehicles, cyclists, pedestrians and large animals, including intersection braking assistant, emergency braking assistant for oncoming traffic and steering support during evasive maneuvers)
- Roof edge spoiler
- Black roof rails (integrated)
- Digital instrumentation: 12.3" full-graphic display (31.2 cm diagonal, high resolution) (with two variable round instruments and information display (e.g. for navigation map view))
- Insoles: Iron Ore
- Aluminum door sill plates with Volvo lettering at the front
- Electronic differential lock
- Automatic emergency braking (emergency braking mechanism after the deployment of the airbags or seatbelt pretensioners to prevent secondary accidents)
- Cruise control system with variable speed limiter
- Front seat belt height adjustment
- rear window wiper
- Interior lighting (headliner, front reading lights, front ambient lighting, front footwell, storage compartment behind center console, glove compartment and luggage compartment)
- Keyless Start (electronic engine start system)
- Automatic climate control (with separate temperature control for driver and front passenger and additional air vents for the rear seats (integrated in the B-pillar) including pre-ventilation and reheating of the interior when the engine is switched off via Volvo On Call smartphone app or menu)
- Lane Keeping Aid (LKA) - Active lane keeping assistant
- Steering wheel adjustable for height and reach
- Steering wheel: Multifunction buttons on the steering wheel
- Rear center armrest (foldable) with cup holders
- Emergency brake lights (brake lights flash rapidly during heavy deceleration; hazard warning lights are automatically activated at speeds below 10 km/h)
- Electric parking brake
- Parking ticket holder
- Particulate filter: Soot particle filter for diesel engines
- Radio: Sensus Connect infotainment system (9" touchscreen (22.9 cm diagonal) - 2 USB ports (compatible with Apple iPod/iPhone/iPad) - Bluetooth hands-free system incl. audio streaming - Digital vehicle owner's manual - Digital radio reception (DAB+) - Internet access incl. internet radio and apps (via paired smartphone) - Voice control
- Road Sign Information (RSI) (Traffic Sign Recognition)
- Front passenger airbag can be deactivated
- Electrically folding exterior mirrors
- Electrically adjustable exterior mirrors
- Heated exterior mirrors and rear window (automatic)
- Outdoor temperature display
- Hill Start Assist (HSA)
- Condensation sensor (for automatic activation of the defroster function)
- third brake light
- CleanZone air quality system (with activated carbon filter, automatic recirculation and pre-ventilation of the interior when the vehicle is unlocked)
- Colored glazing
- Connected Safety (Cloud-based warning of slippery road conditions and vehicles with hazard warning lights activated)
- Drive Mode (driving mode settings for engine, transmission, steering, brakes: Comfort, Eco, Dynamic, Individual)
- Driver Alert - Attention Warning
- Rear parking assist
- Electronic Stability Control (ESC)
- Electric windows front and rear (with auto-down and auto-up function)
- Front grille in waterfall design in black
- Luggage compartment partition net
- Transmission: 8-speed Geartronic (automatic transmission)
- Interior and exterior mirrors with automatic dimming function
- Intelligent driver information system (delays incoming calls or vehicle information in dangerous situations)
- ISOFIX anchors for the outer rear seats
- Child safety lock (manual, rear doors)
- Headrests (5) front and rear, (rear ones manually foldable)
- Rear headrests foldable, electrically
- Charging box under the cargo floor
- Stainless steel loading sill protector in the luggage compartment
- Cargo area roller blind
- LED headlights "Thor's Hammer" (with high beam assist and integrated LED daytime running lights)
- Illuminated makeup mirror for driver and front passenger
- Front center armrest with integrated storage compartment and cup holders
- Oncoming Lane Mitigation ((Preventive protection system when crossing the center line and approaching oncoming traffic including active steering intervention towards one's own lane)
- Radio: Audio system High Performance Sound (170 watts of power - 10 speakers)
- Radio accessories: Digital radio reception (DAB+)
- Radio accessories: Two USB-C ports on the back of the center console
- Rain sensor

- Run-off Road Protection (preventive protection system in case of unintentional leaving the road or impending rollovers including emergency call via Volvo On Call and door unlocking)
- Wheel accessories: Tire sealant (incl. 12-volt compressor - maximum speed 80 km/h)
- Seat belts (active seat belts with belt tensioner - warning tone/ indicator when seat belts are not fastened (for all seats))
- Seats: Driver and front passenger seats height adjustable (electrically) (including manual tilt adjustment for the driver's seat)
- Start/Stop technology
- Power outlet (12-volt connection in the luggage compartment)
- Lashing eyes in the luggage compartment (foldable)
- Preparation for Trailer Stability Assist (TSA)
- Immobiliser
- WHIPS whiplash protection system (including immersion protection on all seats and energy-absorbing front seat cushions)
- Central locking with two remote controls and integrated emergency key (including automatic locking of the doors while driving (can be deactivated) - panic function (integrated in the remote control) - comfort opening/closing of the side windows and, if applicable, the sunroof via remote control)
- Road Edge Detection (system to protect against unintentional leaving of the roadway through steering and braking interventions)
- Wheels: 17" alloy wheels, 5-twin-spoke design (7 J x 17 with 225/50 R 17 V tires)
- Wheels: Tire pressure monitoring system (passive) (with tire-specific pressure loss warning)
- Speed-sensitive power steering
- Safety braking system with disc brakes all around (internally ventilated) (automatic brake system pre-tensioning, brake assist and automatic hold function)
- Safety steering column (adaptive)
- Seats: Lumbar support (2-way electrically adjustable) for driver and front passenger seats
- Seats: Rear seats in a 40/60 split or fully foldable with pass-through function
- Power outlet (12-volt connection at the front)
- Fuel filler neck with misfuelling protection
- Volvo On Call with WiFi hotspot (including integrated modem, external antenna, and WiFi hotspot for mobile devices). Volvo On Call features: Automatic emergency call function with transmission of vehicle position and data, and alerting the Volvo On Call Service Center at the touch of a button (10-year subscription). Additionally, various convenience services are available via the smartphone app, such as Send-to-Car, trip log, and locking/unlocking the vehicle (3-year subscription, extendable upon request; includes extension of the emergency call function).

Extra equipment

- Design Package
- Head-Up Display (graphical projection of driving information onto the windshield)
- Package: Parking Assistance Package (front and rear parking aid - reversing camera)
- Pilot Assist (Adaptive cruise control with distance warning - Lane keeping assist up to 130 km/h - Curve Speed Assist (CSA) - Adjustment of vehicle speed before curves based on map data)
- Upholstery: Premium textile comfort seats
- Radio: Audio system High Performance Sound Pro by Harman/ Kardon (600 watts of power - 14 speakers - Fresh Air Subwoofer - Dirac Unison sound optimization)
- Side and rear windows tinted (from the B-pillar back)
- Fire extinguisher
- Paint finish: Metallic paint
- Package: Lighting Package (LED fog lights - headlight cleaning system - full LED headlights "Thor's Hammer" Active High Beam with extended high beam, dynamic cornering lights, intelligent high beam assist with adaptive headlight range control and integrated LED daytime running lights - ambient lighting, extended interior lighting: multi-colored ambient lighting front/rear, exit lights front/rear, illuminated door pockets and door handles front/rear, illuminated cup holders front, footwell lighting rear, reading lights rear, work light on the tailgate.)
- Wheels: 17" 5-spoke alloy wheels, diamond cut/graphite look (7 J x 17 with 225/50 R 17 V tires)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Equipment	Tirefit filler - Expired - Replace
3	Sill - left side	Sill - dent(s) - Smooth repair work
4	Door - front left side	Door - Scratch(es) - Smart repair
5	Door - front right side	Door - Scratch(es) - Smart repair
6	Indicator - front	Mirror - right side - Scratch(es) - Replace
7	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
8	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
9	Front bumper	Bumper - front right side - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Rear bumper	Rear bumper - dent(s) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 12 Dec 2022	977,41 €
2	Side right, Provided by user / customer, from 27 Jun 2022	1.117,29 €
3	Side - left, Provided by user / customer, from 13 May 2026	1.791,35 €
4	Front, Provided by user / customer, from 26 May 2025	2.216,95 €

Repainting

No.	Repainting
1	Door - rear right side, Professionally carried out, Invoice of repair done Non-existent
2	Door - front right side, Professionally carried out

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Damage 2: Equipment: Tirefit filler - Expired - Replace



Damage 3: Sill - left side: Sill - dent(s) - Smooth repair work



Damage 4: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door - Scratch(es) - Smart repair



Damage 4: Door - front left side: Door - Scratch(es) - Smart repair




Damage 5: Door - front right side: Door - Scratch(es) - Smart repair



Damage 5: Door - front right side: Door - Scratch(es) - Smart repair



Damage 5: Door - front right side: Door - Scratch(es) - Smart repair



Damage 6: Indicator - front: Mirror - right side - Scratch(es) - Replace




Damage 6: Indicator - front: Mirror - right side - Scratch(es) - Replace



Damage 7: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 7: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 8: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 8: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 8: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 9: Front bumper: Bumper - front right side - Scratched - Paint



Damage 9: Front bumper: Bumper - front right side - Scratched - Paint




Damage 9: Front bumper: Bumper - front right side - Scratched - Paint



Damage 9: Front bumper: Bumper - front right side - Scratched - Paint



Damage 9: Front bumper: Bumper - front right side - Scratched - Paint



Repainting 1: Door - rear right side



Repainting 1: Door - rear right side



Repainting 2: Door - front right side



Repainting 2: Door - front right side