BMW X3

Vehicle information


Make:	**BMW**	License:	**2CFR788**
Gearbox:		Body color:	
Model:	**X3**	VIN:	**WBA61DP0009M42046**
Fuel type:		Power:	**120 kW**
Version:	**2.0 XDRIVE30E (120KW) AUTO**	First registration	**06/07/2022**
Mileage:	**110146 km**	N° of doors:	

Damage summary

Interior	2
Left	1
Rear	2
Right	2
Roof & others	1

Commercial pictures



































Options according to the inspector


GPS	**Yes**

Damages

Bodywork
Damaged
Acceptable
Roof & others







Door RR
Scratch(es)
Polish
Right




Ignition key
Missing
Replace
Interior



Interior
Damaged
Acceptable
Interior





Rear light L
Broken
Replace
Rear





Tailgate / Boot
Dent(s) and scratch(es)
Repair and paint (complete)
Rear






Tyre FL
Tear
Replace
Left





Wing RR
Dent(s) and scratch(es)
Repair and paint (complete)
Right






Tyres

Front Left
Summer
Aluminium
225/60/18/104/W
Yokohama
4.0 mm
Front Right
Summer
Aluminium
225/60/18/104/W
Yokohama
4.0 mm
Rear Left
Summer
Aluminium
225/60/18/104/W
Yokohama
4.0 mm
Rear Right
Summer
Aluminium
225/60/18/104/W
Yokohama
4.0 mm

Checks

Battery level	**100**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**N/A**
Maintenance	**OK**	Maintenance	**+ 23000 km**
Number of charging cables (normal)	**1**	Number of charging cables (rapid charge)	**1**
Number of keys total	**1**	Registration Certificate Car (BE)	**Yes**
Registration Certificate Home (BE)	**No**	Repair kit	**N/A**
Reset to factory settings	**Yes, vehicle is reset to factory settings**	Runflat	**N/A**
Statutory inspection	**OK**	Statutory inspection	**06/07/2028**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.