DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	VF7SXHMRV RT085114	Registration date	29/07/2024	Exterior Color	Unknown
Brand	CITROEN	Licence Plate	HH-L 6568	Odometer	8 674 km
Model	C3 PureTech 83 Stop&Start YOU!				

Inspection Details

Arrival Date	12/08/2026	Inspection ID	7130669	Inspection date	18/08/2026
Assign Date	12/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys Hubmotion Gifhorn



Generic equipment

Removable element

Spare wheel kit	✔
Rear parcel shelf	✔
Radio user manual	✔


Technical Document

User manual	✔
Warranty booklet	✔
Log books	✔
Spare key	✔
Key	✔
Service	✔

Tyres

Uniroyal 185/65/15 T All seasons 5.0 mm

Uniroyal 185/65/15 T All seasons 5.0 mm



Uniroyal 185/65/15 T All seasons 5.0 mm

Uniroyal 185/65/15 T All seasons 5.0 mm

Exception / Damage

1

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	-

DEKRA

DEKRA Automotive Solutions

Appraisal Report

2



Part	Bonnet	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

3



Part	Windscreen	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Stone impact	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

4



Part	Wheelcap 15"	Repair Time	0.10	Part Cost	34.70€
Position	Front left	Repair Cost	14.00€	Gross Cost	48.70€
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 7.30
Repair mode	Replace	Flat Rate	-	**Net Cost**	**41.40€**

5



Part	Wheelcap 15"	Repair Time	-	Part Cost	34.70€
Position	Front right	Repair Cost	-	Gross Cost	34.70€
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 5.20
Repair mode	Replace	Flat Rate	-	**Net Cost**	**29.50€**

6



Part	Wheelcap 15"	Repair Time	-	Part Cost	34.70€
Position	Back right	Repair Cost	-	Gross Cost	34.70€
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	- 5.20
Repair mode	Replace	Flat Rate	-	**Net Cost**	**29.50€**

7



Part	Wheelcap 15"	Repair Time	-	Part Cost	-
Position	Back left	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

Summary Inspection

Gross Price	118.10€	Depreciation	-17.70€	Net Price	100.40€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.10	14.00€	15.00 %	-2.10€	11.90€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	104.10€	15.00 %	-15.62€	88.49€
Flat Rate	0.00€	-	-	0.00€