TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48504994
Order No. / Reference: 27252960
Inspection date: 3 Nov 2026

Manufacturer: Volvo	Model: XC40 B4 B AWD DKG Plus Bright
VIN: YV1XZK8V4P2028845	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volvo XC40 B4 B AWD DKG Plus Bright	
Vehicle Identification number	YV1XZK8V4P2028845
Mileage (Read)	24,471 km
First registration	12 May 2023
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,969 ccm / 4
Power	145 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Fjord Blue Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	206 Tag(e)
Last service on / at	06/2026 at 21,491 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ210353
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	9101 / BRP 00022		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,270 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 100V	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/55 R18 100V	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R18 104H	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	235/55 R18 104H	Winter tyres on Light alloy	Bridgestone	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 12-volt power outlet in the luggage compartment
- 12-volt socket at the front
- Airbags (driver and front passenger airbags with two-stage deployment system - driver's knee airbag - driver and front passenger side airbags - head/shoulder airbags (IC) for all occupants)
- Aluminum roof rails (integrated)
- Android infotainment system (9" touchscreen (22.9 cm diagonal) - Bluetooth hands-free system incl. audio streaming - Digital vehicle owner's manual - Digital radio reception (DAB+))
- Anti-lock braking system (ABS) with electronic brake force distribution
- Central locking with two remote controls and integrated emergency keys (including automatic locking of the doors while driving (can be deactivated))
- Comfort opening/closing of the side windows via radio remote control
- Cup holders (two) in the center console
- Digital Services including Google Maps navigation system (Google Services (includes Google Maps, Google Assistant, Google Play Store and unlimited data) - Volvo On Call (includes, among other things, contacting the Volvo On Call service center at the touch of a button and additional convenience services via the Volvo CarsApp) - Usage is time-limited and will be subject to charges thereafter. Further information on renewal is available from a Volvo dealer partner.)
- Electric parking brake
- Electric windows front and rear (with auto-down and auto-up function)
- Electrically adjustable exterior mirrors
- Electronic differential lock
- Emergency brake lights (brake lights flash rapidly during heavy deceleration; hazard warning lights are automatically activated below 10 km/h)
- Enhanced Clean Zone air quality system (with fine dust filtration according to air quality standard PM2.5)
- Exterior mirror caps in car color
- First aid kit and warning triangle
- Front grille in waterfall design in high-gloss black (with end faces in light chrome finish)
- Front headrests
- Glazing: Colored glazing
- Hill start assist
- Hooks for carrier bags in the luggage compartment (two on each side)
- Immobiliser
- Intelligent driver information system (delays incoming calls or vehicle information in dangerous situations)
- Interior and exterior mirrors automatically dimming
- Keyless Drive (electronic access system) with sensor-controlled tailgate, illuminated door handles and puddle lights
- Active safety belts with belt tensioners
- All-wheel drive (AWD) (via electronic Haldex coupling (5th generation) with Instant Traction)
- Aluminum door sill plates with Volvo lettering at the front
- Ambient lighting (Extended interior lighting with: - Ambient lighting front and rear - Exit lights front - Illuminated door pockets front - Illuminated decorative inserts (in dashboard and front doors) - Reading lights rear - Work light on the tailgate)
- Automatic climate control with 2-zone temperature control (including separate temperature control for driver and front passenger, automatic blower control and air distribution including CleanZone air quality system with activated carbon filter)
- Automatic emergency braking (locking the vehicle after the airbags or seatbelt pretensioners have been deployed to prevent secondary accidents.)
- Automatic tailgate (electric)
- Chassis: Dynamically designed
- Child safety lock for the rear doors (electric)
- Chrome side window trim (bottom)
- City Safety (emergency braking system with detection of vehicles, cyclists, pedestrians and large animals, including intersection braking assistant)
- Electrically folding exterior mirrors
- Electronic stability control
- Fold-out (bag) hook on the glove compartment
- Foldable cargo floor with fastening system for carrier bags in the luggage compartment
- Front and rear parking sensors with automatic braking intervention (rear)
- Front center armrest with integrated storage compartment
- Front seat belt height adjustment
- Gearshift lever made of Swedish crystal glass (with center console surround in high-gloss black)
- Heated exterior mirrors and rear window
- Hill descent control
- Illuminated makeup mirror for driver and front passenger
- Integrated, removable waste bin in the center console
- Interior lighting (welcome lights, headliner lighting, luggage compartment lighting, front reading lights)
- ISOFIX mounting for the outer rear seats
- Keyless Start (electronic engine start system)
- Lashing eyes (four) in the luggage compartment
- LED headlights "Thor's Hammer" (with high beam assist and integrated LED daytime running lights)
- LED turn signals integrated into the exterior mirrors
- Optical underride protection front and rear in high-gloss black
- Otto particulate filter

- Luggage compartment partition net
- Package: Parking Assistance Package (Mild Hybrid) (Front and rear parking aid with automatic braking intervention (rear) - reversing camera)
- Package: Winter Package (front seat heating - steering wheel heating)
- Paint finish: Solid
- Preparation for Trailer Stability Assist (TSA)
- Radio accessories: Digital radio reception (DAB+)
- Radio accessories: Two USB-C ports in the front center console
- Rain sensor
- Rear center armrest with two integrated cup holders
- Roof edge spoiler
- Safety Assistance (Automatic emergency braking system with detection of vehicles, cyclists, pedestrians and large animals including intersection braking assistant and emergency braking assistant for oncoming traffic - Connected Safety - Driver Alert - Attention warning - Variable speed limiter - Cruise control - Lane Keeping Aid (LKA) - Active lane keeping assistant - Oncoming Lane Mitigation - Ready to Drive notification - Road Edge Detection - Road Sign Information (RSI) - Traffic sign recognition)
- Stainless steel loading sill protector in the luggage compartment
- Start/Stop technology
- Steering wheel adjustable for height and reach
- Steering wheel: Sports steering wheel
- Textile floor mats: Sport textile floor mats front and rear
- third brake light
- Tire pressure monitoring system (with tire-specific pressure loss warning)
- Wheels: 18" alloy wheels, 5-V-spoke design (7.5 Jx 18" with 235/55 R18 tires, tire category A)
- Wheels: Tire sealant (Incl. 12-volt compressor, maximum speed 80 km/h)
- Package: Seat Comfort Package (Electrically adjustable front passenger seat - Electrically adjustable driver's seat with memory function for driver's seat and exterior mirror settings (stored in remote control) - 2nd row headrests foldable (electrically))
- Pass-through hatch behind the center armrest in the rear
- Passenger side airbag can be deactivated
- Phone: Inductive smartphone charging system (Wirelessly charges smartphones that support the QI standard on a charging pad)
- Radio accessories: Two USB-C ports on the back of the center console
- Radio: Premium Sound audio system by Harman Kardon (600 watts of power - 13 speakers - Fresh Air subwoofer - Dirac Unison sound optimization)
- Rear seats can be folded down in a 40/60 split or completely.
- rear window wiper
- Run-off Road Protection (preventive protection system in case of unintentional leaving the road or impending rollovers including emergency call via Volvo On Call and door unlocking)
- Seats: Adjustable (manual) leg rest for driver and front passenger seats
- Seats: Lumbar support (4-way electrically adjustable) for driver and front passenger seats
- Seats: Passenger seat adjustable in height and length
- Seats: Whiplash protection system WHIPS (including immersion protection on all seats and energy-absorbing seat cushions in the front)
- Second generation digital instrumentation (12.3" full graphic display (31.2 cm diagonal) with two variable round instruments and information display (e.g. for navigation map view))
- Speed-sensitive power steering
- Steering wheel: Multifunction buttons on the steering wheel
- Tachometer
- Transmission: 7-speed dual-clutch transmission
- Warning tone/indicator when seat belts are not fastened (for all seats)

Extra equipment

- Windscreen, heater
- Paint finish: Metallic paint
- Package: Lights (LED fog lights - headlight cleaning system)
- Upholstery: Leather/imitation leather (incl. rear center armrest - real wood inlay: Drift Wood - headliner: Light Beige)
- Glazing: Side and rear windows tinted (from the B-pillar back)
- XC40 W-wheel set 5-DpSp R-Design 235/55 R18 104H Nok
- Luggage compartment tray mat
- Package: Driver Assistance Package (Mild Hybrid) (Adaptive Cruise Control - Emergency Stop Assist - automatic emergency braking system if warnings are ignored due to the driver's failure to steer, brake, or accelerate, including activation of the hazard warning lights and automatic braking to a standstill - Pilot Assist - Blind Spot Information System - Blind Spot Assist - Lane Change Warning including steering intervention - Cross Traffic Alert - cross traffic warning with braking intervention - Rear Collision Mitigation)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
3	Sill - left side	Sill - Scratch(es) - Smart repair
4	2nd wheel set	1 alloy rim - Scratch(es) - Loss in value
5	Roof	Roof (Anätzung) - Paint defect - Conditioning
6	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
7	Bonnet	Bonnet - Scratch(es) - Paint
8	Front bumper	Front bumper (Zusätzlich Spoiler Kratzer) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Side panel - rear right side	Side panel - Soiled - No deduction
2	Vehicle glazing	Windscreen - Stone chips - No deduction
3	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Documents - Log book

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 4: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 4: 2nd wheel set: 1 alloy rim - Scratch(es) - Loss in value



Damage 5: Roof: Roof (Anätzung) - Paint defect - Conditioning



Damage 5: Roof: Roof (Anätzung) - Paint defect - Conditioning



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value




Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Bonnet: Bonnet - Scratch(es) - Paint



Damage 7: Bonnet: Bonnet - Scratch(es) - Paint



Damage 7: Bonnet: Bonnet - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (Zusätzlich Spoiler Kratzer) - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (Zusätzlich Spoiler Kratzer) - Scratch(es) - Paint



Damage 8: Front bumper: Front bumper (Zusätzlich Spoiler Kratzer) - Scratch(es) - Paint