TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48410376
Order No. / Reference: 27154015
Inspection date: 21 Oct 2026

Manufacturer: Mercedes-Benz	Model: GLC-Coupe 200 4Matic 9G-TRONIC Avantgarde Advanced
VIN: W1NKJ5BBXRF099866	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz GLC-Coupe 200 4Matic 9G-TRONIC Avantgarde Advanced	
Vehicle Identification number	W1NKJ5BBXRF099866
Mileage (Read)	63,352 km
First registration	16 Nov 2023
Number of holders	1
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,999 ccm / 4
Power	150 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	Coupe
Colour / colour code	GRAPHITGRAU - METALLICLACK
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Anthracite-Black

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	220 Tag(e)
Last service on / at	04/2026 at 50,565 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY525371
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / BOF 00069		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,510 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R18 103W	Summer tyres on Light alloy	Continental	5mm / 5mm
2)	235/60 R18 103W	Summer tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Adaptive Highbeam Assist (automatic switching of the high beams on and off - camera on the inside of the windshield - detects oncoming and preceding illuminated vehicles - activated by pressing the steering wheel control lever to the high beam position)
- Active Lane Keeping Assist (A steering wheel vibration warns the driver if the vehicle unintentionally leaves its lane, and the ESP system can actively apply the brakes on one side of the vehicle at speeds between 60 and 200 km/h - the Active Lane Keeping Assist warning can be switched on and off - the intervention sensitivity can be set to Standard or Sensitive. In Sensitive mode, the Active Lane Keeping Assist is more prone to intervention.)
- ATTENTION ASSIST (can detect typical signs of fatigue via steering behavior and can warn the driver of impending microsleep)
- Hill start assist
- Double cup holder
- Third brake light in LED technology
- EASY-PACK tailgate (electrically opening and closing tailgate - switch for electrically opening the tailgate in the driver's door - switch for electrically closing the tailgate at the bottom edge of the tailgate - manual cargo cover for covering the cargo area)
- Driver display (31.2 cm (12.3") color LCD display with a resolution of 2,400 x 900 pixels - five different menus with specific content and display styles)
- Velour floor mats
- Transmission: 9G-TRONIC
- Rear window heated
- rear window wiper
- Instrument panel in black with contrasting decorative stitching
- Climate: Pre-conditioning (Pre-conditioning offers increased climate comfort when entering the vehicle for vehicles with hybrid technology and REMOTE CLIMATE CONTROL. Activated by the electronic key, the interior can be pre-heated or cooled as needed before starting the engine.)
- Paint finish: Solid
- LED High Performance headlights (The LED High Performance headlights offer increased safety at night and a distinctive, striking look. Thanks to LED technology, they illuminate the road better than conventional headlights – with lower energy consumption. The adaptive LED taillights adjust their light intensity to the ambient conditions.)
- Center console in high-gloss black
- Navigation accessories: Extended MBUX functions (personalization (profiles) and predictive functions - MBUX voice assistant with natural language understanding - activation via "Hey Mercedes" - learning function of the MBUX voice assistant by connecting to a cloud-based online dictionary - Wi-Fi hotspot - internet radio)
- Airbag for driver and front passenger
- Airbag: Sidebag for driver and front passenger (combined thorax/ pelvisbag)
- Airbag: Windowbag
- Active Brake Assist
- 4MATIC permanent all-wheel drive
- Ambient lighting (Three dimming zones (total, ambient and accent) - Variable brightness setting - 64 colors - Ten color moods - Integrated into the ENERGIZING comfort control programs)
- Anti-lock braking system + Electronic brake force distribution (ABS + EBV)
- Traction control (ASR)
- Automatic passenger airbag deactivation
- Basic services (accident and breakdown management, maintenance management, telediagnostics, remote vehicle diagnostics)
- Tachometer
- Dynamic front bumper with visual underguard (in glossy chrome and diamond mesh air intakes in grained black - rear bumper painted in body color with visual underguard in glossy chrome)
- EASY-Pack: Cargo area cover
- Electronic Stability Program (ESP)
- Chassis: Sport chassis (sport direct steering)
- Fingerprint scanner (color-illuminated fingerprint scanner in the control bar below the central display - two fingerprints can be stored per user - faster access replaces PIN entry - protects personal data such as profiles as well as office and payment functions)
- Interior headliner fabric crystal grey
- Climate: THERMATIC automatic climate control (2-zone automatic climate control - control of climate settings - depending on equipment - sensor system for detecting, for example, indoor/outdoor temperature, solar radiation, humidity and dew point - automatic recirculation - ventilation system: 3 center vents in the center area and 2 side vents (each swiveling and adjustable), 2 air vents each in the footwell for driver and front passenger - fine dust activated carbon filter for filtering dust, soot and pollen - dew point sensor)
- Steering wheel: Multifunction sports steering wheel in leather (sporty steering wheel in 3-spoke design - leather finish - black grained shift paddles - control via touch panels)
- Mercedes-Benz Emergency Call System (The Mercedes-Benz Emergency Call System can provide a crucial time advantage in an emergency. A communication module with its own SIM card automatically triggers an emergency call upon detection of an accident, which can shorten the time until emergency services arrive. The emergency call can also be triggered manually to organize assistance.)
- Navigation accessories: Pre-installation for navigation services (display of online content on the navigation map - parking spaces - weather information - local search - digital logbook)

- Navigation accessories: Pre-installation for Live Traffic Information (With Live Traffic Information, your navigation system receives real-time traffic data and optimizes dynamic route guidance. Thanks to precise and up-to-date information on traffic jams, stop-and-go traffic, and more, you are supported in reducing travel times.)
- Otto particulate filter
- Package: Storage (map pockets on the back of the front seats - folding box)
- Package: Avantgarde Advanced (P14 AVANTGARDE Interior - P15 AVANTGARDE Exterior - 00U Remote Services - 70B Warning Vest for Driver - PBG MBUX Navigation Premium - PDA Advanced Package)
- Package: Interior lighting (front and rear footwell lights - LED light in the center console storage compartment - cupholder lighting - door handle lighting - door pocket lighting - illuminated cosmetic mirror - angled lights in the front/rear doors)
- Package: Parking package with reversing camera (12 ultrasonic sensors: six each in the front and rear bumpers - Active Parking Assist - Reversing camera - PARKTRONIC - Rear Cross Traffic Alert - Drive Away Assist - Button for Active Parking Assist incl. PARKTRONIC on the center console)
- Package: Mirror package (both exterior mirrors electrically folding (button in the driver's door control panel) - interior mirror and exterior mirror on the driver's side automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area with projection of the Mercedes-Benz logo)
- Radio accessories: Digital radio
- Tire pressure loss warning
- Wheels: 45.7 cm (18") light alloy wheels in 5-twin-spoke design, painted black (aerodynamically optimized and polished with 235/60 R18 tires on 8.0 J x 18 ET 32.5)
- Windscreen wipers with rain sensor
- Seats: Heated seats for driver and front passenger seats
- Phone accessories: Wireless charging system for mobile devices at the front (Your smartphone is placed in its designated spot in the charging tray with just one hand movement and is charged wirelessly there. Compatible smartphones charge wirelessly regardless of model and brand.)
- Cruise control
- TIREFIT (Your quick temporary solution for minor tire damage. Damage caused by embedded nails or shards of glass is sealed by the sealant blown in via an air compressor. This allows you to continue driving to the nearest repair shop at speeds of up to 80 km/h.)
- High-visibility vest for drivers
- Heat-insulating dark tinted glass
- Central locking with remote control
- Decorative elements in diamond pattern, silver-grey
- Navigation: MBUX Navigation Premium (hard drive navigation including 3-word address system what3words - high-resolution navigation with satellite view - live traffic information and Car-to-X communication, including display of the emergency lane for emergency vehicles and active warning of traffic jam end - fast online route calculation - Send2Car function: sends selected addresses via app to the vehicle's navigation system)
- Package: Chrome Interior Package
- Package: Boot Comfort Package (electrically foldable rear seat backrests via switches on the right and left in the control panel in the cargo area - 12V socket on the left in the control panel in the cargo area - tension strap on the right side wall - reversible mat with a rubberized, non-slip side and a soft velour side)
- Package: Seating Comfort (various electric and manual adjustment options for the front seats to adapt to the specific body and comfort requirements of the driver and front passenger - electropneumatic 4-way lumbar support and lateral support adjustment with control element on the seat - electric seat cushion tilt adjustment - electric height adjustment - electric backrest adjustment - electric seat cushion depth adjustment by 6 cm with leg rest pad - mechanical longitudinal adjustment - mechanical headrest adjustment)
- Upholstery: ARTICO man-made leather
- Radio accessories: MBUX multimedia system
- Remote Services (Communication module - Mercedes me services: Programming of auxiliary heating/ventilation, remote door locking and unlocking, sunroof/windows with remote locking and opening including ventilation function, personalization of vehicle location, vehicle tracking, geographic vehicle monitoring, parking service monitoring, finder function (Remote Vehicle Finder))
- Telephone accessories: Smartphone integration (wirelessly connects the mobile phone to the MBUX multimedia system - display of selected third-party apps - access to current software and data, e.g., for navigation, traffic information, contact data, messaging, telephony, media, IP radio - optimized user interface for driving - control of smartphone functions via voice control)
- Pre-installation for digital key handover (Share your vehicle key even without personal handover - Decide to whom you open the vehicle and hand over the key - Use the functions conveniently in the Mercedes me app)
- Immobiliser
- Central display (touchscreen with LCD technology - 30.2 cm (11.9") screen diagonal - resolution of 1,624 x 1,728 pixels (width x height) - tilted 6° - 7° towards the driver)

Extra equipment

- Ambient Lighting Plus (ambient lighting with directly illuminated light lines: 64 colors, all individually selectable, 10 color worlds - variable brightness setting in 5 steps - 4 dimming zones: Total, Direct, Ambient, Accent - visual support for vehicle functions: automatic climate control, Welcome scenario, ENERGIZING Comfort Control - visual support for the Active Blind Spot Assist)
- Black fabric headliner
- Paint finish: Metallic
- Center console diamond pattern silver grey
- Package: Avantgarde Advanced Plus (electrically adjustable driver's seat with memory function - Blind Spot Assist - Illuminated door sills with "Mercedes-Benz" lettering - Traffic Sign Assist - Advanced Plus Package)
- Package: Parking package with 360° camera (12 ultrasonic sensors: six each in the front and rear bumpers - 360° camera - Active Parking Assist with PARKTRONIC - Cross-traffic warning can provide visual and audible warnings when reversing out of a parking space and, if necessary, automatically initiate emergency braking - Immobilizer can briefly limit the approach speed - Button for Active Parking Assist including PARKTRONIC on the center console)
- Wheels: Summer tires
- ENERGIZING AIR CONTROL (Air quality sensor and one fine dust sensor each for indoor and outdoor use - Fine dust filtration with 2 filters, consisting of a fine dust pre-filter and an interior filter - Interior filter in the air conditioner based on activated carbon with filter layers against fine dust (PM2.5) and nitrogen oxides (NOx) or sulfur dioxides (SO2) as well as pollen, allergens and soot particles - Automatic recirculation or fresh air switching depending on the measured air quality - Air quality menu in the MBUX multimedia system)
- Package: Driving Assistance Package Plus (Active Distance Assist DISTRONIC, Active Speed Limit Assist, Extended Automatic Restart, Route-Based Speed Adaptation with Traffic Jam Definition, Active Steering Assist, Active Lane Change Assist, Active Emergency Stop Assist with SOS Radio, Emergency Lane Radio, Active Brake Assist, Turn and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist, Exit Warning Radio, PRE-SAFE PLUS Pedestrian Warning Function, Traffic Sign Assist, Active Traffic Jam Assist, PRE-SAFE Impulse Side)
- Upholstery: ARTICO leatherette/fabric
- Type designation removed from trunk lid

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Sill - left side	Sill - Scratch(es) - Smart repair
2	Side panel - rear right side	Sill - Scratch(es) - Smart repair
3	Door - front left side	Door - Dent / paintcoat damage - Paint

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction
4	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 24 Aug 2025	2.305,18 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Navigation




Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Damage 1: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 1: Sill - left side: Sill - Scratch(es) - Smart repair




Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair



Damage 2: Side panel - rear right side: Sill - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Damage 3: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 3: Door - front left side: Door - Dent / paintcoat damage - Paint