TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48439589
Order No. / Reference: 27175875
Inspection date: 2 Nov 2026

Manufacturer: Volkswagen	Model: ID.4 4Motion GTX
VIN: WVGZZZE2ZPE020896	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volkswagen ID.4 4Motion GTX	
Vehicle Identification number	WVGZZZE2ZPE020896
Mileage (Read)	99,051 km
First registration	25 Jan 2023
Number of holders	1
Next periodical technical inspection	01/2028
(Report on hand)	
Fuel type	Electric
Power	77 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Stonewashed Blue Metallic / Dach Schwarzz
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Red

TÜV SÜD Auto Partner GmbH
Gutenbergstraße 13
70771 Leinfelden-Echterdingen

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	96 Tag(e)
Last service on / at	06/2025 at 54,949 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GP916967
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0603 / CLR 00021		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,750 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 104Y	Summer tyres on Light alloy	Pirelli	6mm / 6mm
2)	245/45 R20 101Y	Summer tyres on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 101T	Winter tyres on Light alloy	Bridgestone	3mm / 3mm
2)	255/50 R19 103T	Winter tyres on Light alloy	Bridgestone	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 2 USB-C ports at the front, 2 USB-C charging ports at the rear of the center console
- Airbags: Front and rear head airbags, front side airbags, center airbag
- 30-color ambient lighting
- Adaptive Cruise Control (ACC) "stop & go" including speed limiter
- Car2X
- e-Sound
- Parking assistance
- ESP Electronic Stability Program
- Windscreen made of laminated safety glass
- Back window, heater
- Interior mirror automatically dimming
- Air conditioning system "Air Care Climatronic"
- Mode 3 Type 2 charging cable, 16 A
- Charging: Maximum DC charging power depends on the traction battery.
- Steering wheel: Multifunction leather steering wheel, heated, with touch controls
- Fatigue detection
- Emergency call service
- Stainless steel pedals in a "Play/Pause" design
- Radio "Ready 2 Discover"
- Radio accessories: 6 + 1 speakers
- Rain sensor
- Wheels: "Ystad" alloy wheels 8 J x 20 front, 9 J x 20 rear, in black, polished finish
- Front windshield washer nozzles automatically heated
- electromechanical power steering
- Seats: Armrest for front seats
- Seats: Rear seat backrest asymmetrically split and foldable, with pass-through and center armrest
- Voice control
- Bumpers in a sporty design
- Engine underguard
- First aid kit, warning triangle and high-visibility vest
- Electronic immobilizer
- Turning brake function and evasive steering support
- Airbag for driver and front passenger, with front passenger airbag deactivation
- Permanent 4MOTION all-wheel drive
- App-Connect Wireless for Apple CarPlay and Android Auto
- Electrically adjustable, folding and heated exterior mirrors
- third brake light
- black roof rails
- Black surround for the infotainment display and central controls
- Driving profile selection
- Transmission: 1-speed automatic
- rear window wiper
- ISOFIX mounting points for child car seats
- Front and rear headrests (5)
- Charging: 11 kW AC charging power (alternating current)
- LED matrix headlights - IQ.LIGHT
- The strip between the headlights is illuminated.
- Makeup mirrors in the sun visors
- Variable center console
- Emergency braking assistant "Front Assist" with pedestrian and cyclist detection
- Upholstery: Seat center panels of the front seats and the outer rear seats in "GTX" fabric
- Radio accessories: Digital radio reception DAB+
- Tire pressure monitoring system
- LED taillights: 3D LED taillights with dynamic turn signals
- Windows: Rear side windows and rear window tinted
- Keyless Start system
- Seat belts: Three-point automatic seat belts at the front with height adjustment and belt tensioner
- Seats: Heated front seats
- Seats: Front seats with height adjustment
- Lane keeping assistant “Lane Assist”
- Telephone interface
- Ambient lighting with logo projection
- Traffic sign recognition
- Central locking including remote control

Extra equipment

- Foldable towbar (electric release)
- Charging cable: Mains charging cable for household socket
- Package: Design Package "Plus" (3D LED taillights with dynamic turn signals - Dynamic Light Assist for LED matrix headlights - IQ.LIGHT - LED matrix headlights with automatic headlight control, bad weather lights, welcome function - Illuminated strip between the headlights - Panoramic roof - Laminated safety glass for front side windows; tinted rear window and rear side windows)
- Package: Infotainment package "Plus" (Augmented reality head-up display - "Discover Pro" navigation system - "Ready 2 Discover Max" radio - "Comfort" telephone interface with inductive charging function - sound system, 6 speakers, digital 12-channel amplifier, subwoofer, 450 watts total power)
- Textile floor mats front and rear
- Paint finish: Metallic, different roof color
- Package: Assistance Package "Plus" incl. "IQ.DRIVE" with "Travel Assist" (GTX) (Easy Open & Close - tailgate with sensor-controlled opening and closing, with remote control, Adaptive Cruise Control (ACC) stop&go, speed limiter, anti-theft alarm with interior monitoring and towing, Travel Assist, Lane Assist and Emergency Assist, illuminated strip between the headlights and door handle recesses, memory radio for Park Assist, Park Assist Proactive, occupant protection, keyless entry and start system, Keyless Access with Safe-Side, Lane Change Assist, Side Assist, Area View including Rear View camera)
- Package: Sport package (progressive steering - sport suspension)
- Wheels: Winter wheels (4) "Hamar" 8 J x 19 (total) in Dark Graphite/ gloss-turned (winter tires 235/55 R 19 T / 255/50 R 19 T)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door edge - Scratch(es) - Smart repair
2	2nd wheel set	1 tyre - Does not meet the leasing specifications - Replace
3	2nd wheel set	1 tyre - Does not meet the leasing specifications - Replace

Wear and tear

No.	Component group	Description
1	Door - rear left side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 14 Oct 2025	4.140,56 €
2	Front, Side right, Provided by user / customer, from 9 Jan 2026	14.581,65 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Fahrzeugmodellbezeichnung laut Rechnung: "Volkswagen ID.4 4Motion GTX".



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Documents




Figure 17: Documents




Figure 18: Documents




Figure 19: Documents




Figure 20: Documents




Figure 21: Documents




Figure 22: Documents



Figure 23: Additional tyres



Figure 24: Navigation




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Figure 41: Misc.



Figure 42: Misc.



Figure 43: Misc.



Figure 44: Misc.



Figure 45: Misc.



Figure 46: Misc.




Figure 47: Misc.



Figure 48: Misc.




Figure 49: Misc.



Figure 50: Misc.




Figure 51: Misc.



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair



Damage 1: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 2: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 2: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 2: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 3: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 3: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Damage 3: 2nd wheel set: 1 tyre - Does not meet the leasing specifications - Replace



Wear and tear 1: Door - rear left side: Door - Scratch(es) - No deduction



Wear and tear 1: Door - rear left side: Door - Scratch(es) - No deduction



Wear and tear 1: Door - rear left side: Door - Scratch(es) - No deduction



Wear and tear 1: Door - rear left side: Door - Scratch(es) - No deduction