ARVAL
BNP PARIBAS GROUP

2CHT824

INSPECTION REPORT

End of contract

GENERAL INFO

File	324214
License plate	2CHT824
Vehicle identification number	VR3FCYHZTNY583664
Dossier	2021299199
Make	Peugeot 308 SW 1.5BHDi 130 All
Mileage	65331
First registration	02/08/2022
client availability date	09/10/2026
inspectionDate	15/10/2026











CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	




B
2 - CHT - 824
BELCAR

DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
271	Bumper Front / Trim Left / Replace	N
133	Bumper Rear // Painting	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
210	Door Front Right // Smart Repair Small	N
891	Lettering Removal 15min	N
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
161	Roof // Smart Repair Medium	N
282	Bumper Rear / Trim Center / Replace	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y


Damage Pictures




Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Wheel Two Tone Rear Right // Repair-scratch






Front Bonnet // Polish-scratch

Door Front Left // Smart Repair Small-scratch





Roof // Smart Repair Medium-dent










Bumper Rear / Trim Center / Replace-scratch + dent








Rocker Panel Left // Smart Repair Medium-scratch + dent





Wheel Two Tone Front Right // Repair-scratch




Bumper Front / Trim Left / Replace-scratch





Bumper Front // Painting-scratch






Lettering Removal 15min-






Bumper Rear // Painting-scratch




Door Front Right // Smart Repair Small-scratch






Wing Rear Right // Repair & Painting-scratch + dent






Door Rear Right // Repair & Painting-scratch + dent