TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48493515
Order No. / Reference: 27049068
Inspection date: 22 Oct 2026

Manufacturer: Opel	Model: Insignia Sports Tourer 2.0 Diesel Aut. Ultimate
VIN: W0VZS8GP7N1048136	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Insignia Sports Tourer 2.0 Diesel Aut. Ultimate	
Vehicle Identification number	W0VZS8GP7N1048136
Mileage (Read)	40,732 km
First registration	15 Aug 2023
Number of holders	1
Next periodical technical inspection	08/2028
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	128 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Jade Weiß (Uni)
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Anthracite
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	78 %
Last service on / at	08/2026 at 38,531 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ360197
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	1844 / AMC 00298		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,245 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	245/45 R18 100V	Winter tyres on Light alloy	Bridgestone	7mm / 7mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/35 R20 95V	Summer tyres on Light alloy	Continental	4mm / 4mm
2)	245/35 R20 95V	Summer tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments: Storage compartment in the center console; Pockets in the front doors, suitable for 1.5-liter beverage bottles; Pockets in the rear doors, suitable for 1-liter beverage bottles; Cup holder in the center console; Illuminated glove compartment
- Ambient lighting on dashboard and doors (front)
- Electrically adjustable and heated exterior mirrors for driver and passenger side - manually foldable
- third brake light
- Diesel particulate filter
- Electronic brake force distribution (EBD)
- Chassis: FlexRide Premium chassis. Innovative chassis system with adaptive driving style recognition and three selectable driving modes: Standard, Sport (personalizable) and Tour, including: - Electronic damper control - Speed-sensitive power steering - Networking of all driving dynamics systems
- Speed controller
- Transmission: 8-speed automatic transmission
- rear window wiper
- Child safety lock in the rear doors, manual
- Automatic climate control with two zones and separate temperature control for driver and front passenger, including: - Manual recirculation mode - Particle/activated carbon filter - Automatic air distribution - Sun sensor - Humidity sensor
- LED daytime running lights including LED indicators, front and LED taillights
- Center armrest, front
- Package: Easy-Access - Keyless locking and starting system (Keyless Open & Start) - Sensor-controlled electric tailgate - Stainless steel loading sill protector
- Package: Innovations 1 - IntelliLux LED Pixel Light - Adaptive LED Matrix Headlights: City Light, Highway Light, Country Road Light, Static Cornering Light, Turning Light, Parking Light, High Beam: Traffic-dependent dimming taking into account preceding and oncoming traffic, Automatic Headlight Range Control - Traffic Sign Assist
- Quickheat rapid heating system
- Radio: Digital radio reception DAB+
- Radio: Multimedia Navi Pro with 8" color touchscreen display. Multimedia radio. Voice control for audio, telephone, and navigation. Navigation system with SD card storage. Road map for over 30 European countries. Map display in 2D and 3D. Dynamic route guidance via map and/or arrow display and voice prompts. Connected navigation services. Predictive navigation. Online map updates. Real-time traffic information. 8" driver information display. 2 USB ports. Steering wheel controls. Apple CarPlay and Android Auto.
- Tire pressure display - with tire pressure warning - direct system with automatic calibration after wheel change
- Power steering - speed-dependent
- Airbag: Front airbags (multi-stage) and side airbags, driver and front passenger; front and side airbags, front passenger, deactivatable
- Airbag: Front and rear outer head airbags
- Aluminum sports pedals
- Anti-lock braking system (ABS) with cornering brake control (CBC) and brake assist
- Hill Start Assist
- Roof rails, silver anodized
- Tachometer
- Electronic Stability Program (ESP Plus)
- Electric windows front and rear - with one-touch function and anti-pinch protection
- Front collision warning system with pedestrian detection and automatic emergency braking
- Pedestrian protection including active hood
- Extendable luggage compartment cover with comfort operation
- GS Line Interior Equipment - GS Line Sport Leather Steering Wheel, Heated - Aluminum - Sport Pedals - Black Headliner
- Front headrests - height adjustable
- Rear headrests (3 pieces) - height adjustable
- Paintwork: Solid special color Snow White
- LED headlights - automatic headlight range control
- LED fog lights
- Steering column adjustable in height and length
- Illuminated makeup mirrors in both sun visors
- Package: Charging (Sports Tourer) - Wireless Charging (wireless charging of smartphones in the center console) - 2 USB ports, rear center console (charging function) - 12V socket, in the trunk
- Package: Sound - Noise-reducing, laminated side windows (front) - Bose sound system
- Electric parking brake including 12-volt socket
- Parkpilot, front and rear parking aid with acoustic warning signal when parking forwards and backwards.
- Upholstery: Siena leather interior, perforated, black, including Seat Comfort Package 2 - Ergonomic active seats (AGR), driver and front passenger - Leather upholstery (leather seat contact surfaces; 2nd row center seat, headrests, door panels and outer seat bolsters in leatherette) - Multi-stage heated seats, driver and front passenger - Rear center armrest with cupholder and pass-through from the luggage compartment - Rear seat backrest with FlexFold function, 40:20:40 split-folding - Door sill trims with OPEL lettering, front - Seat Comfort Package 2
- Radio accessories: 2 USB ports, rear center console
- Tire repair kit including tire sealant and 12-volt compressor (without jack)
- Wheels: 8.5 J x 20 alloy wheels in a 5-twin-spoke design - BiColor with 245/35 R 20 tires
- Visibility features: Rain sensor, front interior mirror with automatic dimming, automatic headlights with tunnel detection, high beam assist

- Seat belts: Three-point seat belts in all seats - belt force limiters and belt tensioners in the front and on the outer rear seats - warning tone and light for unfastened seat belts in all seats
- Lane Keeping Assist warns the driver if they unintentionally leave their lane (between 60 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.
- Pre-installation for child seat mounting system "ISOFIX" at the rear
- Thermal insulation glazing, green tinted
- Second folding ignition key
- Solar Protect heat-insulating glazing in the rear, heavily tinted.
- Start/Stop system, reinforced starter, high-performance battery, brake energy recuperation, switch to deactivate the start/stop function
- Bumpers painted in body color
- Traction Control (TC) Plus - Traction control with engine and brake intervention
- Immobiliser
- Central locking with remote control and interior switches

Extra equipment

- Airbag: Side airbags, rear outer; Seat belt warning for unfastened seat belts, rear (child seat attachment system remains activated)
- Package: Innovations 2 (Sports Tourer automatic transmission) Head-up display Adaptive cruise control (Generation 3) Stop & Go function Forward collision alert with pedestrian detection and automatic emergency braking, active from 4 km/h, range 150 m. In case of a collision risk, the braking system is prepared and, if necessary, emergency braking/automatic emergency braking is initiated Lane keeping assist and lane departure warning Keyless entry and start Keyless Open & Start Sensor-controlled electric tailgate Stainless steel loading sill protector
- Park & Go with digital reversing camera - Digital reversing camera - Reversing assistant - Lane change assistant - Blind spot warning in both exterior mirrors
- Wheels: Additional set of winter tires on 17" alloy wheels 225/55 R 17
- Swiveling trailer hitch including trailer stability program
- High Gloss Black Exterior Equipment (Sports Tourer) - Window trim strips in high-gloss black, all around the sides - Radiator grille frame in high-gloss black - Fog light surrounds in high-gloss black - Roof rails in high-gloss black
- Package: Winter 4 Heated seats front/rear Heated leather steering wheel Seat Comfort Equipment 2 (Driver/passenger seats 8-way electrically adjustable length, height, backrest and seat tilt, electro-pneumatic lumbar support, height and tilt adjustable headrest, pocket on front seat back, memory function for driver's seat and exterior mirrors, extendable upper bolsters Electro-pneumatic adjustment of driver's side bolsters, massage function for driver, seat ventilation, exterior mirrors with ambient lighting, electrically adjustable, heated and folding) Charging Package

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Wing mirror - right side	Cap - Scratch(es) - Smart repair
2	Rear bumper	Rear bumper - Scratch(es) - Smart repair
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
4	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
5	Body	Body - Glued / labelled - De-glue / neutralise
6	2nd wheel set	1 alloy rim - Scratch(es) - Replace
7	2nd wheel set	1 alloy rim - Scratch(es) - Replace
8	2nd wheel set	1 alloy rim - Scratch(es) - Replace

Wear and tear

No.	Component group	Description
1	Vehicle glazing	Windscreen - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Rear of vehicle - Adapter cable trailer
Rear of vehicle - Trailer hitch - removable

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Professionally repaired, Invoice of repair done Non-existent, from 8 Dec 2025	5.908,99 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents



Figure 17: Additional tyres




Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair




Damage 1: Wing mirror - right side: Cap - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value




Damage 4: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 5: Body: Body - Glued / labelled - De-glue / neutralise



Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 6: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 7: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 7: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 8: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Damage 8: 2nd wheel set: 1 alloy rim - Scratch(es) - Replace



Wear and tear 1: Vehicle glazing: Windscreen - Stone chips - No deduction