TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48476106
Order No. / Reference: 27216113
Inspection date: 30 Oct 2026

Manufacturer: Ford	Model: Kuga 2.5 Duratec PHEV COOL&CONNECT
VIN: WF0FXXWPMHPD64219	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Kuga 2.5 Duratec PHEV COOL&CONNECT	
Vehicle Identification number	WF0FXXWPMHPD64219
Mileage (Read)	108,956 km
First registration	13 Jul 2023
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	2,488 ccm / 4
Power	112 kW
Gearbox / Number of gears	Automatic / 1
Type of drive	Front drive
Type of vehicle	Multipurpose vehicle
Colour / colour code	Frozen White
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black

Vehicle details

Maintenance booklet / proof	digital evidence / incomplete	**Next maintenance in**	20 %
Last service on / at	07/2025 at 66,284 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GT886446
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8566 / BTM 00020		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,320 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/65 R17 106V	All-season tyres on Light alloy	Michelin	6mm / 6mm
2)	225/65 R17 106V	All-season tyres on Light alloy	Michelin	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2027		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Acoustic Vehicle Alerting System (AVAS)
- Passenger airbag deactivation
- Tires: Tire repair kit (maximum speed 80 km/h when used)
- third brake light
- Roof spoiler (painted in car color)
- Tachometer
- Driver information system with on-board computer - color
- Selective driving mode switch (5 driving modes to choose from: Normal, Sport, Eco, Slippery and Unpaved Roads)
- Electric parking brake with auto hold function
- Ford Easy Fuel (Ford Easy Fuel comfort refueling system (Eliminates the need for a separate internal fuel cap and prevents misfueling by detecting the size difference between petrol and diesel nozzles. The filler neck only opens when the correct fuel is used.)
- Luggage compartment cover, roller blind, removable
- Cruise control
- Illuminated glove compartment
- Heated rear window
- Intelligent Protection System (IPS) (front airbag for driver and front passenger - front and rear head and shoulder airbags - side airbag for driver and front passenger - seat belt tensioners and force limiters in the front and on the outer seats of the 2nd row - 3-point seat belts in all seats, height-adjustable in the front - warning system for unfastened driver and front passenger seat belts)
- LED taillights
- Steering wheel: Steering wheel, 3-spoke design, in Sensico synthetic leather
- MyKey key system (individually programmable second key)
- Navigation system: Ford navigation system incl. Ford SYNC 3 (AppLink, Android Auto, Apple CarPlay - 8" touchscreen (20.3cm screen diagonal) - DAB/DAB+ radio reception (Digital Audio Broadcasting) - 6 speakers - Steering wheel controls - Bluetooth® hands-free system and audio streaming - 2 USB ports - Voice control for audio and telephone - SMS text-to-speech function - Road map for Europe)
- Tire Pressure Monitoring System (TPMS)
- Projection lens headlights with LED daytime running lights
- Headlights with delayed shut-off
- Power steering (electro-mechanical, speed-dependent (EPAS - Electric Power Assisted Steering))
- Seats: Rear bench seat, sliding, with split-folding backrest
- Seats: Front sports seats with integrated headrests
- Sun visor on driver and passenger side
- Carpet floor mats in the front
- Immobiliser
- Anti-lock braking system
- Tires: 7 J x 17 alloy wheels (4) in 5-spoke design (with 225/65 R 17 tires)
- Fabric headliner
- Dual exhaust system
- Electronic Stability Program (ESP) (with hill start assist, traction control and emergency brake assist)
- Lane keeping assist including lane keeping assist
- Electric front and rear windows (with quick-down function including all-around closing function)
- Ford EcoCoach (shows the efficiency of current driving behavior)
- FordPower start function (keyless start)
- FordPass Connect (including eCall, live traffic information and Wi-Fi hotspot)
- Luggage compartment lighting
- Transmission: continuously variable automatic transmission (CVT)
- rear window wiper
- ISOFIX mounts including top tether attachment points on the outer seats of the 2nd row.
- Air conditioning with automatic temperature control (separately adjustable for driver and passenger side (2-zone automatic climate control))
- Front and rear headrests (5) height adjustable
- Charging cable (for household sockets and public charging stations)
- Steering column, adjustable in height and reach
- Front center console with integrated armrest (2 front cup holders)
- Fog light
- Emergency brake light, pulsating illumination of the brake lights during hard braking
- Front and rear parking pilot system
- Upholstery: Cloth
- Post-Collision Assist
- Pre-Collision Assist (including forward alert system (FA) with pedestrian and bicycle detection - active from approx. 5 km/h to 130 km/h, pedestrian and bicycle detection up to approx. 80 km/h.)
- Headlight assistant with day/night sensor
- Seats: Passenger seat, 4-way manually adjustable
- Seats: Driver's seat, 8-way manually adjustable, including adjustable lumbar support
- Seats: Front seats, individually and variably heated
- Power outlet: 12-volt connection in the luggage compartment
- Central locking with remote control and remote luggage compartment release

Extra equipment

- Tires: 4 all-season tires 225/65 R 17 102V
- Safety partition net (including attachment points behind the first and second rows of seats)
- Paint finish: Solid color, special color

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance (Wartungsnachweis unvollständig, letzter Nachweis fehlt) - No evidence - No deduction
2	Door - front left side	Door edge - Scratch(es) - Smart repair
3	Door - rear right side	Door - dent(s) - Smooth repair work
4	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
5	Boot lid / rear door	Boot lid - dent(s) - Smooth repair work
6	Exhaust system	Tail pipe - Scratched - Loss in value
7	Steering system	Steering wheel (Lackablösung Blende Mitte) - Paint defect - Loss in value
8	Rear bumper	Rear bumper (unpainted) - Scratch(es) - Loss in value
9	Rear bumper	Spoiler - Scratched - Replace
10	Vehicle glazing	Windscreen (Mit Rissbildung) - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	Front bumper	Front bumper - Stone chips - No deduction
2	Door - rear right side	Door handle - outside - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
Engine - Engine cover

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents




Figure 16: Documents




Figure 17: Documents



Figure 18: Navigation



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.



Figure 37: Misc.






Figure 38: Misc.



Figure 39: Misc.



Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 2: Door - front left side: Door edge - Scratch(es) - Smart repair




Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 3: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work




Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 5: Boot lid / rear door: Boot lid - dent(s) - Smooth repair work



Damage 6: Exhaust system: Tail pipe - Scratched - Loss in value



Damage 6: Exhaust system: Tail pipe - Scratched - Loss in value



Damage 6: Exhaust system: Tail pipe - Scratched - Loss in value



Damage 6: Exhaust system: Tail pipe - Scratched - Loss in value



Damage 7: Steering system: Steering wheel (Lackablösung Blende Mitte) - Paint defect - Loss in value



Damage 7: Steering system: Steering wheel (Lackablösung Blende Mitte) - Paint defect - Loss in value



Damage 7: Steering system: Steering wheel (Lackablösung Blende Mitte) - Paint defect - Loss in value



Damage 7: Steering system: Steering wheel (Lackablösung Blende Mitte) - Paint defect - Loss in value



Damage 8: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 8: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 8: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 8: Rear bumper: Rear bumper (unpainted) - Scratch(es) - Loss in value



Damage 9: Rear bumper: Spoiler - Scratched - Replace




Damage 9: Rear bumper: Spoiler - Scratched - Replace




Damage 9: Rear bumper: Spoiler - Scratched - Replace



Damage 9: Rear bumper: Spoiler - Scratched - Replace



Damage 10: Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - Replace



Damage 10: Vehicle glazing: Windscreen (Mit Rissbildung) - Stone chips - Replace



Wear and tear 1: Front bumper: Front bumper - Stone chips - No deduction



Wear and tear 2: Door - rear right side: Door handle - outside - Scratch(es) - No deduction



Missing part 1: Engine: Engine cover - Missing - Replace