Iveco DAILY 35S16V 2.3 410L H3, Double Cabin

ZCFC735B605364956 · lot Costs



VEHICLE DATA & SPECIFICATIONS

VIN	zcfc735b605364956
First Registration	8/10/2020
Country of Origin	Netherlands
Mileage	171,372 km
Iveco DAILY 35S16V 2.3 410L ...	Lot: 15Veghel, NetherlandsFirst registration: August 10, 2020Mileage: 171,372 km157 hp
Front / Right	Back / Left
Place your bid	Auto-bid
Transport costs	Vehicle location:Veghel, NetherlandsCalculate delivery time and price
Vehicle location	Veghel, Netherlands
Amount of Axles	2
Type of suspension axle 2	parabolic
Tyre condition Axle 1 Left (MM)	6 mm
Tyre condition Axle 1 Right (M...	5 mm
Tyre condition Axle 2 Left (MM)	2 mm
Tyre condition Axle 2 Right (M...	2 mm
Tyre size Axle 1	225/65 R16
Tyre Size Axle 2	225/65 R16
Undercarriage	Wheeled
Wheelbase	413 cm
Door opening height	180 cm
Door opening width	153 cm


VEHICLE DATA & SPECIFICATIONS - CONTINUED

Inner height	194 cm
Inner length	379 cm
Inner width	183 cm
Space between wheelarches	135 cm
Door angle	270 degrees
Floor height	66 cm
Material floor	Wood
Mileage	171372 km
Power type	Diesel
Registration Date	2020-08-10
Request Transaction Id	3d06a4f5-80c2-498e-b69a-2d803fb8e636
VIN / Serial Number/ Chassisn...	ZCFC735B605364956
Brand	Iveco
Model	Daily
Product Group (Tax)	Closed Van
Vehicle Height (cm)	264 cm
Vehicle Length (cm)	745 cm
Vehicle Width (cm)	202 cm
Truck ID	70342173
Lot	15
First registration	August 10, 2020
November 10, 2026 at 02	07 PM

Damage & Condition

All known damages are listed and shown in photos for full transparency.

2 damages reported | Worst: Moderate



Interior — Moderate

Electrical

Check engine light!




Multiple — Minor

Cosmetic Damage

.



Front / Right



Back / Left


225/65R16C






















DAILY







TRACKING ALARM




11°C
03 Jan
Motorstoring
maak afspraak
bij werkplaats
AdBlue 90%
171376 km
Trip A
0 km
km/h
rpm
x100


ESI[tronic]
BOSCH
Voertuiginfo
Diagnose
Zoeken
Onderhoud
Handboeken
Schakelschema's
Motorregeling / Motorregeling EDC 17C49 V2
Foutgeheugen
Fout selecteren. Verdere informatie
over de gekozen fout met Verder
Aantal fouten 9
6D0002 Koelmiddeldruksensor
Gegevens ongeldig/onregelm./foutief
811010 Omzettingssnelheid katalysator (syst.1)
Data geldig maar bov. ber., mid. st.
190D0C Dynamo
Component defect
E10611 AdBlue-Systeem: waarschuwingstrap 1
Data geld. maar ond.ber.,laagste st.
7D1400 AdBlue-doseersyst: modus
Kalibratie buiten geldig gebied
68040F Status variabele turbinegeometrie
Data geld. maar bov.ber.,laagste st.
E1060B AdBlue-Systeem: waarschuwingstrap 2
Component defect
Afbreken
Terug
Opslaan
Wissen
Search


IVECO






IVECO




km/h






IVECO
IVECO SPA
3500 kg
1-
2-
kg















DAILY








BOSCH
Fout selecteren. Verdere informatie
over de gekozen fout met Verder
Aantal fouten : 9
6D0002 Koelmiddeldruksensor
Gegevens ongeldig/onregelm./foutief
811D10 Omzettingseenheid katalysator (syst.1)
Data geldig maar bov. ber., mid. st.
190D0C Dynamo
Component defect
E10B11 AdBlue-Systeem: waarschuwingstrap 1
Data geld. maar ond.ber.,laagste st.
7D1400 AdBlue-doseersyst: modus
Kalibratie buiten geldig gebied
68040F Status variabele turbinegeometrie
Data geld. maar bov.ber.,laagste st.
E10B0B AdBlue-Systeem: waarschuwingstrap 2
Component defect