TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48031113
Order No. / Reference: 27150219
Inspection date: 9 Oct 2026

Manufacturer: CUPRA	Model: Born 150kW/58kWh
VIN: VSSZZZK12PP032732	





Vehicle details

Manufacturer / Type / Model / Equipment	
CUPRA Born 150kW/58kWh	
Vehicle Identification number	VSSZZZK12PP032732
Mileage (Read)	33,771 km
First registration	31 Jul 2023
Number of holders	1
Fuel type	Electric
Power	70 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Rear drive
Type of vehicle	Car hatchback
Colour / colour code	Glacial White Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	338 Tag(e)
Last service on / at	09/2025 at 17,770 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ516264
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	7593 / ASO 00015		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,280 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/50 R19 93T	Summer tires (with run-flat tires) on Light alloy	Continental	5mm / 5mm
2)	215/50 R19 93T	Summer tires (with run-flat tires) on Light alloy	Continental	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R18 95T	Winter tyres on Light alloy	Bridgestone	6mm / 6mm
2)	215/55 R18 95T	Winter tyres on Light alloy	Bridgestone	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag: Airbag for driver and front passenger
- Airbag: Head airbag system, front and rear
- Exterior mirrors: aspherical on driver's side, convex on passenger's side
- Battery warranty 8 years, maximum 160,000 km
- C-pillar with CUPRA design element
- CUPRA Drive Profile
- CUPRA lettering on tailgate
- Black headliner
- Electronic parking brake including auto-hold function
- Electric window regulator with anti-pinch protection and one-touch function
- Transmission: 1-speed automatic
- Rear spoiler in car color
- Interior mirror automatically dimming
- Keyless Go (engine start/stop button)
- Air conditioning: Climatronic with electronic temperature control
- Steering wheel: CUPRA Supersport multifunction steering wheel in leather
- Center console with integrated storage compartment and cup holders
- Progressive steering
- Rain sensor
- Seat belts - front and rear
- Seats: CUPRA sports bucket seats in the front
- Seats: Driver's seat with height adjustment
- Sport pedals in aluminum look
- 12V socket in the luggage compartment
- Ultrasonic parking aid front and rear
- Electronic immobilizer
- thermal insulation glazing
- Airbag: Passenger airbag deactivation
- Ambient lighting in the front door panel
- Electrically adjustable, folding and heated exterior mirrors
- Exterior mirror housing in Liquid Grey
- third brake light
- CCS charging socket
- CUPRA e-Sound
- CUPRA side skirts in Liquid Grey
- decorative elements
- Electronic Stability Control (ESC)
- Luggage compartment lighting
- Speed limiter
- rear window wiper
- Rear bumper and diffuser in body color
- ISOFIX child seat restraint system, in the 2nd row of seats left and right as well as on the front passenger seat
- Headrests, 2 front
- Headrests, 3 rear
- Lights: Full headlights
- front center armrest
- Fatigue detection
- Emergency call service
- Radio: Radio, navigation and multimedia systems
- Tire pressure monitoring system
- Seats: 3 rear seats, rear seat backrest asymmetrically split and foldable
- Sun visors with illuminated makeup mirror
- Lane departure warning system
- Front bumper in body color
- Front Assist area monitoring system with City Emergency Braking function

Extra equipment

- Charge 32A (Charging cable Mode 3, Type 2 / 32A (Enables single-phase charging with up to 7.2 kW))
- Package: Cargo Pack (Power cable for household socket (charging cable Mode 2, Type 2 / 10A) - Variable luggage compartment floor)
- Privacy Glass: Side windows from the 2nd row of seats and rear window are dark tinted.
- Radio accessories: Beats Audio sound system (9 speakers, digital multi-channel amplifier, subwoofer, 395 watts total power)
- Tool kit in conjunction with 18-20" summer tires / 19" all-season tires (wheel wrench, towing eye, adapter for the anti-theft wheel bolt, hook for removing the wheel covers, clip for wheel bolt caps)
- Paint finish: Metallic
- Package: Below Zero Pack (Heated front seats - Heated front windshield washer nozzles)
- Package: Pilot M+ Pack (Adaptive Cruise Control ACC with predictive speed control - CUPRA CONNECT PLUS - prepared for activation of the Online Infotainment service package - High Beam Assist - Traffic Sign Recognition - Navigation system with 12" color touchscreen - Rearview camera)
- Wheels: TYPHOON 7.5J x 19" alloy wheels, black/silver, diamond-cut finish (tires 215/50 R 19 with self-sealing function)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Smart repair
2	Wheel / tyres	Alloy rim - front right side - Scratched - Loss in value

Wear and tear

No.	Component group	Description
1	Trim / covers	Boot lid - interior trim - Scratch(es) - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Fahrzeugmodellbezeichnung laut Rechnung: "CUPRA Born 150kW/58kWh".

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Smart repair



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value



Damage 2: Wheel / tyres: Alloy rim - front right side - Scratched - Loss in value