BMW

BMW 1 BERLINE (F40)(2019->) 116D ADVANTAGE MOTEUR 1,5 LITRE(S) - 85 KW 12V TURBODIESEL 5 PORTES

VIN: WBA7M710707K82359



Description

Registration number 2BUZ929	**Registration date** 01/04/2022	**Odometer** 211530 km
Color PHYTONICBLAU METALLIC	**Year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
CO2 139	**Engine displacement** 1496	**Gearbox type** Manual
Engine type Combustion	**Fuel Type** Diesel	**Number of gears** 6
Drivetrain Front Wheel Drive (FWD)	**Max power** 85 KW	

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Vehicle Equipments

Standard

armrest front	Advantage	airbag driver side/passenger side
airbag passenger side deactivatable	sidebag front	generator 150 A
immobilizer	battery 70 Ah	BMW Live cockpit
BMW Live cockpit Professional	start-stop button	transmission 6-speed
body: 5-door	air conditioning	steering column (steering wheel) mechanic. adjustable
dynamic traction control (DTC)	tire pressure control system	radio reception digital (DAB)
electronically locking differential	power steering Servotronic	rear seat backrest split/folding
dynamic stability control (DSC) with extended scope	light and rain sensor	maintenance: vehicle with Oil service interval 25000 km / 24 months
interior equipment interior trim strips Quartz silver matte Grained	rear lights LED	diesel particulate filter
refrigerant R 1234 YF	parking brake electromechanical	windshield washer jets heated
Light-alloy rims	vehicle speed limiter	window lifter electric front + rear
engine 1,5 liter - 85 kW 12V turbo diesel catalyst	low emissions according to emission standard Euro 6d	trip computer
Equipment package: Connected	Equipment package: ConnectedDrive Services	Storage package
USB connection in rear seat area	lashing eyes cargo space sideways	Parkpilot system front and rear
Pneus 205/55 R16 ..V	trailer stabilization program (TSA)	headlight LED
headlight leveling control	cruise control with brake function	urea tank (SCR) 20,5 liter
exterior mirror electrically adjustable and heated	Isofix mounts for child seat at rear seat	floor mats velours
head airbag system rear	head airbag system front	antilock braking system (ABS)
driver assistance system: Active Guard plus (lane assist, front-end collission warning)	driver assistance system: Performance Control	driver assistance system: alertness assistant
driver assistance system: driving-experience switch	personalization system (Personal Profile)	Service system: intelligent emergency call incl. TeleServices
Service system: ConnectedDrive Services	start/stop system	warning triangle
Blue & Me (Bluetooth with voice control, USB port, MP3)	Steering AV European market (EU specific)	central locking system
heat protection glazing tinted	steering wheel (leather) with multiple function	daytime running lights LED

Optional

BMW Live cockpit Plus	active hood	model variant CO2 scope (code 1CB)
metallic paintwork	metallic paintwork Phytonic blue	interior mirror with automatic dimming
seat covers/upholstery: cloth	seat front right mechanical height-adjustable	sports seats front
driver assistance system: high-beam assistant	Service system: legally required emergency call feature	veh. without model lettering

Statement details

Inspection loc	Statement date	Inspection approval date
PARC HÖDLMAYR TONGEREN	12/10/2026	13/10/2026


Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Spare Key / -	Missing	Replace
			
002	Personal Data / -	Non Compliant	Carry out
	 		
003	Rim / Back Right Material : Aluminium alloy / Rim/Tyre diameter : 16 " / Surface : Painted	Scratched	Acceptable
			
004	Roof / - Sunroof : No	Dent	Acceptable
			
005	Bonnet / -	Scratched	Acceptable
			
006	Rear-view mirror / Left	Scratched	Acceptable
			
007	Door / Front Left	Dent	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



008	Rear windscreen / Back	Sticker	Removal



009	Tailgate / Boot door / -	Scratched	Acceptable



010	Bumper / Back Painted : Yes	Dent	Repair







011	Wing / Back Right	Scratched	Painting






012	Door sill / Back Right	Dent	Repair




013	Door / Back Right	Dent	Acceptable

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.




014	Rear-view mirror / Right	Scratched	Acceptable



015	Turning signal light / Right	Chip	Replace





Loose Items

- [x] Triangle
- [x] Rear parcel shelf
- [ ] Spare Key
- [x] First aid kit
- [x] Conformity certificate
- [x] Safety vest
- [x] Registration certificate owner
- [x] Registration certificate

Main set of tyres

Front Left	CONTINENTAL	205/55/16 Summer	3 mm
Front Right	CONTINENTAL	205/55/16 Summer	3 mm
Back Left	MICHELIN	205/55/16 Summer	3 mm
Back Right	MICHELIN	205/55/16 Summer	3 mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat


Front passenger compartment



Front right



Odometer



Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other




Other



Other




Other



Spare Key / - / Missing




Personal Data / - / Non Compliant



Personal Data / - / Non Compliant



Rim / Back Right / Scratched



Roof / - / Dent



Bonnet / - / Scratched



Rear-view mirror / Left / Scratched



Door / Front Left / Dent



Rear windscreen / Back / Sticker



Tailgate / Boot door / - / Scratched



Bumper / Back / Dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Bumper / Back / Dent



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Wing / Back Right / Scratched



Door sill / Back Right / Dent



Door sill / Back Right / Dent




Door / Back Right / Dent



Rear-view mirror / Right / Scratched



Turning signal light / Right / Chip



Turning signal light / Right / Chip

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.