TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach

Expertise

Protocol number: 48525285
Order No. / Reference: 27212191
Inspection date: 4 Nov 2026

Manufacturer: Opel	Model: Corsa-e GS
VIN: VXKUHZKW5R4240101	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Corsa-e GS	
Vehicle Identification number	VXKUHZKW5R4240101
Mileage (Read)	26,603 km
First registration	30 Oct 2024
Number of holders	1
Next periodical technical inspection	10/2027
(Report not on hand)	
Fuel type	Electric
Power	62 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	Front drive
Type of vehicle	Car hatchback
Colour / colour code	Arktis Weiß
Doors / Seats	5 / 5
Upholstery type	Alcantara / Leather
Colour of upholstery	Black-Anthracite
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	Available / complete	**Next maintenance in**	23,000 km
Last service on / at	09/2026 at 25,998 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HE012923
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	short drive on the company premises	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	2525 / AAK 00010		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	1,897 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	5mm / 5mm
2)	195/55 R16 91H	All-season tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 05/2030		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments (storage compartment in the center console, front and rear cup holders in the center console; glove compartment; storage compartment in the front doors, suitable for 1.5-liter beverage bottles; storage compartment in the rear doors, suitable for 0.5-liter beverage bottles)
- Aluminum sports pedals
- Ambient lighting in the door storage compartments, front
- Electrically adjustable and heated exterior mirrors for driver and passenger side (electrically folding - exterior mirror housing in black)
- third brake light
- Headliner, Black
- Electronic brake force distribution (EBD)
- Driver information display 7", color (fully digital)
- Electric windows front and rear (with one-touch function and anti-pinch protection)
- Pedestrian protection
- Intelligent speed control and limiter
- Transmission: Continuously variable direct drive
- Back window, heater
- rear window wiper
- Heating and ventilation system with pollen filter
- Child safety lock in the rear doors, manual
- automatic climate control
- Front headrests and 3 rear headrests, height adjustable
- Charging cable: Mode 3 charging cable (22 kW, 3-phase) for public charging, 6 meters long
- Steering wheel made of vegan synthetic leather, flattened at the bottom
- Front reading lights
- Center armrest with storage compartment in front
- Driver fatigue detection (Based on steering behavior and driving duration, it detects signs of possible driver fatigue and issues a visual and audible warning (3-stage warning).)
- OpelConnect with telematics services (Connect One: - Emergency call/breakdown call - Vehicle status and information - Route and trip information; Connect Plus: - Live Navigation (including real-time traffic information, fuel prices, POI search) - Remote Control (activating the headlights and horn, as well as locking and unlocking the vehicle remotely via the myOpel app) - e-Remote Control (remote charging and climate control via the myOpel app) - Free2Move eSolutions - e-ROUTES (navigation app) - ChatGPT (voice control))
- Adaptive brake light
- Airbag system (front airbags, driver and front passenger - side airbags, driver and front passenger - head airbags, front and rear outer (front and side airbag, front passenger, manually deactivatable))
- Active pedestrian warning tone (AVAS) (ambient noise up to a driving speed of 50 km/h)
- Anti-lock braking system (ABS) (with cornering brake control (CBC) and brake assist)
- Hill Start Assist
- On-board computer
- Roof design line, in black
- Decorative strip Silent Black/Liquid Palladium
- Electronic Stability Program Plus (ESP Plus)
- Driving modes: 3 adjustable (ECO, Normal and Sport)
- Front collision warning with automatic emergency braking and pedestrian detection (Active between 5 and 85 km/h, depending on the detected obstacle - Moving obstacle: 5-85 km/h - Stationary obstacle: 5-80 km/h - Pedestrian: 5-60 km/h. Monitors the distance to the vehicle ahead. If a collision is imminent, the braking system is prepared and, if necessary, emergency braking is initiated. At speeds below 30 km/h, the vehicle is braked to a complete stop. Above 30 km/h, the system reduces the impact speed by a maximum of 22 km/h.)
- Paintwork: Roof in contrasting black
- LED taillights
- LED headlights (LED daytime running lights - high beam assist - LED turn signals in exterior mirrors)
- Steering column adjustable in height and length
- Make-up mirror, sun visor for driver and front passenger
- myOpel App, with Astra Electric specific functions (battery charge level indicator and range monitoring - remote control of climate control and charging settings)
- Onboard charger (7.4 kW/16 A, single-phase, vehicle-integrated charging unit)
- Package: Tech Package Corsa Electric (130-degree coverage reversing camera - Park Pilot, front and rear parking aid with audiovisual warning - Blind spot warning - Electrically folding exterior mirrors)
- Electric parking brake
- Parkpilot, rear parking aid (with acoustic warning signal when reversing)
- Upholstery: Cloth
- Quickheat rapid heating system
- Radio: Digital radio reception DAB+
- Wheels: 6.5 J x 16 alloy wheels in 5-spoke diamond cut design, in high-gloss black, (195/55 R16 - low rolling resistance tires)
- Keyless Start system
- Side impact protection

- Radio: Multimedia radio with 10" color touchscreen display (automatic music recognition (title, album, artist, cover) for audio devices with USB connection, Bluetooth audio streaming, hands-free calling via Bluetooth interface, phonebook and call list display, smartphone integration via Apple CarPlay, Android Auto, voice control (e.g., navigation (Google Maps, Apple Maps), music, phone, reading and dictating text messages), 1 USB port in the center console, steering wheel controls, dual tuner, graphic equalizer, 6 speakers)
- Visibility equipment
- Seats: Driver's seat, 6-way manually adjustable (length, seat height and backrest angle)
- Seats: Front sports seats, black with white accents
- 12V power outlet in the center console, front
- Sporty-looking bumpers, front and rear
- Traction Control (TC) Plus (traction control with engine and brake intervention)
- Exterior door handles, in car color
- Ambient lighting
- Pre-installation for ISOFIX child seat mounting system (on the front passenger seat)
- Pre-installation for ISOFIX child seat mounting system (rear outer)
- Heat-insulating glazing, tinted
- Ignition keys (2) (one of which is foldable and has a radio remote control)
- Power steering (speed-dependent)
- Seat belt: Three-point seat belts in all seats (belt force limiter, front and rear outer seats; belt tensioner, front and rear outer seats; warning tone and light for unfastened seat belts, front and rear outer seats)
- Seats: Passenger seat, 4-way manually adjustable (length and backrest angle)
- Seats: Rear seat backrest split 60:40 and foldable
- Lane Keeping Assist (warning in case of unintentional lane departure (between 65 km/h and 180 km/h) via a warning light in the driver information display. The Lane Keeping Assist also alerts the driver by gently counter-steering, but does not continuously steer the vehicle.)
- Traffic sign recognition (recognition of speed limits and their cancellation, as well as display of the recognized sign in the driver information display (depending on visibility and weather conditions))
- heat pump
- Central locking with remote control

Extra equipment

- Paint finish: Solid
- Onboard charger (vehicle-integrated charging unit, 3-phase (11 kW))
- Package: Tech Package Corsa Electric GS (IntelliLux LED Matrix headlights. The IntelliLux LED Matrix headlights consist of 8 lighting cells (4 on each side) - LED fog lights - Electric parking brake - Extended driver assistance systems: - Automatic speed assist with stop function - Enhanced traffic sign recognition - Forward collision alert with automatic emergency braking and pedestrian and cyclist detection - Active lane keeping assist)
- Wheels: 6.5 J x 16 alloy wheels in 5-spoke diamond cut design, in high-gloss black (195/55 R16 - low rolling resistance tires - all-weather tires)
- Navigation system (multimedia infotainment system with 10" color touchscreen display and 7" driver information display, 3D map display for Europe and Russia, dynamic route guidance via map and/or arrow display and voice prompts, TomTom Traffic online POI search and route guidance, parking information, fuel price information, live weather, over-the-air map updates, intelligent voice control, "Hey Opel" shortcut button, 6 functions, active route suggestions, wireless charging, OpelConnect)
- Upholstery: Alcantara trim, black (seat contact surfaces and inner side bolsters in Alcantara - headrests, door panels & outer side bolsters in premium leather look - comfort driver's seat with massage function: 6-way manually adjustable (length, height, backrest angle) - electro-pneumatic lumbar support (length, height) - comfort passenger seat, 6-way manually adjustable (length, height, backrest angle) - pocket on front seat back)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	A short maneuvering and shunting exercise was carried out on the company premises.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Tyre - rear left side (nicht fahrbereit) - Broken / torn - Replace
2	Rear axle	Rear axle (wegen der beschädigten Felge) - Specify findings - Measure
3	Wheel / tyres	Alloy rim - rear left side (Materialabtrag) - Scratched - Replace

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Navigation




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.




Figure 29: Misc.



Figure 30: Misc.



Damage 1: Wheel / tyres: Tyre - rear left side (nicht fahrbereit) - Broken / torn - Replace



Damage 1: Wheel / tyres: Tyre - rear left side (nicht fahrbereit) - Broken / torn - Replace



Damage 1: Wheel / tyres: Tyre - rear left side (nicht fahrbereit) - Broken / torn - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace




Damage 3: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Niederlassung
Wolnzach
Feierabendmühle 2
85283 Wolnzach



Damage 3: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - rear left side (Materialabtrag) - Scratched - Replace