AUDI Q4 SPORTBACK E-TRON

Vehicle information

Make:	**AUDI**	License:	**2ECU317**
Gearbox:		Body color:	
Model:	**Q4 SPORTBACK E-TRON**	VIN:	**WAUZZZFZ0RP002582**
Fuel type:		Power:	**125 kW**
Version:	**BEV 55KWH 35 ATTRACTION AUTO**	First registration	**30/08/2023**
Mileage:	**82577 km**	N° of doors:	


Damage summary

Interior	2
Rear	1
Roof & others	1

Commercial pictures






























POWERED BY AVILOO

SoHSCAN

Gescande OEM-SoH*

92%

VOERTUIGGEGEVENS

Merk: Audi
Model: Q4 e-tron - 52 kWh
Kilometerstand: 82.577km
Gescande SoH*: 92%

UITLEESGEGEVENS

Datum: 30-09-2026
Uitgevoerd door: Macadam Belgium


UITVOERINGSPROTOCOL

10:42:12 SoH**SCAN** gestart
10:42:34 Data-acquisitie gestart
10:46:12 SoH**SCAN** voltooid

* Let op het volgende voor een volledige beoordeling van de veiligheid en waarde van de accu:

1. Mogelijke afwijkingen en storingen van de accu en de cellen worden niet zichtbaar met de SoHSCAN. Ze zijn eenvoudig tot op celniveau op te sporen met de AVILOO FLASH Test.
2. De gescande (uitgelezen) gezondheidstoestand (SoH) van de hoogspanningsaccu volgens de fabrikant (OEM) is de SoH waarvan het accumanagementsysteem (BMS) uitgaat. Deze kan aanzienlijk afwijken van de werkelijke SoH en AVILOO aanvaardt geen aansprakelijkheid voor de juistheid ervan.
3. De werkelijke SoH kan exact worden bepaald met de AVILOO PREMIUM Test.

CARA Approved Battery Health Check




Options according to the inspector


GPS	**Yes**

Damages

Bodywork
Damaged
Acceptable
Roof & others








Charging cable (normal)
Missing
Check
Rear



Interior
Damaged
Acceptable
Interior




Seat cover R
Stain
Cleaning
Interior





Tyres

Front Left
Summer
Aluminium
235/50/20/100/T
Hankook
4.0 mm
Front Right
Summer
Aluminium
235/50/20/100/T
Hankook
4.0 mm
Rear Left
Summer
Aluminium
255/45/20/101/T
Hankook
3.0 mm
Rear Right
Summer
Aluminium
255/45/20/101/T
Hankook
3.0 mm

Checks

Battery level	**20**	Category	**Passenger Car**
Certificate of Conformity	**Yes**	Compressor	**N/A**
Maintenance	**OK**	Number of charging cables (normal)	**0**
Number of charging cables (rapid charge)	**1**	Number of keys total	**2**
Registration Certificate Car (BE)	**Yes**	Registration Certificate Home (BE)	**No**
Repair kit	**N/A**	Reset to factory settings	**Yes, vehicle is reset to factory settings**
Type of Maintenance book	**Digital maintenance**		

Information on the content and the scope of the inspection report:

- The assessment is based on the sales standards specified by the customer.
- Acceptable usage damages according to the sales standards are not always documented in this status report.
- The specified repair methods and/or resulting repair times have been determined, taking into account modern industrial repair methods.
- The purchasing dealer should assess individual repair costs.
- The inspection was carried out in a non-disassembly condition. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.