Peugeot

VIN: VR3UDYHSKNJ720494



Description

Registration number 2CMB118	**First registration date** 12/09/2022	**Odometer** 86148 km
Color PEINTURE GRIS PLATINIUM/TYPE HABILLAGE EXT METALLISEE VERNIS	**Model year** 2020	**Upholstery** -
Number of doors 5	**Number of seats** 5	**Generation** -
CO2 118	**Engine displacement** 1499	**Gearbox type** Manual
Engine type Combustion	**Number of gears** 6	**Drivetrain** Front Wheel Drive (FWD)
Max power 81 KW		

Vehicle Equipments

Automatic headlights	Cruise control	Electrically foldable door mirrors
Climate control	Alloy wheel rims	SATNAV
Rain-sensitive wipers	Rear sensors	Front sensors

Statement details

Inspection loc PARC HÖDLMAYR TONGEREN	**Statement date** 21/10/2026	**Inspection approval date** 22/10/2026

Control

Detected issues

Engine / Sound	✓ Ok	Vehicle leak proofness	✓ Ok
Exhaust / Clarity	✓ Ok		

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Defects & corrections

#	Element	Defect	Correction
001	Exterior complete / - [1]	Hail dent	Repair



002	Bumper moulding / Back Painted : Yes	Scratched	Acceptable



003	Door sill / Front Right	Scratched	Acceptable



004	Bumper / Back Painted : No	Scratched	Acceptable



[1] + - 515 deukjes <25mm +- 10 deukjes >25mm

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Loose Items

- [x] Remote key
- [x] Triangle
- [x] User manual
- [x] Registration certificate
- [x] Compressor tyre repair kit
- [x] First aid kit
- [x] Refill tyre repair kit
- [x] Spare Key
- [x] Document holder
- [x] Registration certificate owner
- [x] Conformity certificate
- [x] Safety vest

Main set of tyres

Front Left	FULDA	215/65/16 Summer	6 mm
Front Right	FULDA	215/65/16 Summer	6 mm
Back Left	FULDA	215/65/16 Summer	6 mm
Back Right	FULDA	215/65/16 Summer	6 mm

Comments

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.

Pictures


Front left


Rear left


Boot opened


Rear right


Rear passenger compartment


Dashboard from rear seat



Front passenger compartment


Front right


Odometer


Navigation


Spare Tyre




Vin


All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Other



Other



Other



Other



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent




Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent



Exterior complete / - / Hail dent

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.



Bumper moulding / Back / Scratched



Door sill / Front Right / Scratched



Bumper / Back / Scratched

All amounts are expressed in values excluding VAT.
This inspection report may contain personal data under GDPR (EU 2016/679). Such data is processed solely to manage vehicle returns, assess condition, and handle related costs. Access is restricted to authorised group entities, relevant service providers, and business customers as required. Any other use or disclosure must comply with data protection laws, and sharing with unauthorised third parties is prohibited.