TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 48201592
Order No. / Reference: 26830968
Inspection date: 16 Oct 2026

Manufacturer: Volvo	Model: XC40 B4 B DKG Core
VIN: YV1XZK8V1R2206634	





Vehicle details

Manufacturer / Type / Model / Equipment	
Volvo XC40 B4 B DKG Core	
Vehicle Identification number	YV1XZK8V1R2206634
Mileage (Read)	69,679 km
First registration	26 Jun 2023
Number of holders	1
Next periodical technical inspection	06/2028
(Report on hand)	
Fuel type	Hybrid Petrol / E
Engine displacement / Cylinder	1,969 ccm / 4
Power	145 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	Front drive
Type of vehicle	SUV
Colour / colour code	Onyx Schwarz-Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	25,653 km
Last service on / at	06/2026 at 65,336 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV796923
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	9101 / BRQ 00023		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,220 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R19 103V	Winter tyres on Light alloy	Michelin	5mm / 5mm
2)	235/50 R19 103V	Winter tyres on Light alloy	Michelin	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/60 R17 102H	Winter tyres on Light alloy	Goodyear	5mm / 5mm
2)	235/60 R17 102H	Winter tyres on Light alloy	Goodyear	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 07/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Integrated, removable waste bin in the center console
- Passenger side airbag can be deactivated
- Active safety belts with belt tensioners
- Ambient lighting (Extended interior lighting with: - Ambient lighting front and rear - Exit lights front and rear - Illuminated door pockets front and rear - Illuminated decorative inserts (in dashboard and front doors) - Work light on the tailgate - Illuminated footwell front and rear - Reading lights front and rear)
- Fold-out (bag) hook on the glove compartment
- Electrically adjustable exterior mirrors
- Exterior mirror caps in car color
- Hill start assist
- third brake light
- Roof edge spoiler
- Aluminum roof rails (integrated)
- Digital Services including Google Maps navigation system (Google Services (includes Google Maps, Google Assistant, Google Play Store and unlimited data) - Volvo On Call (includes, among other things, contacting the Volvo On Call service center at the touch of a button and additional convenience services via the Volvo CarsApp) - Usage is time-limited and will be subject to charges thereafter. Further information on renewal is available from a Volvo dealer partner.)
- Chassis: Dynamically designed
- Electric windows front and rear (with auto-down and auto-up function)
- Front grille in waterfall design in high-gloss black with chrome surround
- Luggage compartment partition net
- Cup holders (two) in the center console
- Hooks for carrier bags in the luggage compartment (two on each side)
- rear window wiper
- Interior lighting (welcome lights, headliner lighting, luggage compartment lighting, front reading lights)
- ISOFIX mounting for the outer rear seats
- Keyless Start (electronic engine start system)
- Child safety lock for the rear doors (electric)
- Automatic climate control with 2-zone temperature control (including separate temperature control for driver and front passenger, automatic blower control and air distribution including CleanZone air quality system with activated carbon filter)
- LED headlights "Thor's Hammer" (with high beam assist and integrated LED daytime running lights)
- Steering wheel: Sports steering wheel
- Rear center armrest with two integrated cup holders
- Emergency brake lights (brake lights flash rapidly during heavy deceleration; hazard warning lights are automatically activated below 10 km/h)
- Electric parking brake
- ABS - Anti-lock Braking System
- Airbags (airbags for driver and front passenger with two-stage deployment system - knee airbag for driver - side airbags for driver and front passenger - head/shoulder airbags for all occupants)
- Android infotainment system (9" touchscreen (22.9 cm diagonal) - Bluetooth hands-free system incl. audio streaming - Digital vehicle owner's manual - Digital radio reception (DAB+))
- Electrically folding exterior mirrors
- Heated exterior mirrors and rear window
- Hill descent control
- LED turn signals integrated into the exterior mirrors
- City Safety (emergency braking system with detection of vehicles, cyclists, pedestrians and large animals, including intersection braking assistant)
- Second generation digital instrumentation (12.3" full graphic display (31.2 cm diagonal) with two variable round instruments and information display (e.g. for navigation map view))
- Pass-through hatch behind the center armrest in the rear
- Rear parking assist with automatic braking intervention (rear)
- Electronic differential lock
- Electronic stability control
- Foldable cargo floor with fastening system for carrier bags in the luggage compartment
- Automatic emergency braking (locking the vehicle after the airbags or seatbelt pretensioners have been deployed to prevent secondary accidents.)
- Transmission: 7-speed dual-clutch transmission
- Front seat belt height adjustment
- Automatic tailgate (electric)
- Heated rear window
- Interior and exterior mirrors automatically dimming
- Intelligent driver information system (delays incoming calls or vehicle information in dangerous situations)
- Keyless Drive (electronic access system) with sensor-controlled tailgate, illuminated door handles and puddle lights
- Comfort opening/closing of the side windows via radio remote control
- Rear headrests fixed
- Front headrests
- Paint finish: Solid
- Steering wheel adjustable for height and reach
- Steering wheel: Multifunction buttons on the steering wheel
- Illuminated makeup mirror for driver and front passenger
- Front center armrest with integrated storage compartment
- Optical underride protection front and rear in high-gloss silver
- Otto particulate filter
- Upholstery: Textile (Rivel Chine) (incl. rear center armrest - aluminum inlay: Urban Grid - headliner: anthracite)
- Radio accessories: Two USB-C ports in the front center console
- Rain sensor

- Radio: Audio system High Performance Sound (250 Watt power - 8 speakers - Air Woofer Technology)
- Radio accessories: Two USB-C ports on the back of the center console
- Tire pressure monitoring system (with tire-specific pressure loss warning)
- Wheels: 18" alloy wheels, 5-V-spoke design (7.5 J x 18" with all-season tires 235/55 R18, tire category A)
- Wheels: Tire sealant (Incl. 12-volt compressor, maximum speed 80 km/h)
- Safety Assistance (Automatic emergency braking system with detection of vehicles, cyclists, pedestrians and large animals including intersection braking assistant and emergency braking assistant for oncoming traffic - Connected Safety - Driver Alert - Attention warning - Variable speed limiter - Cruise control - Lane Keeping Aid (LKA) - Active lane keeping assistant - Oncoming Lane Mitigation - Ready to Drive notification - Road Edge Detection - Road Sign Information (RSI) - Traffic sign recognition)
- Seats: Whiplash protection system WHIPS (including immersion protection on all seats and energy-absorbing seat cushions in the front)
- Phone: Inductive smartphone charging system (Wirelessly charges smartphones that support the QI standard on a charging pad)
- Lashing eyes (four) in the luggage compartment
- Warning tone/indicator when seat belts are not fastened (for all seats)
- Run-off Road Protection (preventive protection system in case of unintentional leaving the road or impending rollovers including emergency call via Volvo On Call and door unlocking)
- Rear view camera
- Rear seats can be folded down in a 40/60 split or completely.
- Side window trim in black (bottom)
- Speed-sensitive power steering
- Seats: Passenger seat adjustable in height and length
- Seats: Adjustable (manual) leg rest for driver and front passenger seats
- Seats: Driver's seat height and length adjustable including tilt adjustment
- Seats: Lumbar support (4-way electrically adjustable) for driver and front passenger seats
- Start/Stop technology
- 12-volt power outlet in the luggage compartment
- 12-volt socket at the front
- Textile floor mats front and rear
- First aid kit and warning triangle
- Glazing: Colored glazing
- Preparation for Trailer Stability Assist (TSA)
- Immobiliser
- Central locking with two remote controls and integrated emergency keys (including automatic locking of the doors while driving (can be deactivated))

Extra equipment

- Paint finish: Metallic paint
- Package: Winter Package (front seat heating - steering wheel heating)
- Wheels: 19" alloy wheels, 5-Y-spoke design, diamond cut/matt graphite look (7.5 Jx 19" with all-season tires 235/50 R19, tire category A)
- Package: Parking Assistance (Mild Hybrid) (Front and rear parking aid with automatic braking intervention (rear))
- Upholstery: Leather/imitation leather (incl. rear center armrest - real wood inlay: Drift Wood - headliner: Light Beige)
- Glazing: Side and rear windows tinted (from the B-pillar back)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
2	Wheel / tyres	Alloy rim - rear right side - Scratched - Replace
3	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
4	Front bumper	Front bumper - Stone chips - Paint
5	Door - front right side	Door (+ Delle) - Scratch(es) - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body - Scratch(es) - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear



Figure 7: Instrument cluster




Figure 8: Instrument panel



Figure 9: Cargo area



Figure 10: VIN




Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres




Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Damage 1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 1: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 2: Wheel / tyres: Alloy rim - rear right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 3: Wheel / tyres: Alloy rim - front right side - Scratched - Replace



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint




Damage 4: Front bumper: Front bumper - Stone chips - Paint




Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint




Damage 4: Front bumper: Front bumper - Stone chips - Paint




Damage 4: Front bumper: Front bumper - Stone chips - Paint




Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 4: Front bumper: Front bumper - Stone chips - Paint



Damage 5: Door - front right side: Door (+ Delle) - Scratch(es) - Repair and paint



Damage 5: Door - front right side: Door (+ Delle) - Scratch(es) - Repair and paint



Damage 5: Door - front right side: Door (+ Delle) - Scratch(es) - Repair and paint

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen



Damage 5: Door - front right side: Door (+ Delle) - Scratch(es) - Repair and paint