TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck

Expertise

Protocol number: 48238313
Order No. / Reference: 27110334
Inspection date: 21 Oct 2026

Manufacturer: Audi	Model: Q4 e-tron 50 Sportback quattro
VIN: WAUZZZFZ6RP006183	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi Q4 e-tron 50 Sportback quattro	
Vehicle Identification number	WAUZZZFZ6RP006183
Mileage (Read)	88,041 km
First registration	18 Sept 2023
Number of holders	1
Fuel type	Electric
Power	77 kW
Gearbox / Number of gears	Direct drive / 1
Type of drive	All-wheel drive
Type of vehicle	SUV
Colour / colour code	Stonewashed blue-metallic (D5H)
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	11 Monat(e)
Last service on / at	08/2025 at 59,860 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV406331
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZU 00037		
Emission standard	2017/1151	**fine dust sticker**	
Permitted total weight	2,715 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/50 R20 100T	Summer tires (with run-flat tires) on Light alloy	Pirelli	5mm / 5mm
2)	255/45 R20 101T	Summer tires (with run-flat tires) on Light alloy	Pirelli	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/55 R19 105T	Winter tyres on Light alloy	Continental	8mm / 8mm
2)	255/50 R19 107T	Winter tyres on Light alloy	Continental	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 09/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Equipment

- Klimaanlage

Standard equipment

- Airbag for driver and front passenger
- Acoustic vehicle warning system
- Anti-lock braking system (ABS)
- Audi connect Remote & Control for MMI plus and pro
- Audi pre sense front
- Electrically adjustable/heated exterior mirrors
- third brake light
- Decorative inlay, black tactile lacquer
- Rear parking sensors
- Chassis: Comfort chassis
- Luggage compartment lid, electrically opening and closing without sensor-controlled luggage compartment release
- rear window wiper
- Interior mirror dimming
- Automatic air conditioning
- Comfort center armrest in front
- Combo 2 charging socket (EU)
- LED taillights
- Steering wheel: Double-spoke leather steering wheel with multifunction
- On-board charger up to 11 kW (AC)
- Package: Gloss Package
- Progressive steering
- Radio: MMI Radio
- Seats: Rear seat backrest foldable
- Lane Departure Warning
- 12-volt socket
- Camera-based traffic sign recognition
- Green thermal insulation glazing
- Airbag: Front side airbags, with head airbag and front interaction airbag
- Audi connect emergency call and service
- Audi drive select
- Evasive steering assist and turning assist
- Vehicle tool kit
- Fabric headliner
- Tachometer
- Electronic Stability Control (ESC)
- front and rear floor mats
- Speed limiter with preparation for adaptive cruise control
- Transmission: 1-speed direct drive
- Interior lighting
- i-Size child seat anchors on the front passenger side, i-Size and Top Tether anchors on the outer rear seats
- Headrests (5)
- Mode 3 charging cable for public charging
- LED headlights
- Light and rain sensor
- Model name and performance/technology lettering
- Package: Advanced
- Upholstery: Fabric Index
- Wheel: Tire pressure monitoring system
- Seats: Standard front seats
- Seats: Front seats manually adjustable
- Stationary air conditioning
- First aid kit with warning triangle
- Electronic immobilizer
- Central locking

Extra equipment

- Towing device (The mechanically swiveling towing device can be conveniently locked and unlocked via a release mechanism - ball head mechanically swiveling, with electric release - ball rod and head made of forged steel - trailer stabilization via the electronic stability control (ESC) - the integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving)
- Electrically opening and closing tailgate with sensor-controlled tailgate release (The tailgate opens electrically after unlocking and can be closed again at the touch of a button. Closing the tailgate is just as easy and convenient as opening it, using the button on the inside of the tailgate, the vehicle key button, or the button in the driver's door. The soft-close function makes manual closing easier when necessary. The opening angle of the tailgate can be limited in areas with low ceilings.)
- Paint finish: Metallic
- LED headlights: Matrix LED headlights (The Matrix LED headlights with digital light signatures, dynamic light styling and dynamic turn signals. Front and rear LED headlights with the following functionalities: - digital daytime running light signature (4 light signatures selectable when stationary) - low beam - high beam - position light - dynamic turn signal - cornering light - all-weather light - maneuvering light - motorway light - automatic dynamic headlight range control. LED taillights)
- Package: Ambient Lighting Package (LED roof module front/rear - luggage compartment light right - ambient lighting of the doors front/rear - entry lights on the underside of the front doors - storage compartment in the center console front - contour lighting of the dashboard - illuminated glove compartment - footwell lighting front/rear)
- Package: Assistance Package Pro (Adaptive Cruise Control with predictive control (the set speed of the adaptive cruise control is additionally adjusted to detected speed limits and the road ahead) - Adaptive Driving Assist with Emergency Assist supports acceleration, braking, maintaining speed and distance, and lane keeping - Parking Assist Plus with parking aid and surround view display - surround view cameras)
- Package: Climate Control Package (The 3-zone automatic climate control electronically regulates the air temperature, volume, and distribution. An additional function is the sun-position-dependent control. The temperature settings for the driver and front passenger sides can be adjusted separately. Separate temperature control and air vents are available in the rear. The 3-zone automatic climate control features automatic recirculation in combination with a dust- and odor-removing cabin air filter. The comfort stationary climate control cools or heats the interior.)
- Audi connect Navigation & Infotainment plus (Navigation with Google satellite map - Online search for navigation destinations - Online voice input - Online traffic information plus - Lane-accurate motorway navigation - Highly detailed 3D city display - Online radio - Hybrid radio)
- Chassis: Sport chassis (The sport chassis, with a 15 mm lower ride height compared to the standard chassis and more dynamic spring and damper tuning, uses a McPherson strut axle with lower wishbones, shock absorbers, coil springs, subframe and stabilizer bar at the front. At the rear, a 4-link axle with separate spring and damper arrangement, shock absorbers, coil springs, subframe and stabilizer bar is used.)
- Comfort key without Safelock (The vehicle can be unlocked at all doors and the tailgate via wireless communication. The comfort key simply needs to be carried and does not need to be actively used. The vehicle can be locked again using the sensors on the door handles. The engine is started and stopped using the engine start/stop button.)
- Steering wheel: Double-spoke leather sports steering wheel, flattened at the top and bottom, with multifunction controls and paddle shifters (The double-spoke leather sports steering wheel, flattened at the top and bottom, impresses with its sporty look and feels good in the hand. The height and reach of the steering wheel are manually adjustable.)
- Navigation: MMI Navigation pro (11.6-inch MMI Navigation plus with MMI touch including Audi connect Navigation & Infotainment plus - camera-based traffic sign recognition - 10.25-inch Audi virtual cockpit plus with three display options "Classic", "Sport" and "e-tron" - Audi connect Navigation & Infotainment plus - voice control - smartphone interface connects the smartphone to the vehicle's operating system - augmented reality head-up display)
- Package: S line interior with sport seats in black leather/leatherette combination (sport seats front - leather/leatherette mono.pur 550-Kom.S embossing in black leather - steering wheel with chrome-look applications, S emblem - ambient lighting package in white light - illuminated door sills with aluminum inlays, S lettering - aluminum decorative inlays - glossy black accent surfaces - aluminum-look interior applications - stainless steel pedals - front/rear door handles - black fabric headliner - rear seat backrest split 40:20:40 or fully foldable, with center armrest.)
- Package: Comfort package (electrically adjustable, heated and folding exterior mirrors, automatically dimming on both sides, with integrated LED turn signals and curb view function for the passenger-side exterior mirror, aspherical mirror glass on the left, convex on the right, including heated windshield washer nozzles - automatically dimming, frameless interior mirror - 4-way lumbar support for the front seats - projection lights in the exterior mirrors)

- Package: S line exterior (S line bumpers with bottom line all around in contrasting paint finish Manhattan Grey Metallic - Wheels, 5-Y-spoke, 8.0 J / 9.0 J x 20, tires 235/50 / 255/45 R 20 - S line exterior differentiations with S line emblem on the fenders - Sport suspension)
- Wheel: Audi new car tire warranty (36-month term from vehicle handover to the first customer)
- Wheel: Light alloy wheels (4 pieces) in 5-Y-spoke design
- Radio accessories: SONOS Premium Sound System
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- Package: Smartphone package in conjunction with MMI Navigation pro (Audi phone box (Bluetooth, inductive charging function) - Smartphone interface - 12-volt on-board power socket and 2 USB-C ports for charging devices)
- Wheel: Tire repair kit
- Headlight cleaning system (Provides more light on the road, especially in adverse weather conditions. Cleaning with water and high pressure creates better luminosity and good visibility due to reduced scattering.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Roof	Roof - dent(s) - Smooth repair work
2	Door - front right side	Door - dent(s) - Smooth repair work
3	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
4	Wheel / tyres	Tyre - front left side - Damaged - Replace
5	Body	Wheel well - front right side (Radhausschale) - Damaged - Replace
6	Door - front left side	Door seal - Broken / torn - Replace
7	Rear bumper	Rear bumper (Inkl. Spoiler) - Damaged - Replace

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Seat - front	Seat cover - left side - Abrasion - No deduction
3	Misc.	Main inspection - No evidence - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 1 Sept 2024	697,68 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

Der beiliegende Winterradsatz ist nicht Bestandteil der Ausstattung.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN




Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents



Figure 16: Additional tyres



Figure 17: Navigation



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.




Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.





Figure 32: Misc.



Figure 33: Misc.



Damage 1: Roof: Roof - dent(s) - Smooth repair work



Damage 1: Roof: Roof - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 2: Door - front right side: Door - dent(s) - Smooth repair work



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 3: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Tyre - front left side - Damaged - Replace



Damage 4: Wheel / tyres: Tyre - front left side - Damaged - Replace




Damage 4: Wheel / tyres: Tyre - front left side - Damaged - Replace



Damage 5: Body: Wheel well - front right side (Radhausschale) - Damaged - Replace



Damage 5: Body: Wheel well - front right side (Radhausschale) - Damaged - Replace



Damage 6: Door - front left side: Door seal - Broken / torn - Replace



Damage 6: Door - front left side: Door seal - Broken / torn - Replace



Damage 7: Rear bumper: Rear bumper (Inkl. Spoiler) - Damaged - Replace



Damage 7: Rear bumper: Rear bumper (Inkl. Spoiler) - Damaged - Replace

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
Faberweg 25
73230 Kirchheim unter Teck



Damage 7: Rear bumper: Rear bumper (Inkl. Spoiler) - Damaged - Replace