MACADAM

VOLVO XC40

Vehicle information


Brand:	**VOLVO**	License plate:	**2BQT936**
Gearbox:		Body color:	
Model:	**XC40**	LEVEL:	**YV1XZBBVFN2747676**
Fuel type:		Power:	**132 kW**
Version:	**1.5 T5 PHEV Express Registration.**	First registration	**17/02/2022**
Mileage:	**176163 km**	Number of doors:	

Summary of damages


LEFT	2
Interior	3
Roof & other	1

Commercial photos































Options according to the inspector

GPS	**Yes**

Damages

Bodywork

Damaged -

Acceptable.

Roof & other



















































Ignition key
not working (well)
Acceptable
Interior




Damaged **Interior**
- Acceptable
Interior























Left rear door -


Dent(s) and scratch(es)

- Repair and paint (complete

)












Left Front Door

Scratch(es)

Paint

Left













AVG Seat Cover

Hole

E - Replace

Interior




Tires

Front Left
Summer
Aluminum
235/55/18/104/Y
Goodyear
3.0 mm
Front Right
Summer
Aluminum
235/55/18/104/Y
Goodyear
3.0 mm
Left Back
Summer
Aluminum
235/55/18/104/Y
Goodyear
3.0 mm
Rear Right
Summer
Aluminum
235/55/18/104/Y
Goodyear
4.0 mm

Controls

Category	**Private vehicle**	Registration certificate - home address section	**No**
Vehicle registration certificate	**Yes**	Certificate of Conformity	**Yes**
Compressor	**Yes**	Vehicle inspection	**OK**
Vehicle inspection	**17/02/2028**	Interview	**OK**
Interview	**over 10638 km**	Repair kit	**Yes**
Number of charging cables (220V)	**1**	Number of charging cables (fast charging)	**1**
Total number of keys	**2**	Charge level	**30**
Factory reset	**Yes, the vehicle has been reset to factory settings.**	Type of maintenance log	**Digital interview**

Information on the content and scope of the inspection report:

- The evaluation is based on the sales standards specified by the client.
- Acceptable wear and tear according to sales standards is not always documented in this condition report.
- The specified repair methods and/or resulting repair times were determined taking into account modern industrial repair methods.
- The reseller must assess individual repair costs.
- The inspection was carried out without dismantling. Macadam cannot be held responsible for any missing information. For further information, please contact the seller.