TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Arnoldschacht 9-11
44894 Bochum

Expertise

Protocol number: 48591639
Order No. / Reference: 27292973
Inspection date: 9 Nov 2026

Manufacturer: Opel	Model: Astra 1.5 D Automatik Business Elegance
VIN: VXKFBYHZTP1019247	





Vehicle details

Manufacturer / Type / Model / Equipment	
Opel Astra 1.5 D Automatik Business Elegance	
Vehicle Identification number	VXKFBYHZTP1019247
Mileage (Read)	80,395 km
First registration	21 Apr 2023
Number of holders	1
Next periodical technical inspection	04/2028
(Report on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,499 ccm / 4
Power	96 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Arktisweiß
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Grey

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	12,500 km
Last service on / at	06/2025 at 49,953 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GQ387456
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	1889 / AES 00087		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,940 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	6mm / 6mm
2)	225/45 R17 94V	Summer tyres on Light alloy	Michelin	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R16 91H	Winter tyres on Light alloy	Continental	5mm / 5mm
2)	205/55 R16 91H	Winter tyres on Light alloy	Continental	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 06/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartments
- Airbag: Front airbags, driver and front passenger
- Airbag: Front and rear outer head airbags
- Automatic activation of the hazard warning lights
- Exterior mirror housings in black
- On-board computer
- Diesel particulate filter (DPF) maintenance-free
- Electronic brake force distribution (EBD)
- Electric windows front and rear
- Front collision warning system
- Back window, heater
- Interior rearview mirror, automatically dimming
- Air conditioning: Intelli-Air air quality system "Clean Cabin"
- Front headrests and 3 rear headrests, height adjustable
- LED ambient lighting
- LED headlights
- Steering wheel heating
- Illuminated makeup mirrors in both sun visors
- Center armrest, front and rear
- Fog light
- Tire repair kit
- Wheels: Alloy wheels 7.5 J x 17 (5 spokes) in silver/black
- Rear seat backrest folds forward in a 60:40 split
- Seat belts: Three-point seat belts in all seats
- Heated seats, driver and passenger
- Solar Protect thermal insulation glazing
- 12V power outlet in the center console
- Electronic immobilizer
- Central locking with remote control
- Airbag: Chest-pelvis-side airbags, driver and front passenger
- Anti-lock braking system (ABS)
- Exterior mirrors, electrically adjustable, heated and folding
- Hill Start Assist
- third brake light
- Tachometer
- Electronic Stability Program (ESP) and Traction Control with engine and brake intervention (TCPlus)
- Transmission: 8-speed automatic transmission
- rear window wiper
- Cable set for trailer hitch
- Dual-zone automatic climate control
- Paintwork: Roof in car color
- LED interior lighting
- Steering wheel: Leather steering wheel, flat-bottomed, perforated, with steering wheel remote control and paddle shifters
- Navigation system
- Electric parking brake
- Tire pressure monitoring system
- 180-degree reversing camera
- Keyless locking and starting system Keyless Open & Start
- Seats: Ergonomic active driver's seat, fabric/premium leatherette Isabella
- Start/Stop System
- Pre-wiring for ISOFIX child seat mounting system
- Wireless Charging

Extra equipment

- Paint finish: Solid
- Wheels: Winter tires 205/55R16 on LMF

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Trim / covers	Door trim - front left side - Soiled - Clean
2	Mudguard - left side	Mudguard - left side - dent(s) - Smart repair
3	Door - rear right side	Door - Scratch(es) - Smart repair
4	Wheel / tyres	Alloy rim - rear left side - Scratch(es) - Loss in value
5	Wheel / tyres	Tyre - front right side (nicht fahrbereit) - Porous / cracked - Replace
6	Wheel / tyres	Alloy rim - rear right side - Scratch(es) - Loss in value
7	Wheel / tyres	Alloy rim - front right side - Scratch(es) - Loss in value
8	Side panel - rear right side	Elbow - Scratch(es) - Smart repair
9	Bonnet	Insulation lining - Damaged - Replace
10	Side panel - rear left side	Side panel - Dent / paintcoat damage - Paint
11	Door - rear left side	Door - Dent / paintcoat damage - Paint
12	Door - front left side	Door - Dent / paintcoat damage - Paint
13	Rear bumper	Rear bumper - Scratch(es) - Paint
14	Front bumper	Front bumper (+ Steinschläge) - Scratch(es) - Paint
15	Vehicle glazing	Windscreen - Stone chips - Replace

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Professionally repaired, Invoice of repair done Non-existent	

Repainting

No.	Repainting
1	Door - front right side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Door - front right side	154 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Professionally repaired previous damages were found at the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Navigation




Figure 17: Misc.




Figure 18: Misc.




Figure 19: Misc.




Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.





Figure 36: Misc.



Damage 1: Trim / covers: Door trim - front left side - Soiled - Clean



Damage 2: Mudguard - left side: Mudguard - left side - dent(s) - Smart repair



Damage 2: Mudguard - left side: Mudguard - left side - dent(s) - Smart repair




Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 3: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 4: Wheel / tyres: Alloy rim - rear left side - Scratch(es) - Loss in value



Damage 5: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Porous / cracked - Replace



Damage 5: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Porous / cracked - Replace



Damage 5: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Porous / cracked - Replace



Damage 5: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Porous / cracked - Replace



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 6: Wheel / tyres: Alloy rim - rear right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 7: Wheel / tyres: Alloy rim - front right side - Scratch(es) - Loss in value



Damage 8: Side panel - rear right side: Elbow - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Elbow - Scratch(es) - Smart repair



Damage 8: Side panel - rear right side: Elbow - Scratch(es) - Smart repair



Damage 9: Bonnet: Insulation lining - Damaged - Replace



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint




Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint



Damage 10: Side panel - rear left side: Side panel - Dent / paintcoat damage - Paint




Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 11: Door - rear left side: Door - Dent / paintcoat damage - Paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Paint




Damage 12: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 12: Door - front left side: Door - Dent / paintcoat damage - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 13: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 14: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint




Damage 14: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 14: Front bumper: Front bumper (+ Steinschläge) - Scratch(es) - Paint



Damage 15: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 15: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 15: Vehicle glazing: Windscreen - Stone chips - Replace



Repainting 1: Door - front right side