TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48379093
Order No. / Reference: 27217279
Inspection date: 26 Oct 2026

Manufacturer: Ford	Model: Transit 350 L4 VA Trend Kofferaufbau mit Ladebordwand
VIN: WF0AXXTTRAMD44816	





Vehicle details

Manufacturer / Type / Model / Equipment	
Ford Transit 350 L4 VA Trend Kofferaufbau mit Ladebordwand	
Vehicle Identification number	WF0AXXTTRAMD44816
Mileage (Read)	169,490 km
First registration	4 Apr 2022
Number of holders	1
Next periodical technical inspection (Report not on hand)	09/2028
Fuel type	Diesel
Engine displacement / Cylinder	1,995 ccm / 4
Power	96 kW
Gearbox / Number of gears	Manual / 6
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Frozen White
Doors / Seats	2 / 3
Upholstery type	Cloth
Colour of upholstery	Black-Anthracite
Re-import	no
readiness to drive	Not roadworthy / moveable

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	25,000 km
Last service on / at	06/2026 at 167,552 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GL232602
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Not roadworthy / moveable		
Manufacturer key number/ type code number	8566 / 000 000		
Emission standard	EURO VI	**fine dust sticker**	
Permitted total weight	3,500 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	5mm / 5mm
2)	235/65 R16 115R	Summer tyres on Steel rim with wheel cover	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
E	235/65 R16 115R	Summer tyres on Steel	Continental	9 mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Headliner in driver's cab
- Tachometer
- Lane Assist additionally with Lane Keeping Assist
- Front electric windows
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Transmission: 6-speed transmission
- Interior lighting with delay circuit
- Fuel tank 70 l
- MyKey key system
- Package: Technology Package 8
- Flatbed: Standard flatbed (wide)
- Wheels: Steel wheels 6.5 J x 16 with 235/65 R 16 tires
- Power steering
- Seat belts
- Start-stop system
- Immobiliser
- Central locking with remote control
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer
- Roof, overhead storage compartment at the front
- Roof marker lights
- Electronic Stability Program (ESP) with Traction Control (TSC)
- Ford Easy Fuel
- Generator, high-performance version
- Cruise control
- Lockable glove compartment with lid
- Front air conditioning
- Paint finish: Solid color paint
- Fog light
- Particulate filter: diesel particulate filter
- Radio: Ford audio system with radio and DAB+
- Headlight low beam: Halogen headlights with daytime running lights
- Seats: Seat package 13
- recirculation mode
- Heat-insulating glazing, lightly tinted
- Second key, foldable, with remote control

Extra equipment

- Airbag (passenger side)
- Exterior mirror, long arm (with integrated turn signals)
- Application of decals including installation
- Package: Visibility Package 1 (TREND)
- Tire pressure monitoring system
- Headlight dipped beam: with static cornering light (supplement to headlight dipped beam)
- Dülmer construction
- Battery: AGM deep-cycle high-performance battery (2 HB AGM batteries - standard battery is replaced by AGM including extended battery life to 30 min;)
- Wheels/Tires: Spare wheel, steel wheel
- Telematics Moove incl. installation
- TÜV approval of the Dülmer body

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was not capable of driving under its own power at the time of inspection, but can be moved on its own axle with the aid of assistance.

Value reducing factors

No.	Component group	Description
1	Interior	Sun visor - right side - Differs from the original configuration - Perform diagnosis
2	Instrument panel	Instrument panel (Einsatz fehlt) - Differs from the original configuration - Replace
3	Instrument panel	Indicator light (Reifendruck) - on - Perform diagnosis
4	Door - rear right side	Door (Klemmt) - Functional / admissibility - Perform diagnosis
5	Front bumper	Front bumper - Scratched - Loss in value
6	Indicator - front	Mirror - left side - Loose - Replace
7	Indicator - front	Mirror - right side - Loose - Replace
8	Vehicle glazing	Windscreen - Broken / torn - Replace

Wear and tear

No.	Component group	Description
1	Door - front left side	Door - dent(s) - No deduction
2	Door - front left side	Door edge - Scratch(es) - No deduction
3	Trim / covers	Boot lining (Kofferaufbau) - Dent / paintcoat damage - No deduction
4	Trim / covers	Boot sill cover - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Kofferaufbau mit Ladebordwand Dülmer, siehe Bilder.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Documents




Figure 15: Documents



Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.




Figure 24: Misc.



Damage 1: Interior: Sun visor - right side - Differs from the original configuration - Perform diagnosis




Damage 1: Interior: Sun visor - right side - Differs from the original configuration - Perform diagnosis



Damage 2: Instrument panel: Instrument panel (Einsatz fehlt) - Differs from the original configuration - Replace




Damage 2: Instrument panel: Instrument panel (Einsatz fehlt) - Differs from the original configuration - Replace



Damage 3: Instrument panel: Indicator light (Reifendruck) - on - Perform diagnosis



Damage 4: Door - rear right side: Door (Klemmt) - Functional / admissibility - Perform diagnosis



Damage 5: Front bumper: Front bumper - Scratched - Loss in value



Damage 5: Front bumper: Front bumper - Scratched - Loss in value



Damage 6: Indicator - front: Mirror - left side - Loose - Replace



Damage 6: Indicator - front: Mirror - left side - Loose - Replace




Damage 7: Indicator - front: Mirror - right side - Loose - Replace



Damage 7: Indicator - front: Mirror - right side - Loose - Replace



Damage 8: Vehicle glazing: Windscreen - Broken / torn - Replace



Damage 8: Vehicle glazing: Windscreen - Broken / torn - Replace