TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Mosolf SE & Co.KG
August-Horch-Straße 1
04519 Rackwitz

# Expertise

Protocol number: 48368641
Order No. / Reference: 27131535
Inspection date: 29 Oct 2026

| | |
|---|---|
| Manufacturer: Ford | Model: Transit Custom 320 L1H1 LKW VA Autm. Trend |
| VIN: WF0ZXXTTGZPK80870 | |







## Vehicle details

| | |
|---|---|
| **Manufacturer / Type / Model / Equipment** | |
| Ford Transit Custom 320 L1H1 LKW VA Autm. Trend | |
| **Vehicle Identification number** | WF0ZXXTTGZPK80870 |
| **Mileage** (Read) | 118,236 km |
| **First registration** | 18 Apr 2023 |
| **Number of holders** | 1 |
| **Next periodical technical inspection** (Report on hand) | 05/2027 |
| **Fuel type** | Diesel |
| **Engine displacement / Cylinder** | 1,995 ccm / 4 |
| **Power** | 125 kW |
| **Gearbox / Number of gears** | Automatic / 6 |
| **Type of drive** | Front drive |
| **Type of vehicle** | Van |
| **Colour / colour code** | Frost-Weiß |
| **Doors / Seats** | 4 / 6 |
| **Upholstery type** | Cloth |
| **Colour of upholstery** | Black |

## Vehicle details

| | | | |
|---|---|---|---|
| **Maintenance booklet / proof** | digital proof / complete | **Next maintenance in** | 35,000 km |
| **Last service on / at** | 07/2026 at 117,768 km | | |
| **Key is / should be** | 1 / 2 | **FZG documents** | ZB#2 (B) was available (copy), ZB#1 (S) was not available. |
| | | **Letter No.** | GT886592 |
| **Previous damage / Accident** | None detectable | **Repainting** | None detectable |
| **Inspection conditions** | sufficient | **Lifting equipment / pit** | yes |
| **Test drive** | Not performed | **Engine function test** | Performed |
| **Manufacturer key number/ type code number** | 8566 / BMV 08191 | | |
| **Emission standard** | EURO6 | **fine dust sticker** | |
| **Permitted total weight** | 3,200 kg | **Empty weight** | |

## Tyres

### Mounted tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R16 107T | Summer tyres on Steel rim with wheel cover | Goodyear | 5mm / 5mm |
| 2) | 215/65 R16 107T | Summer tyres on Steel rim with wheel cover | Goodyear | 8mm / 8mm |

### Additional tyres

| # | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| 1) | 215/65 R16 107S | Winter tyres on Steel | Continental | 8mm / 8mm |
| 2) | 215/65 R16 106T | Winter tyres on Steel | Semperit | 8mm / 8mm |

### Replacement

| Typ | Tyre size | Type of tyre | Manufacturer | Tread depth |
|---|---|---|---|---|
| E | 215/65 R16 107T C | Summer tyres on Steel | Goodyear | 9 mm |

**Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.**

## Equipment

### Standard equipment

- 1 battery
- Anti-lock braking system with electronic brake force distribution (EBD)
- roof, flat
- Headliner in driver's cab (up to the partition wall to the cargo area)
- Tachometer
- Third brake light
- Windows, 2nd row: Side windows fixed, right and left
- Front electric windows (with quickdown/up function for driver's side)
- FordPass Connect (including live traffic information, information about the current status or location of the vehicle, and control of selected vehicle functions via smartphone with the FordPass app. Real-time traffic information (in conjunction with audio systems 24 and 25). Further information about FordPass Connect can be found at https://www.ford.de/fordpass-connect.)
- Grab handle on the B-pillar of the passenger side
- Interior lighting with delay function (with reading lights at the front)
- Paint finish: Solid color paint
- Steering column, adjustable in height and reach
- Emergency brake assist including emergency brake light
- Front and rear parking pilot system including fog lights
- Particulate filter: diesel particulate filter
- Wheel trims
- Wheels/Tires: Spare wheel, steel wheel
- Wheels: Steel wheels 6.5 J x 16 with 215/65 R 16 R tires (6.5 J x 16 with 215/65 R 16 R tires)
- Headlights: Halogen projector headlights (with LED daytime running lights and fog lights with static cornering lights)
- Mud flaps front and rear
- Half-height side wall cladding
- Seat belts (front seat belt tensioners and force limiters - warning system for unfastened driver's seat belt)
- Seats: Seat Package 13 - (Custom DOKA Trend) (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (foldable) - Interior armrest for driver - Manual lumbar support (driver's seat) - TREND seat cover: fabric - Double cab partition with window)
- Auxiliary heater, electric
- Driver's side airbag
- Exterior mirrors, electrically adjustable and heated
- On-board computer (with consumption and mileage information (e.g. remaining range) and outside temperature display)
- Double-leaf rear door with 180° opening angle (without window)
- Electronic Stability Program (ESP) with Traction Control System (TCS) (Hill Start Assist - Crosswind Assist - Emergency Brake Assist - Rollover Protection)
- Ford Easy Fuel (comfortable fuel filler cap and misfuelling protection)
- Warranty: 2-year Ford new car warranty including Ford Assistance mobility guarantee
- Generator, 240 A
- Cruise control system including imitation leather steering wheel (with adjustable speed limiter)
- Transmission: 6-speed automatic
- Lockable glove compartment with lid
- Front air conditioning (including dust and pollen filter)
- Fuel tank 70 l
- Cargo area lighting with activatable switch-off delay (after 30 minutes)
- Package: Style color package (front and rear bumpers and exterior mirror caps painted in body color)
- Radio: Audio system 13 additionally with DAB/DAB+ (Radio (FM/AM) - Four speakers, antenna - Audio remote control on the steering wheel - Bluetooth, USB port and hands-free system - MyFord Dock - additionally with digital radio reception DAB/DAB+ (Digital Audio Broadcasting))
- Sliding door entry light automatically illuminates when the door is opened
- Sliding door: Sliding door, right (also with window, fixed)
- Side protection strips
- Power steering
- Seats: 2nd row, 3-seater bench (incl. height-adjustable headrests, 2 ISOFIX mounts (each on the outer seat) and open under-seat storage compartment (rear seat cover always the same as front seat cover))
- Start-stop system
- Power outlet: 12-volt connection
- Lashing eyes 4
- Immobiliser
- Heat-insulating glazing, lightly tinted
- Central locking with remote control

### Extra equipment

- Bott: DED019H0000788 basic package
- BOTT: Installation as per invoice 350467590
- BOTT: Installation as per invoice 350467590
- Package: Visibility Package II (Trend) (Heated windscreen - Electrically folding exterior mirrors - Adjustable instrument lighting - Windscreen wipers with rain sensor - Headlight assistant with day/night sensor)
- Reversing camera (reversing camera with image transmission of the rear driving path in the multifunction display and coupling aid)
- Seats: Seat Package 15 (Custom DOKA Trend) (Driver's seat, 4-way adjustable (forward/backward, backrest, seat cushion tilt, height) - Double passenger seat with storage compartment under individually foldable seat cushions - Height-adjustable headrests - Integrated tray in the double passenger seat (foldable) - Heated driver's seat - Heated passenger seat (outer seat) - Inner armrest for driver - Manual lumbar support (driver's seat) - TREND seat cover: fabric - Double cab partition with window)
- Tire Pressure Monitoring System (TPMS)
- Airbag (passenger side)
- Blind spot assist including cross traffic alert and trailer function (electrically adjustable and heated exterior mirrors, also electrically foldable)
- BOTT: Load securing pad VE 6
- BOTT: vario CarOffice
- Radio: Audio system 25: Ford audio system including Ford SYNC 3 with AppLink, DAB/DAB+, navigation (Radio (FM/AM) 8" touchscreen multifunction display, FordPass Connect integrated control panel and audio remote control, Ford SYNC 3 with touchscreen (hands-free system with voice control, SMS readout/sending function, Bluetooth, Emergency Assistance...), AppLink (advanced voice control, privacy mode, support for Android Auto and Apple CarPlay, capacitive touchscreens...), lane guidance, adaptive cruise control, lane keeping assist, traffic sign recognition, Park Pilot front/rear)
- Towing device (fixed, 13-pin socket - incl. trailer stability control (TSC))

## Brief expert findings

| | |
|---|---|
| Documents submitted | At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy) |
| VIN comparison | The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection. |
| Inspection | The inspection conditions were sufficient for the assessment of the vehicle.<br>Lifting equipment and/or a pit were available for examining the vehicle. |
| Test drive | No test drive/shunting maneuver was carried out during the inspection of the vehicle. |
| Engine function test | An engine test run was performed. |

## Value reducing factors

| No. | Component group | Description |
|---|---|---|
| 1 | Instrument panel | Indicator light (Ad Blue) - Empty - No deduction |
| 2 | Boot lid / rear door | Rear door - right side - Glued / labelled - De-glue / neutralise |
| 3 | Mudguard - right side | Mud flap - Missing - Replace |
| 4 | Sill - left side | Sill - Deformed - Smart repair |
| 5 | Vehicle glazing | Windscreen - Broken / torn - Replace |

## Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  *(Delivery by third-party service providers)*
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  *(Functional testing of driver assistance systems is not included in the scope of services!)*
- a photographic documentation of the vehicle

## Basis for the order

This product is based on the guidelines for vehicle returns and valuations of light commercial vehicles published by Alphabet Fleet Management GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

## Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.




**Figure 1:** Diagonal front (left)




**Figure 2:** Diagonal front (right)




**Figure 3:** Diagonal rear (left)




**Figure 4:** Diagonal rear (right)



**Figure 5:** Interior - front



**Figure 6:** Interior - rear




**Figure 7:** Instrument cluster



**Figure 8:** Instrument panel



**Figure 9:** Interior 360° view (Online Link)



**Figure 10:** Cargo area





**Figure 11:** VIN



**Figure 12:** Mounted tyres




**Figure 13:** Documents





**Figure 14:** Documents




**Figure 15:** Documents




**Figure 16:** Documents



**Figure 17:** Additional tyres




**Figure 18:** Navigation



**Figure 19:** Misc.



**Figure 20:** Misc.



**Figure 21:** Misc.



**Figure 22:** Misc.




**Figure 23:** Misc.




**Figure 24:** Misc.





**Figure 25:** Misc.



**Figure 26:** Misc.



**Figure 27:** Misc.




**Figure 28:** Misc.



**Figure 29:** Misc.



**Figure 30:** Misc.



**Figure 31:** Misc.



**Figure 32:** Misc.




**Figure 33:** Misc.




**Figure 34:** Misc.




**Figure 35:** Misc.





**Figure 36:** Misc.



**Figure 37:** Misc.



**Figure 38:** Misc.




**Damage 1:** Instrument panel: Indicator light (Ad Blue) - Empty - No deduction




**Damage 1:** Instrument panel: Indicator light (Ad Blue) - Empty - No deduction



**Damage 2:** Boot lid / rear door: Rear door - right side - Glued / labelled - De-glue / neutralise




**Damage 2:** Boot lid / rear door: Rear door - right side - Glued / labelled - De-glue / neutralise



**Damage 3:** Mudguard - right side: Mud flap - Missing - Replace



**Damage 3:** Mudguard - right side: Mud flap - Missing - Replace



**Damage 4:** Sill - left side: Sill - Deformed - Smart repair




**Damage 4:** Sill - left side: Sill - Deformed - Smart repair



**Damage 4:** Sill - left side: Sill - Deformed - Smart repair



**Damage 5:** Vehicle glazing: Windscreen - Broken / torn - Replace



**Damage 5:** Vehicle glazing: Windscreen - Broken / torn - Replace