TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48143794
Order No. / Reference: 27092434
Inspection date: 14 Oct 2026

Manufacturer: Skoda	Model: Superb Combi 1.4 TSI iV DSG Style
VIN: TMBJW9NP7M7055328	





Vehicle details

Manufacturer / Type / Model / Equipment	
Skoda Superb Combi 1.4 TSI iV DSG Style	
Vehicle Identification number	TMBJW9NP7M7055328
Mileage (Read)	117,274 km
First registration	1 Nov 2021
Number of holders	1
Next periodical technical inspection	11/2026
(Report on hand)	
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,395 ccm / 4
Power	115 kW
Gearbox / Number of gears	Automatic / 6
Type of drive	Front drive
Type of vehicle	Car station wagon
Colour / colour code	Black Magic Pearlescent
Doors / Seats	5 / 5
Upholstery type	Cloth
Colour of upholstery	Anthracite-Black
Vehicle with smoke odor	no

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	23,600 km
Last service on / at	05/2026 at 110,802 km		
Key is / should be	3 / 3	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GA515243
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	8004 / AUJ 00093		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,259 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 94V	Summer tyres on Light alloy	Michelin	3mm / 3mm
2)	215/55 R17 94W	Summer tyres on Light alloy	Continental	5mm / 5mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	215/55 R17 98V	Winter tyres on Light alloy	Continental	4mm / 4mm
2)	215/55 R17 98V	Winter tyres on Light alloy	Continental	7mm / 7mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 12/2024		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Closed storage compartments behind the wheel arches in the trunk, including cargo elements
- Airbag, driver and switchable passenger airbag
- Airbag, driver's knee airbag
- Airbag, head airbags
- Airbag, front side airbags
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Electrically adjustable and heated exterior mirrors
- Exterior mirrors and door handles in body color
- Electrically folding exterior mirrors with boarding lights - interior and exterior mirrors with automatic dimming
- Hydraulic brake assist (HBA)
- Roof rails, anodized
- Tachometer
- Dynamic Light Assistant (Masked Continuous High Beam)
- Electric tailgate opening including boot cover and multifunction storage compartment
- Electronic Stability Control (ESC)
- Driving profile selection including customizable key (Normal, Eco, Sport, Individual) including additional key
- Electric windows front and rear, including anti-pinch protection and child safety lock
- Front footwell lighting
- Cruise control system (cruise control) including speed limiter
- Transmission: 6-speed direct-shift gearbox (DSG)
- Tinted windows
- Heated rear window
- ISOFIX preparation on the outer rear seats, including top tether
- Boot cover, roll-up and removable, semi-automatic
- Front and rear headrests are height-adjustable.
- Charging cable, Mode 2, Schuko, 10A
- Remote release of the rear seat backrests in the trunk
- Steering wheel: height and reach adjustable
- Reading lights at the front and rear of the headliner
- Matrix LED headlights - AFS - Dynamic high beam assist - Automatic headlight range control - Headlight cleaning system - LED taillights in crystal glass look - Including dynamic turn signals
- Color multifunction display in the instrument cluster
- Navigation: Amundsen 8" Dynamic Navigation System
- Otto particulate filter
- Upholstery: Cloth
- Radio accessories: Digital radio reception DAB+
- Radio accessories: Wireless SmartLink, Apple CarPlay, Android Auto
- Tire mobility kit - tire repair spray incl. compressor
- Heated windshield washer nozzles
- Electromechanical power steering
- Seats: Heated front seats
- Seats: Adjustable lumbar support in the front seats
- Storage compartments, ticket holder on the windshield, 4 roof grab handles (rear with coat hooks), coat hooks on the B-pillar, holders for safety vests in the front doors, sunglasses compartment in the headliner, storage compartments in the door panels (front and rear) with 1.5L bottle holders, cup holders in the front center console with easy-open bottle opening, storage pockets on the front seatbacks, storage compartments behind the wheel arches in the trunk including cargo elements, illuminated trunk.
- Illuminated glove compartment
- Hill start assist
- Grey headliner
- Decorative inlay Dark Brushed
- Third brake light
- Easy Start (start-stop button instead of ignition lock)
- Electronic parking brake including auto-hold function
- Electronic transverse differential lock (XDS+)
- Driving light assistant and rain sensor, tunnel light, coming and leaving home function
- Chassis: Adaptive chassis DCC including driving profile selection and customizable key, without lowering.
- Front radar assist including city emergency braking function: The front radar assist warns of impending collisions and initiates braking to reduce the force of an unavoidable impact. The front radar assist continuously monitors the distance to vehicles ahead using a radar sensor integrated into the radiator grille.
- Rear window wiper including windshield washer system
- Air Care Climatronic (2-zone) air conditioning system - fully automatic, separately adjustable for driver and front passenger, including odor and allergen filter and air-conditioned glove compartment
- Metal loading sill protector
- Steering wheel: 2-spoke leather steering wheel with multifunction buttons including gearshift and handbrake lever in leather
- Rear center armrest with cup holders and pass-through option
- Front center armrest with storage compartment
- Engine drag torque control (MSR)
- Multi-collision brake
- LED fog lights with integrated cornering lights
- Rear parking sensors
- Radio accessories: 2 USB-C ports in the center console
- Radio accessories: SmartLink+ - Apple CarPlay - Android Auto - MirrorLink - SmartGate
- Tire pressure monitoring
- Wheels: 17" Drakon alloy wheels - 6.5J x 17" ET 41 with 215/55 R17 tires - anthracite, polished
- Superb safety belts - Height-adjustable three-point front seat belts with pretensioners - Three three-point rear seat belts - Seat belt reminder indicator for all seats
- Seats: electrically adjustable driver's seat with memory function - driver's seat and exterior mirrors with memory function

- Seats: Electrically adjustable front seats, driver's seat with memory function
- Seats: Electric operation of the front passenger seat from the rear
- Seats: Rear seat backrest split 60:40, foldable
- Sun visor on driver and passenger side with illuminated make-up mirror
- Start/stop system including brake energy recuperation
- 12V socket in the trunk
- 12V socket in the center console, front and rear
- Telephone: Convenient hands-free phone system with Bluetooth, without connection to an external antenna
- Chrome-plated elements on air vents, light switches, music or navigation systems, air conditioning
- Immobiliser
- Seats: Height-adjustable front seats
- SKODA Care Connect SOS emergency call function (emergency call including automatic activation in the event of an accident with airbag deployment), mobility service (connection for rapid assistance in case of breakdown), information service (connection to the hotline for all questions regarding vehicle functions), free remote vehicle access for 1 year with access to vehicle data and functions via smartphone, e.g., parking position, hazard warning lights activation, current fuel level
- Lashing eyes in the trunk
- Central locking with remote control

Extra equipment

- Waste bin for the inside door
- Airbag, proactive occupant protection including rear side airbags
- Decorative inlay Argenzo Zebrano
- Kessy, keyless entry and start-stop system
- Paint finish: Pearl effect
- LED ambient lighting - decorative trim strips with selectable color scheme, reading lights, door handles and footwells as well as sun visors with LED lighting - projection of the SKODA lettering from the bottom of the door onto the ground (front doors)
- Sunset (rear window and rear side windows tinted dark)
- Adaptive Cruise Control (ACC) (control range up to 210 km/h) replaces cruise control.
- Swiveling trailer hitch including trailer stabilization
- Luggage net partition
- Comfort opening for the electric tailgate (sensor-controlled opening)
- Steering wheel: Heated steering wheel (2 spokes) with paddle shifters
- Fatigue detection
- Network program in the trunk
- Front and rear parking sensors

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Expired - Replace
2	Door - rear right side	Door - dent(s) - Smooth repair work
3	Side panel - rear right side	Elbow - dent(s) - Smooth repair work
4	Mudguard - left side	Mudguard - left side - dent(s) - Smart repair
5	Side panel - rear left side	Side panel - Scratched - Paint
6	Front bumper	Front bumper - Scratched - Paint

Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratched - No deduction
2	Bonnet	Bonnet - Stone chips - No deduction
3	Rear bumper	Rear bumper (Ladekante) - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side right, Provided by user / customer, from 20 Nov 2025	1.683,56 €

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Der beiliegende Winterradsatz ist kein Bestandteil des Auslieferungsumfangs.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area




Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation




Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Damage 1: Equipment: Tirefit filler - Expired - Replace



Damage 2: Door - rear right side: Door - dent(s) - Smooth repair work




Damage 2: Door - rear right side: Door - dent(s) - Smooth repair work



Damage 3: Side panel - rear right side: Elbow - dent(s) - Smooth repair work




Damage 3: Side panel - rear right side: Elbow - dent(s) - Smooth repair work




Damage 4: Mudguard - left side: Mudguard - left side - dent(s) - Smart repair




Damage 4: Mudguard - left side: Mudguard - left side - dent(s) - Smart repair




Damage 5: Side panel - rear left side: Side panel - Scratched - Paint




Damage 5: Side panel - rear left side: Side panel - Scratched - Paint




Damage 5: Side panel - rear left side: Side panel - Scratched - Paint



Damage 6: Front bumper: Front bumper - Scratched - Paint



Damage 6: Front bumper: Front bumper - Scratched - Paint



Damage 6: Front bumper: Front bumper - Scratched - Paint



Damage 6: Front bumper: Front bumper - Scratched - Paint



Wear and tear 1: Body: Underbody panelling - Scratched - No deduction




Wear and tear 1: Body: Underbody panelling - Scratched - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction



Wear and tear 2: Bonnet: Bonnet - Stone chips - No deduction




Wear and tear 3: Rear bumper: Rear bumper (Ladekante) - Scratch(es) - No deduction



Wear and tear 3: Rear bumper: Rear bumper (Ladekante) - Scratch(es) - No deduction

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Wear and tear 3: Rear bumper: Rear bumper (Ladekante) - Scratch(es) - No deduction