
MACADAM







Volkswagen ID.3: R612FG

Vinnumber:	**WVWZZZE1ZN8005879**	Versionname:	**ID.3 107kW / 62kWH Pro automaat**
First Registrationdate:	**29/08/2022**	Fiscalpower:	
Expertise Mileage:	**110854**	Power Kw:	**107**
Bodytype:		Body colour	**Mangan Grey metallic**
Gearbox:	**Automatic**	Paint type	**Metalic**
Transmission:		Type of rims (mounted)	**Aluminium**
Fueltype:	**Electric**	Parking lot	**1120**
Number of seats	**5**		
Type of rims (mounted)	**Aluminium**		
Maintenance needed	**Yes**		

Options

Number of keys total	**2**	Rear parking sensors	
GPS			
Autom climate control			
Radio multimedia			

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	215 / 55 / 18 / 99 / V / Aluminium	6,3 mm	Bridgestone	Summer
	Right	215 / 55 / 18 / 99 / V / Aluminium	6,4 mm	Bridgestone	Summer
Rear	Left	215 / 55 / 18 / 99 / V / Aluminium	4,3 mm	Bridgestone	Summer
	Right	215 / 55 / 18 / 99 / V / Aluminium	3,7 mm	Bridgestone	Summer

Assistance equipment

Number of charging cables (rapid charge)	**1**

Service, Maintenance, Execute



Wing RL, Scratch(es), Repair and paint (complete)





Door FR, Scratch(es), Repair and paint (complete)




Bumper R, Scratch(es), Repair and paint (complete)





Roof, Chemical polution, Polish




Onderhoudshistorie van: WVWZZZE1ZN8005879

ALPHABET

Kenteken	R612FG
Merk Model	Volkswagen ID.3 107kW / 62kWH Pro automaat
Brandstofsoort	Elektrisch
Datum deel1	8/29/22

Datum reparatie	Kilometerstand	Reparatie omschrijving
8/24/26	105,000	APK
8/24/26	105,000	Ruitenwisserblad(en) voorzijde