APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	BMW
Model / version:	5 SERIES BERLINE
Vin:	WBA11CH0X0CK20698
Plate:	CDAC494
Mileage:	76888
SOH:	
First registration:	29/04/2022
Color:	Saphirschwar

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS

Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES






























































VIN INFORMATION

Téléphone	Transmission automatique	8 rapports
4 roues motrices	Equipement Luxury Line	Entourage de vitres chromé

Matière : alliage
Diamètre arrière 18
Diamètre avant 18
Hauteur arrière 45
Largeur avant 245
Climatisation réfrigérant 1234YF
1998 cm3
292 ch
Rétroviseur gauche jour/nuit automatique
Sièges avant chauffants
Suspension pilotée
Assistance au parking
Caméra avec vision à 270°
Protection piéton

Freinage d'urgence assistée autonome(extra-urbain)
depuis 12.21
Teleservices
BMW Live Cockpit Professional

Lettre repère (J)
Largeur avant 8,0
Diamètre arrière 18
Indice de vitesse avant Y
Largeur arrière 245
Finition intérieure bois
2.00 litres
Euro 6
Rétroviseur droit jour/nuit automatique
Foureau à skis
Aide au stationnement avant
Caméra avant
Alarme
Alerte franchissement de ligne (AFIL)

Avertisseur de collision avant

éclairage d'ambiance
tuner DAB
tableau de bord Sensatec

Diamètre avant 18
Largeur arrière 8,0
Hauteur avant 45
Indice de vitesse arrière Y
Climatisation automatique 4 zones
Hybride essence
215 kw
Métallisée vernissée
Siège avant gauche chauffant
Garnitures cuir
Aide au stationnement arrière
Caméra arrière de recul
Appel de secours
Freinage d'urgence assistée autonome (urbain)
Contrôle pression des pneus

mesures CO2 étendues
protection acoustique des piétons spécifique Europe

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	✓	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	✓
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	1	**Fast charging cables:**	1

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	3 mm	Bridgestone	2454518100y	Summer	Aluminium	×
Front right	3 mm	Bridgestone	2454518100y	Summer	Aluminium	×
Rear left	3 mm	Bridgestone	2454518100y	Summer	Aluminium	×
Rear right	3 mm	Bridgestone	2454518100y	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper F	
2	Wing FL	
3	Outside rear-view mirror housing L	
4	Alloy rim FL	Scratch(es)
5	Alloy rim RL	Scratch(es)
6	Bumper R	
7	Alloy rim RR	
8	Door FR	Dent(s)
9	Indicator FR	Crack
10	Alloy rim FR	Scratch(es)

Total: 10

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
No damages present					

DAMAGES DETAILS

1 - Bumper F





2 - Wing FL




3 - Outside rear-view mirror housing L





4 - Alloy rim FL - Scratch(es)





5 - Alloy rim RL - Scratch(es)




6 - Bumper R






7 - Alloy rim RR




8 - Door FR - Dent(s)





9 - Indicator FR - Crack




10 - Alloy rim FR - Scratch(es)




SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

23/10/2026 12:46



Customer

23/10/2026 12:46

Useless