TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48087844
Order No. / Reference: 27056863
Inspection date: 13 Oct 2026

Manufacturer: Mercedes-Benz	Model: E 300 de 4Matic T 9G-TRONIC Exclusive
VIN: W1KZH1BB6PB171442	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz E 300 de 4Matic T 9G-TRONIC Exclusive	
Vehicle Identification number	W1KZH1BB6PB171442
Mileage (Read)	29,622 km
First registration	19 Sept 2023
Number of holders	1
Next periodical technical inspection	09/2026
(Report not on hand)	
Fuel type	Hybr.D/E ext.aufl
Engine displacement / Cylinder	1,950 ccm / 4
Power	143 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	All-wheel drive
Type of vehicle	Car station wagon
Colour / colour code	Graphitgrau Metallic
Doors / Seats	5 / 5
Upholstery type	Leather
Colour of upholstery	Black-Anthracite
Vehicle with smoke odor	no

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	Non-existent	**Next maintenance in**	63 Tag(e)
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV729968
Previous damage / Accident	Detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / ATL 00065		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,850 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R18 100V	Winter tyres on Light alloy	Pirelli	7mm / 7mm
2)	275/40 R18 103V	Winter tyres on Light alloy	Pirelli	6mm / 6mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- ADAPTIVE BRAKE with hill start assist, pre-filling and drying braking in wet conditions
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Acoustic environmental protection
- Premium ambient lighting with 64 colors and 3 color zones
- Anti-lock braking system (ABS)
- Traction control (ASR)
- Attention Assist
- Basic services
- On-board computer
- Diesel particulate filter
- Third brake light
- EASY-PACK cargo cover including EASY-PACK safety net
- Electronic Stability Program (ESP)
- Chassis: Air suspension on the rear axle with level control
- Electric window regulator with comfort operation and anti-pinch protection, 4-way
- Heated rear window with timer
- Interior headliner in nevagrau fabric
- KEYLESS START
- Climate: Pre-conditioning
- Headrests 5-way adjustable for driver and front passenger, 4-way adjustable, and 2-way adjustable in the rear.
- Steering wheel: Multifunction steering wheel in Nappa leather in a 3-spoke design
- Mercedes-Benz emergency call system
- Center console with on-the-fly storage compartment
- Navigation: Hard disk navigation
- Package: Storage compartment (for plug-in hybrid)
- Package: Public Charging
- Upholstery: ARTICO man-made leather
- Radio: Extended MBUX functions
- Radio accessories: Digital radio
- Tire pressure monitoring system
- Remote Services Plus
- Power steering
- Seats: Rear seat backrests foldable, 40/20/40 split
- Touchpad
- Electronic immobilizer
- Central locking
- AdBlue tank with a capacity of 23.5 liters
- Airbag for driver and front passenger
- Airbag: Kneebag for driver
- Airbag: Windowbags left/right
- 4MATIC all-wheel drive
- AMG sports pedal assembly made of brushed stainless steel with rubber studs
- Foldable armrest for driver and front passenger
- Left and right exterior mirrors, heated and electrically adjustable, painted in body color
- Brake assist, active
- Tachometer
- DYNAMIC SELECT
- EASY-PACK tailgate
- Chassis: AGILITY CONTROL chassis with selective damping system
- Velour floor mats
- Transmission: 9-speed automatic, 9G-TRONIC
- rear window wiper
- Instrument panel and door sills in ARTICO man-made leather
- THERMATIC automatic climate control
- charging cable
- Charging system: AC charging system 7.4 kW
- LED High Performance Headlights
- Steering column mechanically adjustable in height and length
- Center console piano black finish
- Navigation accessories: Pre-installation for Live Traffic Information
- Package: AVANTGARDE Exterior (for plug-in hybrid)
- Package: Seating comfort
- PRE-SAFE system
- Radio: MBUX multimedia system
- Radio accessories: Communication module (LTE) for using Mercedes me connect services
- Windscreen wipers with rain sensor
- Seats: i-Size child seat attachment
- Power outlet: 12V socket in the cargo area
- High-visibility vest for drivers
- Green, heat-insulating glass all around
- Decorative elements, light brown open-pored ash wood

Extra equipment

- Decorative elements, wood, ash, brown, glossy
- Head-up display (lens and mirror system projects a virtual image into the driver's field of vision - full-color display that is easily readable even on sunny days and at night - depending on the equipment, display of, for example, navigation instructions, speed, speed limits or settings of cruise control or active distance assist DISTRONIC)
- Heated windshield washer system (including heated washer fluid reservoir, windshield washer nozzles and washer fluid hoses)
- MULTIBEAM LED (84 individually controllable high-performance LEDs, low beam and high beam in LED projection technology, Adaptive Highbeam Assist Plus (glare-free permanent high beam), ULTRA RANGE high beam, cornering light or cornering light with roundabout and intersection function, active curve illumination (with predictive control with active lane keeping assist or driving assistance packages), extended fog light, city light, country road light, motorway light and bad weather light, adaptive full-LED taillights)
- Package: Business (MBUX High-End Package - Connectivity Package Navigation - Traffic Sign Assist - Smartphone Integration (Apple CarPlay and Android Auto) - Preparation for Digital Key Handover - Widescreen Cockpit - Wireless Charging System for Mobile Devices - MBUX Augmented Reality for Navigation - Heated Seats for Driver and Front Passenger - Parking Package with Rearview Camera - Fuel Tank with 66 Liter Capacity (916) (60l for Diesel Plug-in Hybrids).)
- Package: Driving Assistance Package Plus (Active Distance Assist DISTRONIC incl. Active Speed Limit Assist, Extended Automatic Restart on Motorways, Route-Based Speed Adaptation with Traffic Jam Function (only when Parking Packages are selected), Active Steering Assist incl. Active Emergency Stop Assist with SOS Function, Emergency Lane Radio, Active Brake Assist incl. Turn and Intersection Radio, Traffic Jam Emergency Brake Radio, Evasive Steering Assist, Active Lane Keeping Assist, Active Blind Spot Assist incl. Exit Warning, Pedestrian Warning Radio, PRE-SAFE Impulse Side, Active Traffic Jam Assist)
- Package: Mirrors (both exterior mirrors electrically foldable (button in the driver's door control panel) - automatic lowering of the passenger-side mirror glass to parking position when reverse gear is engaged - interior mirror and driver's side exterior mirror automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area)
- Package: Sun protection package (mechanical sunshade in rear doors left and right - extendable sun visors with make-up mirror for driver and front passenger)
- Paint finish: Metallic
- Center console wood ash brown glossy
- Illuminated door sills with Mercedes-Benz lettering (With an illuminated "Mercedes-Benz" lettering, the brushed stainless steel front door sills add sporty and exclusive highlights. At the same time, they protect the entry area from damage.)
- Package: Active Multicontour Seat Package (Active multicontour seats in the front with separately adjustable air chambers - 4-way lumbar support with adjustable air chambers - Driving dynamics function with automatic lateral guidance depending on steering angle, lateral acceleration and vehicle speed - 14 air chambers enable ENERGIZING massage function with 8 different programs - 2 of the massage programs offer an additional heat effect (hot stone massage principle) - Seat heating Plus for driver and front passenger)
- Package: EXCLUSIVE Exterior (for plug-in hybrid) (18-inch (45.7 cm) 5-spoke light-alloy wheels, high-gloss black and diamond-turned finish with 245/45 R 18 tires on 8 J x 18 ET 43 rims at the front, 275/40 R 18 tires on 9 J x 18 ET 53 rims at the rear; Mercedes star on the hood; radiator grille with chrome surround and 3 louvers; front bumper with chrome A-wing and chrome front splitter; polished aluminum side skirts and window trim; side sills painted in body color with chrome inserts; polished aluminum roof rails; exhaust system with 2 tailpipe trims)
- Package: KEYLESS-GO Comfort Package (vehicle key with KEYLESS-GO functionality - KEYLESS-GO access and drive authorization system - start/stop button - comfort opening and closing - door handles with chrome inlay - HANDS-FREE ACCESS - handle recess lighting - remote trunk lid closing)
- Package: Memory (driver and front passenger seats, steering column and exterior mirrors electrically adjustable and storable - seat longitudinal position and headrest height additionally electrically adjustable - distribution of the heated areas of the seat cushion and seat backrest storable - position of the optional head-up display adjustable and storable - 4-way lumbar support for driver and front passenger - seat cushion depth adjustment with gapless cushion - PRE-SAFE positioning function for the front passenger seat)
- Radio accessories: Burmester surround sound system (13 high-performance speakers - 9-channel DSP amplifier with a total output of 590 W - Frontbass technology with woofers integrated into the body shell for powerful bass reproduction - Sound optimization for the front and rear seats - Noise cancellation (VNC) - Sound preset: Surround function to generate a virtual surround sound - Multi-channel format support for true surround sound)
- Roof rack (Expand your transport options. You can combine the base carrier with a variety of Mercedes-Benz roof accessories – such as roof boxes, bicycle carriers or ski racks. It is precisely matched to the body and offers the best possible safety and aerodynamics.)
- Steering wheel: Steering wheel heating

- Seats: Climate control for driver and front passenger in conjunction with active multi-contour seats or heat comfort seats (including seat heating and ventilation. Active ventilation quickly cools the seat surface to a comfortable temperature on hot days, creating a balanced seating climate. The switchable seat heating provides pleasant warmth as desired during the colder months.)
- Towbar with ESP trailer stabilization (fully electrically foldable and retractable)
- Telephone accessories: Multifunctional telephony (this equipment perfectly integrates the mobile phone into the vehicle - it connects the device to the external antenna and charges the mobile phone - both without cables or a cradle.)
- Upholstery: Nappa leather

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Door - front left side	Door - Scratch(es) - Smart repair
2	Misc.	Misc. (Reifendruckkontrolle) - on - Perform diagnosis
3	Sill - left side	Sill - Scratch(es) - Smart repair
4	Wheel / tyres	Tyre - front right side (nicht fahrbereit) - Defective - Replace
5	Side panel - rear left side	Elbow - Dent / paintcoat damage - Smart repair
6	Body	Underbody panelling - Broken / torn - Replace
7	Wheel / tyres	Alloy rim - front right side - Scratched - Replace
8	Mudguard - left side	Mudguard - left side - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - Expired - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Rear, Provided by user / customer, from 18 Jun 2025	3.416,22 €

Accident damages

No.	Accident
1	Side right

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

Non-repaired previous damages were found at the vehicle. The necessary repair costs are listed in the expert report or if necessary, are listed in detail in a separately enclosed repair cost calculation.

Comments

Die beigefügte Reparaturkostenkalkulation wurde nach bestem Wissen und Gewissen unter eingeschränkten Besichtigungsbedingung im demontagefreien Zustand erstellt. Es können aufgrund verdeckter Beschädigung erhebliche Mehrkosten und somit Abweichung der für den Unfall ausgewiesenen Reparaturkosten nicht ausgeschlossen werden.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel




Figure 9: Interior 360° view



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents




Figure 14: Navigation



Figure 15: Misc.




Figure 16: Misc.



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.




Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.




Figure 34: Misc.



Figure 35: Misc.



Damage 1: Door - front left side: Door - Scratch(es) - Smart repair




Damage 1: Door - front left side: Door - Scratch(es) - Smart repair



Damage 2: Misc.: Misc. (Reifendruckkontrolle) - on - Perform diagnosis



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 3: Sill - left side: Sill - Scratch(es) - Smart repair



Damage 4: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Defective - Replace




Damage 4: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Defective - Replace



Damage 4: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Defective - Replace



Damage 4: Wheel / tyres: Tyre - front right side (nicht fahrbereit) - Defective - Replace



Damage 5: Side panel - rear left side: Elbow - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Elbow - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Elbow - Dent / paintcoat damage - Smart repair



Damage 5: Side panel - rear left side: Elbow - Dent / paintcoat damage - Smart repair



Damage 6: Body: Underbody panelling - Broken / torn - Replace



Damage 6: Body: Underbody panelling - Broken / torn - Replace



Damage 6: Body: Underbody panelling - Broken / torn - Replace



Damage 6: Body: Underbody panelling - Broken / torn - Replace



Damage 6: Body: Underbody panelling - Broken / torn - Replace




Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 7: Wheel / tyres: Alloy rim - front right side - Scratched - Replace




Damage 8: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 8: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Damage 8: Mudguard - left side: Mudguard - left side - Scratch(es) - Paint



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right



Accident 1: Side right