DEKRA

DEKRA Automotive Solutions


Appraisal Report

Vehicle details

VIN	W0VZRHNS5 R6025837	Registration date	22/07/2024	Exterior Color	Unknown
Brand	OPEL	Licence Plate	F-SG 3858	Odometer	42 259 km
Model	GRANDLAND 1.2 Turbo 96kW GS Auto				

Inspection Details

Arrival Date	07/08/2026	Inspection ID	7103076	Inspection date	11/08/2026
Assign Date	07/08/2026	Fleet owner	Leasys Privat Leasing	Inspection loc.	Leasys AKB Zörbig



Generic equipment

Removable element

Toolkit	✓
Rear parcel shelf	✓
Floor mat BR	✓
Floor mat BL	✓
Floor mat FR	✓
Floor mat FL	✓
Spare wheel kit	✗


Technical Document

User manual	✓
Warranty booklet	✓
Log books	✓
Spare key	✓
Remote key	✓
Service	✗

Tyres

Goodyear 225/55/18 V All seasons 6.0 mm

Goodyear 225/55/18 V All seasons 6.0 mm



Goodyear 225/55/18 V All seasons 7.0 mm

Goodyear 225/55/18 V All seasons 7.0 mm

Exception / Damage

1



Part	Service	Repair Time	-	Part Cost	250.00€
Position	-	Repair Cost	-	Gross Cost	250.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**250.00€**

2



Part	Spare wheel kit	Repair Time	0.10	Part Cost	53.14€
Position	-	Repair Cost	14.00€	Gross Cost	67.14€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**67.14€**

3



Part	Service 2	Repair Time	-	Part Cost	250.00€
Position	-	Repair Cost	-	Gross Cost	250.00€
Damages	Missing	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Replace	Flat Rate	-	**Net Cost**	**250.00€**

4



Part	Wing	Repair Time	-	Part Cost	-
Position	Back right	Repair Cost	-	Gross Cost	30.00€
Damages	Scratched	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	Polishing	Flat Rate	30.00€	**Net Cost**	**30.00€**

5

Part	Bumper	Repair Time	-	Part Cost	-
Position	Front	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

6

Part	Bonnet	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

7

Part	Windscreen	Repair Time	-	Part Cost	-
Position	-	Repair Cost	-	Gross Cost	-
Damages	Worn out	Paint Time	-	Depreciation %	-
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

8

Part	Bumper	Repair Time	-	Part Cost	-
Position	Back	Repair Cost	-	Gross Cost	-
Damages	Scratched	Paint Time	-	Depreciation %	15.00%
Severity	-	Paint cost	-	Depreciation	-
Repair mode	For info	Flat Rate	-	**Net Cost**	**-**

Summary Inspection

Gross Price	597.14€	Depreciation	-	Net Price	597.14€

Labor cost summary

	Hourly Rate	Time	Gross Price	Depreciation %	Depreciation	Net Price
Bodywork	140.00€	0.10	14.00€	-	-	14.00€
Paintwork	0.00€	0.00	0.00€	-	-	0.00€
Paint preparation	0.00€	0.00	0.00€	-	-	0.00€

Miscellaneous

	Gross Price	Depreciation %	Depreciation	Net Price
Small parts / disposal charge	0.00€	-	-	0.00€
Part Cost	553.14€	-	-	553.14€
Flat Rate	-537.14€	-	-	-537.14€