TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Expertise

Protocol number: 48491806
Order No. / Reference: 27217950
Inspection date: 4 Nov 2026

Manufacturer: Mercedes-Benz	Model: B 200 d 8G-DCT Progressive Advanced
VIN: W1K4F1CB1RJ558598	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz B 200 d 8G-DCT Progressive Advanced	
Vehicle Identification number	W1K4F1CB1RJ558598
Mileage (Read)	206,796 km
First registration	5 Oct 2023
Number of holders	1
Fuel type	Diesel
Engine displacement / Cylinder	1,950 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic / 8
Type of drive	Front drive
Type of vehicle	Van
Colour / colour code	Nachtschwarz
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Anthracite

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Industriestraße 11
36272 Niederaula

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	296 Tag(e)
Last service on / at	08/2026 at 200,910 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GY503932
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	2222 / AHI 00114		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,090 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91W	Summer tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/55 R17 91W	Summer tyres on Light alloy	Pirelli	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	205/55 R17 91H	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	205/55 R17 91H	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 11/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Storage compartment in center console with roller blind
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation
- Airbag: Side airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Foldable armrest in the center console for driver and front passenger
- Outdoor temperature display
- Basic services
- Diesel particulate filter
- EASY-PACK tailgate
- Electronic Stability Program (ESP)
- Electric windows (4-way)
- Speed Limit Assistant
- Rear lights with taillights and brake lights using LED light guide technology
- Interior headliner fabric crystal grey
- Mechanical child safety lock
- Rear headrests (3)
- Paint finish: Solid
- LED High Performance headlights including Adaptive High Beam Assist
- Steering column mechanically adjustable in height and length
- Navigation: MBUX Navigation Premium
- Package: Seating comfort
- Package: USB Package Plus
- Radio: MBUX multimedia system
- Radio accessories: Digital radio
- Remote Services
- Seats: 4-way lumbar support for driver and front passenger
- Seats: Rear seat backrests foldable in a 40/20/40 ratio
- Lane Keeping Assist, active
- Cruise control
- Pre-installation for digital key handover
- Central locking with remote control
- ADAPTIVE BRAKE with hill start assist, HOLD function, pre-filling and drying braking in wet conditions
- Airbag: Kneebag for driver
- Airbag: Windowbag
- Traction control (ASR)
- ATTENTION ASSIST
- Heated exterior mirrors (left and right), electrically adjustable from inside
- Brake assist, active
- Third brake light in LED technology
- Door sills with "Mercedes-Benz" lettering
- Chassis: Comfort chassis with lowered suspension
- Velour floor mats
- Transmission: 8G-DCT automatic
- Rear window wiper with intermittent function
- Heated rear window with timer
- ISOFIX child seat attachment with top tether in the rear
- THERMATIC automatic climate control
- Front headrests are height-adjustable
- Cargo area cover
- Steering wheel: Multifunction sports steering wheel in leather
- Steering: Direct steering
- Mercedes-Benz emergency call system
- Package: Parking package with reversing camera
- Package: Mirror package
- Upholstery: ARTICO leatherette/Bertrix fabric
- Radio accessories: Central Media Display
- Tire pressure monitoring system
- Seat belts B-Class
- Seats: Comfort seats
- Heated seats for driver and front passenger
- Bumpers in body color
- TIREFIT with tire inflation compressor
- Electronic immobilizer
- Decorative elements Star Pattern

Extra equipment

- Rear armrest (with two integrated cupholders for drinks)
- THERMOTRONIC automatic climate control with 2 zones (individually adjustable temperature for driver and front passenger side, automatic control of temperature, air volume and air distribution, sensors maintain the desired climate constantly, continuous monitoring of the intake outside air for harmful gases with automatic recirculation, a fine dust activated carbon filter improves the air quality in the vehicle, dew point sensor prevents the windows from fogging up and enables energy-efficient climate control, rear center air vents)
- Package: Cargo area (12V socket in the luggage compartment - reversible mat - nets on the left and right sides - storage compartment under the left net - tension strap on the right side - net on the trunk floor)
- Package: Winter package (heated steering wheel - heated windshield washer system)
- Wheels: Winter complete wheels M+S 4-way 43.2 cm (17") (43.2 cm (17") light alloy wheels 5-twin-spoke design aerodynamically optimized, vanadium silver painted with 205/55 R17 on 6.5J x 17 ET44)
- Seats: Front right seat electrically adjustable with memory
- Phone accessories: Smartphone integration (consisting of Apple CarPlay and Android Auto)
- Fully digital instrument display (Experience the full range of digital display options. The large, high-resolution 10.25" display can be individually configured – for example, classically with speedometer on the left and tachometer on the right.)
- Chassis: Chassis with adaptive damping (adaptive damping for each wheel - different chassis settings Comfort, Sport and Individual, selectable via DYNAMIC SELECT switch - chassis level lowered by 15 mm - sport direct steering)
- Package: Driving Assistance (Active Distance Assist DISTRONIC (Active Speed Limit Assist, Extended Automatic Restart on Motorways, Route-Based Speed Adaptation with Traffic Jam Radio) - Active Steering Assist (Active Emergency Stop Assist with SOS Radio, Emergency Lane Radio) - Active Brake Assist (Turning and Intersection Function, Traffic Jam Emergency Braking Function) - Evasive Steering Assist - Active Lane Keeping Assist - Active Blind Spot Assist (Exit Warning Function) - Traffic Sign Assist (Pedestrian Warning Function in the Area of Zebra Crossings) - PRE-SAFE PLUS)
- PRE-SAFE System
- Wheels: Complete winter wheel sets fitted at the factory
- Seats: Driver's seat electrically adjustable with memory function
- Seats: Rear seats longitudinally adjustable
- Auxiliary heating
- Separation net
- Traffic Sign Assistant
- Elimination of type designation
- Dark tinted heat-insulating glass (rear side windows and rear window)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Equipment	Vehicle key with remote control (Batterie) - Empty - Replace
2	Side panel - rear right side	Side panel - dent(s) - Smooth repair work
3	Mudguard - right side	Mudguard - right side - dent(s) - Smooth repair work
4	Door - front right side	Door edge - Scratch(es) - Smart repair
5	Door - rear left side	Door edge - Scratch(es) - Smart repair
6	Body	B-pillar - left side - Dent / paintcoat damage - Smart repair
7	Door - rear right side	Door - Scratch(es) - Smart repair
8	Bonnet	Bonnet (Sandstrahleffekt) - Stone chips - Paint
9	Door - front left side	Door (Überall kleine Kratzer) - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Misc.	Main inspection - No evidence - No deduction
2	Boot lid / rear door	Boot lid - dent(s) - No deduction
3	Front bumper	Front bumper - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Missing parts

Description
2nd wheel set - Wheel cover set - complete (4x Nabendeckel)

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.

Comments

Die im Gutachten errechneten und angegebenen Minderwerte beziehen sich nur auf festgestellte Schäden oder Mängel, die über die normale Abnutzung entsprechend Fahrzeug-Alter und Laufleistung bzw. über das übliche Verschleißmaß hinausgehen.
Beschädigungen, die durch normalen Gebrauch während der Dauer der Nutzung entstanden sind, wurden nicht berücksichtigt (Gebrauchsspuren).



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)




Figure 5: Interior - front




Figure 6: Interior - rear




Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres




Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Navigation



Figure 16: Misc.



Figure 17: Misc.




Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.




Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 2: Side panel - rear right side: Side panel - dent(s) - Smooth repair work



Damage 3: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work



Damage 3: Mudguard - right side: Mudguard - right side - dent(s) - Smooth repair work



Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair




Damage 4: Door - front right side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 5: Door - rear left side: Door edge - Scratch(es) - Smart repair



Damage 6: Body: B-pillar - left side - Dent / paintcoat damage - Smart repair



Damage 6: Body: B-pillar - left side - Dent / paintcoat damage - Smart repair



Damage 6: Body: B-pillar - left side - Dent / paintcoat damage - Smart repair



Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 7: Door - rear right side: Door - Scratch(es) - Smart repair



Damage 8: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 8: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint



Damage 8: Bonnet: Bonnet (Sandstrahleffekt) - Stone chips - Paint




Damage 9: Door - front left side: Door (Überall kleine Kratzer) - Scratch(es) - Paint



Damage 9: Door - front left side: Door (Überall kleine Kratzer) - Scratch(es) - Paint



Damage 9: Door - front left side: Door (Überall kleine Kratzer) - Scratch(es) - Paint



Damage 9: Door - front left side: Door (Überall kleine Kratzer) - Scratch(es) - Paint



Damage 9: Door - front left side: Door (Überall kleine Kratzer) - Scratch(es) - Paint



Damage 9: Door - front left side: Door (Überall kleine Kratzer) - Scratch(es) - Paint



Missing part 1: 2nd wheel set: Wheel cover set - complete (4x Nabendeckel) - Missing - Replace