TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Expertise

Protocol number: 47746600
Order No. / Reference: 26744888
Inspection date: 22 Sept 2026

Manufacturer: Audi	Model: A3 35 TDI Limousine S line
VIN: WAUZZZGYXRA134385	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A3 35 TDI Limousine S line	
Vehicle Identification number	WAUZZZGYXRA134385
Mileage (Read)	52,390 km
First registration	4 Jun 2024
Number of holders	1
Next periodical technical inspection	06/2027
(Report not on hand)	
Fuel type	Diesel
Engine displacement / Cylinder	1,968 ccm / 4
Power	110 kW
Gearbox / Number of gears	Automatic /
Type of drive	Front drive
Type of vehicle	Saloon car
Colour / colour code	Gletscherweiss Metallic (S9R)
Doors / Seats	4 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	7,700 km
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	HB067298
Previous damage / Accident	None detectable	**Repainting**	None detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	yes
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZO 02081		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	1,950 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92Y	Summer tyres on Light alloy	Nexen	3mm / 3mm
2)	225/40 R18 92Y	Summer tyres on Light alloy	Nexen	3mm / 3mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R18 92V	Winter tyres (Without wheel rim)	Uniroyal	5mm / 4mm
2)	225/40 R18 92V	Winter tyres (Without wheel rim)	Uniroyal	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 03/2028		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Anti-lock braking system (ABS)
- Traction control ASR
- Audi pre sense front
- Evasive steering assist and turning assist
- Exterior mirror housings in body color
- Headliner in steel grey fabric
- Decorative strips in black glass look
- Rear parking sensors
- Electric auxiliary air heater
- Electromechanical parking brake
- Electronic Stability Control (ESC)
- Electric windows front and rear
- front and rear floor mats
- Transmission: 6-speed manual transmission
- Interior lighting
- i-Size child seat attachment and top tether for the outer rear seats
- Paint finish: Solid
- Light and rain sensor
- Radio: MMI Radio plus
- Tire repair kit
- Electromechanical power steering
- Seats: Rear seat backrest foldable
- Start-stop system
- 12V socket
- Electronic immobilizer
- Airbag: Front side airbags with head airbag system and front interaction airbag
- Audi connect emergency call & service m.connect remote & control
- Electrically adjustable and heated exterior mirrors
- third brake light
- Decorative inlays in silk-effect lacquer, platinum grey
- Additive-free diesel particulate filter (DPF)
- Door sill trims with aluminum inlay at the front, illuminated, with S lettering
- Electronic Differential Lock (EDS)
- Chassis: Sport chassis
- Remote key (without Safe-Lock)
- Speed limiter
- Heated rear window
- Electrically operated child safety lock
- Rear headrests (3)
- Front headrests
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction
- Tire pressure monitoring system
- Headlight
- 3-point automatic seat belts
- Lane Departure Warning
- 12-volt power outlet in the rear
- Glazing: Green tinted thermal insulation glazing
- Central locking with remote control

Extra equipment

- Adaptive cruise control (assists with acceleration, braking, and maintaining speed and distance. The adjustable speed limiter helps, for example, to prevent exceeding a preset maximum speed within built-up areas from approximately 30 km/h. Audi pre sense front uses a front radar to detect the area in front of the vehicle within the system's limits and warns of potential hazards with visual and audible signals.)
- Audi virtual cockpit (fully digital instrument cluster in a 10.25-inch display - can display speed, engine speed, map display, Audi connect services, radio and media information such as playback duration of media tracks or album cover display and much more, according to the driver's needs - the VIEW button in the multifunction steering wheel allows for intuitive and quick switching between two different sized displays of the round instruments)
- Hold assist (holds the vehicle after stopping on inclines and declines typical in road traffic for an unlimited time).
- 2-zone automatic climate control (electronically regulates air temperature, volume and distribution - separate temperature distribution for driver and front passenger side - with sun position-dependent control - automatic recirculation control - dust and odor separating allergen filter - air vents in the rear center console - separate defroster button for faster defrosting of the front and side windows)
- Paint finish: Metallic
- LED headlights and LED taillights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights (to reduce glare in poor visibility conditions), motorway lights, static cornering lights, maneuvering lights (illumination of the maneuvering area at the front and sides when reversing), automatic dynamic headlight range control, intersection lights (in conjunction with MMI Nav. plus), dynamic rear turn signals, brake lights, tail lights, rear license plate lights, reversing lights)
- S line interior package (front sport seats with manual adjustment of seat height, seat fore/aft position, seat tilt, backrest tilt and seat belt height, as well as headrests; fabric Puls/mono.pur 550-K synthetic leather upholstery; 3-spoke multifunction leather steering wheel including steering wheel grip and gearshift/selector lever knob in perforated leather; front/rear door armrests in synthetic leather; aluminum spectrum dark decorative inlays; illuminated front door sill trims with aluminum inlays and S logo; black fabric headliner; front center armrest; stainless steel floor mats, pedals and footrest)
- Wheel: Alloy wheels - 18 inch - 5-twin-spoke V (S-design), graphite grey (8.0 J × 18, tires 225/40 R 18)
- Radio accessories: Audi sound system
- Towing hitch
- Audi drive select (allows the desired vehicle characteristics to be set in various available modes via a separate control element in the switch panel of the center console and via the MMI operating system. This includes adjustments to the steering assistance, engine characteristics or shift points (in vehicles with S tronic), driving dynamics control, and other standard systems. If ordered, optional equipment is also adapted to the selected mode.)
- Exterior mirror housings in black
- Deletion of model designation and performance/technology lettering
- High-beam assist (within the system's limitations, it automatically detects oncoming headlights, taillights of other road users, and light sources in built-up areas. Depending on the traffic situation, the high beams are automatically switched on or off. The system thus improves the driver's visibility and increases comfort.)
- Comfort key with sensor-controlled luggage compartment unlocking (The vehicle can be unlocked wirelessly at all doors and the luggage compartment lid. The comfort key simply needs to be carried and does not need to be actively used. The vehicle can be locked again using the sensors on the door handles. The engine is started and stopped using the engine start/stop button. The tailgate can be conveniently unlocked and closed with a foot gesture (kick movement) at the rear.)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction plus
- Storage and luggage compartment package (lockable glove compartment - storage compartment on driver's side - storage net on the back of the front seatbacks - comfort cupholder - 12-volt socket in the trunk - luggage compartment net - second luggage compartment light on the left in LED (only for A3 Sportback))
- Ambient Lighting Package Plus (Glove box lighting (incandescent bulb), LED trunk lighting (right side), front/rear roof module including reading lights (LED), illuminated vanity mirrors (LED), entry lights on the underside of front doors (LED), front footwell lighting (LED), entry lights on the underside of rear doors (white), dashboard contour lighting (multicolor), ambient door lighting (front/rear, multicolor), door contour lighting (front/rear, multicolor), center console storage compartment (multicolor))
- Package: Black Optics Package Plus (Black optics package with Audi rings front and rear and model designation on the rear in black. On the S model, the model designation in the radiator grille is also finished in black)
- Radio accessories: USB Type-C charging cable, for Type-C devices
- Seat covers in Puls fabric/mono.pur 550 synthetic leather combination with S embossing (center section of the front and both outer rear seats in Puls fabric - side bolsters, headrests, middle rear seat and front center armrest (if ordered) in mono.pur 550 synthetic leather - with rock grey contrast stitching and S embossing in the backrests of the front seats)

- Reversing camera (captures the area behind the vehicle within the system limits. The display is adjusted according to the steering angle using dynamic display elements in the MMI touch display. The user can choose between perpendicular parking and trailer modes. Depending on the selected mode, the calculated driving lane or a guide line for coupling a trailer is displayed, also dependent on the steering angle. The reversing camera is activated by engaging reverse gear or via a button in the center console.)
- Front seat heating (heats seat and backrest center section (standard seats in fabric), otherwise seat and backrest center section as well as seat side bolsters - individually adjustable in 3 stages for driver and front passenger via direct selection button on the climate control unit)
- Glazing: Sun protection glazing, tinted (rear window, rear door and side windows tinted)
- Seats: Rear seat backrest foldable (three-part), with center armrest (split in a 40:20:40 ratio or fully foldable; with center armrest and cupholders)
- Lane change warning (assists the driver, e.g., in city traffic and when driving on multi-lane roads, by monitoring the traffic situation behind the vehicle. Two radar sensors installed in the rear detect vehicles approaching from the side and rear. The distance and speed difference can be measured and analyzed. If a situation is classified as critical for a lane change, a warning is issued via LED indicators on the respective side mirror.)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. Lifting equipment and/or a pit were available for examining the vehicle.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Misc.	Inspection / maintenance - No evidence - No deduction
2	Side panel - rear right side	Sill - dent(s) - Smooth repair work
3	Front bumper	Front bumper - Scratch(es) - Smart repair
4	Instrument panel	Indicator light (Fahrassistenz) - Specify findings - Perform diagnosis

Wear and tear

No.	Component group	Description
1	Body	Underbody panelling - Scratch(es) - No deduction
2	Vehicle glazing	Windscreen with lane departure assistant - Stone chips - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Paint coat thickness measurement

Roof	130 µm	Roof rail - left side	126 µm
Roof rail - right side	113 µm	Boot lid / rear door	110 µm
Mudguard - left side	117 µm	Mudguard - right side	117 µm
Bonnet	112 µm	Side panel - rear left side	115 µm
Side panel - rear right side	117 µm	Door - rear left side	124 µm
Door - rear right side	116 µm	Door - front left side	122 µm
Door - front right side	126 µm		

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

No apparent prior damage that had been repaired could be found on the vehicle.



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents




Figure 13: Documents




Figure 14: Documents



Figure 15: Additional tyres



Figure 16: Additional tyres



Figure 17: Additional tyres



Figure 18: Additional tyres



Figure 19: Additional tyres



Figure 20: Additional tyres




Figure 21: Navigation



Figure 22: Misc.




Figure 23: Misc.



Figure 24: Misc.




Figure 25: Misc.




Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.



Figure 33: Misc.



Figure 34: Misc.



Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.




Figure 38: Misc.



Damage 2: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 2: Side panel - rear right side: Sill - dent(s) - Smooth repair work



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair



Damage 3: Front bumper: Front bumper - Scratch(es) - Smart repair

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Compound Professionals
Wachau 2
89584 Ehingen



Damage 4: Instrument panel: Indicator light (Fahrassistenz) - Specify findings - Perform diagnosis