APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	AUDI
Model / version:	Q2
Vin:	WAUZZZGA2NA009961
Plate:	2BML727
Mileage:	64020
First registration:	13/01/2022
Color:	Manhattangri

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?


DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓

PICTURES















































VIN INFORMATION

Radio avec système de navigation
6 rapports
Lettre repère (J)
Largeur avant 6,5
Diamètre arrière 16
Indice de vitesse avant V
Largeur arrière 215
Accoudoir central avant
1.00 litre
TFSI
Freins arrière à disques
Volant cuir
Aide au stationnement arrière
Airbag passager désactivable
Protection piéton

radio avec récepteur numérique
ERA Glonass (appel d'urgence)
Audi Music Interface

norme anti-pollution Euro 6 AP

8 haut-parleurs
Traction avant
Diamètre avant 16
Largeur arrière 6,5
Hauteur avant 60
Indice de vitesse arrière V
Climatisation automatique
Essence
81 kw
Effet perle vernissée
Sièges avant réglable en hauteur
Volant sport
Equipement Stop & Start
Témoin d'oubli de ceinture avant
Freinage d'urgence assistée autonome (urbain)

rétroviseurs électrique et chauffants
système de navigation MMI High
Audi connect appel d'urgence & service avec contrôle du véhicule

Boîte manuelle
Matière : alliage
Diamètre arrière 16
Diamètre avant 16
Hauteur arrière 60
Largeur avant 215
Climatisation réfrigérant 1234YF
999 cm3
110 ch
Freins avant à disques
Garnitures tissu
Volant multifonction
Pare-brise avec bande pare-soleil
Témoin d'oubli de ceinture arrière
depuis 10.21

Audi Virtual Cockpit
barre stabilisatrice av 24 mm
réservoir à charbon actif (EVAP)

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Bridgestone	215/60/R16//95V	Summer	Aluminium	×
Front right	5 mm	Bridgestone	215/60/R16//95V	Summer	Aluminium	×
Rear left	5 mm	Bridgestone	215/60/R16//95V	Summer	Aluminium	×
Rear right	5 mm	Bridgestone	215/60/R16//95V	Summer	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Bumper F	Dent(s) and scratch(es)
3	Outside rear-view mirror housing R	Dent(s) and scratch(es)

Total: 2

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
2	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Bumper F - Dent(s) and scratch(es)





3 - Outside rear-view mirror housing R - Dent(s) and scratch(es)




2 - Bodywork - Dent(s) and scratch(es) - Renta®




SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

31/07/2026 14:08

