TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Expertise

Protocol number: 48377465
Order No. / Reference: 27199740
Inspection date: 26 Oct 2026

Manufacturer: Mercedes-Benz	Model: C 220 d T 9G-TRONIC AMG Line Advanced
VIN: W1KAH0EB5RF129469	





Vehicle details

Manufacturer / Type / Model / Equipment	
Mercedes-Benz C 220 d T 9G-TRONIC AMG Line Advanced	
Vehicle Identification number	W1KAH0EB5RF129469
Mileage (Read)	194,043 km
First registration	26 Sept 2023
Number of holders	1
Next periodical technical inspection	09/2026
(Report not on hand)	
Fuel type	Hybrid Diesel / E
Engine displacement / Cylinder	1,993 ccm / 4
Power	147 kW
Gearbox / Number of gears	Automatic / 9
Type of drive	Rear drive
Type of vehicle	Station wagon
Colour / colour code	GRAPHITGRAU MAGNO Metallic
Doors / Seats	5 / 5
Upholstery type	Artificial leather
Colour of upholstery	Black
Re-import	no
readiness to drive	Roadworthy

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	8,075 km
Last service on / at	06/2026 at 177,118 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GV740231
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
readiness to drive	Roadworthy		
Manufacturer key number/ type code number	2222 / AYH 00364		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,400 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/40 R19 93Y	Summer tyres on Light alloy	Goodyear	4mm / 4mm
2)	255/35 R19 96Y	Summer tyres on Light alloy	Goodyear	4mm / 4mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	225/45 R18 95H	Winter tyres on Light alloy	Goodyear	4mm / 4mm
2)	225/45 R18 95H	Winter tyres on Light alloy	Goodyear	6mm / 6mm

Replacement

Typ	Tyre size	Type of tyre	Manufacturer	Tread depth
	Tirefit	Expiration date 10/2026		

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Adaptive Highbeam Assist (automatic switching of the high beams on and off - camera on the inside of the windshield - detects oncoming and preceding illuminated vehicles - activated by pressing the steering wheel control lever to the high beam position)
- Airbag: Center airbag (Additional airbag for increased front occupant protection in the event of a side impact)
- Airbag: Sidebag for driver and front passenger (combined thorax/ pelvisbag)
- Ambient lighting with 64 light colors (Three dimming zones (Total, Ambient and Accent) - Variable brightness setting - 64 colors - Ten color moods - Integrated into the ENERGIZING comfort control programs)
- Left and right exterior mirrors are heated and electrically adjustable
- Brake system with larger brake discs on the front axle
- Brake assist, active
- Diesel particulate filter
- DYNAMIC SELECT (consisting of driving programs: Comfort, Sport, Eco mode)
- Electronic Stability Program (ESP) (including Anti-lock Braking System (ABS) and Traction Control System (ASR))
- Chassis: AGILITY CONTROL chassis with selective damping system and lowered suspension
- Fingerprint scanner (Color-illuminated fingerprint scanner in the control bar below the central display - Two fingerprints can be stored per user - Fast access replaces PIN entry - Protects personal data such as profiles as well as office and payment functions)
- Black fabric headliner
- ISOFIX child seat attachment with top tether in the rear
- KEYLESS-GO start function
- Rear headrests (3)
- Fuel tank with larger volume 66 l
- LED High Performance headlights (low beam with LED projection technology, high beam with LED reflection technology, daytime running lights, position lights and direction indicators in LED technology, adaptive full-LED taillights with automatic adjustment of light intensity to the surroundings)
- Mercedes-Benz emergency call system (can provide a crucial time advantage in an emergency. A communication module with its own SIM card automatically triggers an emergency call upon detection of an accident, which can shorten the time until emergency services arrive. The emergency call can also be triggered manually to organize assistance.)
- Package: Storage (Luggage net on the left side panel in the trunk/ cargo area - Elastic tension strap on the right in the cargo area (only for the T-Model) - Folding box under the load floor (not available for plug-in hybrid vehicles) - Double cup holder in the center console for 2 x 750 ml - Map pockets on the back of the front seats)
- Airbag for driver and front passenger
- Airbag: Automatic passenger airbag deactivation (The system automatically deactivates the passenger airbag as soon as it detects a rear-facing child seat or registers that the passenger seat is unoccupied. A transponder in the child seat is not necessary. If it detects that an adult is taking the seat, the airbag is automatically activated, reducing the risk of incorrect operation.)
- Airbag: Windowbag for driver and front passenger
- AMG floor mats
- ATTENTION ASSIST (the attention assistant) (can detect typical signs of fatigue through driver behavior and warn the driver of increasing fatigue or inattentiveness)
- Basic services (breakdown management, maintenance management, accident management, telediagnosis, remote vehicle diagnostics)
- Roof rails in matte black
- Double cup holder at the front
- EASY-PACK tailgate (with electric operation for opening and closing)
- Driver display (31.2 cm (12.3") color LCD display with a resolution of 2400 x 900 pixels - five different menus with specific content and display styles)
- Electric windows (4-way)
- Speed Limit Assistant (The Speed Limit Assistant detects and displays speed limits.)
- Transmission: 9-speed automatic, 9G-TRONIC
- rear window wiper
- Heated rear window
- Instrument panel and door sills in ARTICO man-made leather with a nappa leather look
- Mechanical child safety lock for the rear doors
- Front headrests
- Cargo area cover including EASY-PACK safety net
- Steering wheel: Multifunction sports steering wheel in Nappa leather (sporty steering wheel in a 3-twin-spoke design, flattened at the bottom - finished in Nappa leather, deeply embossed in the grip area - horizontal double spokes in high-gloss black, vertical double spokes in silver chrome - shift paddles in silver chrome - control via touch panels: left: instrument cluster, cruise control and limiter or Active Distance Assist DISTRONIC; right: multimedia system (e.g., audio volume and track selection, telephony and navigation), touch sensitivity adjustment)
- Center console in high-gloss black
- Navigation: MBUX Navigation Premium (Pre-installation for navigation services - Package (control code) - Multimedia / Digital content - Hard disk navigation - Pre-installation for Live Traffic Information - Communication module (LTE) for the use of Mercedes me connect services)
- Package: AMG Line Advanced (00U Remote Services - 70B Warning vest for driver - P29 AMG Line Interior - P31 AMG Line Exterior - PBG MBUX Navigation Premium)

- Package: Interior lighting package (Illuminated glove compartment - Lighting for wireless mobile interface or mobile phone storage - Lighting for the storage compartment in the center console or the double cupholder - Lighting for the storage compartment under the armrest of the center console - Two makeup lights in front - Two reading lights in the overhead control unit - Two reading lights and interior light function in the grab handles in the rear - Lighting for the trunk or cargo area)
- Package: Seating comfort (various electric and manual adjustment options for the front seats to adapt to the specific body and comfort requirements of driver and front passenger - electro-pneumatic 4-way lumbar support - electric seat cushion tilt adjustment - electric height adjustment - electric backrest adjustment - electric seat cushion depth adjustment by 6 cm with leg rest pad - mechanical longitudinal adjustment - mechanical headrest adjustment)
- Package: USB (2 USB-C ports under the front center armrest, suitable for data transfer)
- Radio: Extended MBUX functions (personalization (profiles) and prediction functions - MBUX voice assistant with natural language understanding - activation via "Hey Mercedes" - learning function of the MBUX voice assistant by connecting to a cloud-based online dictionary - Wi-Fi hotspot - internet radio)
- Radio accessories: Digital radio (DAB)
- Radio accessory: Communication module (LTE) for using Mercedes me connect services (The communication module with a vehicle-integrated, LTE-enabled SIM card offers you added comfort and safety. It continuously connects you to your vehicle – and the vehicle to infrastructure such as the Mercedes-Benz server or the internet. This allows you to use services such as Mercedes me connect Live Traffic Information.)
- Tire pressure monitoring system (TPMS)
- Windscreen wipers with rain sensor
- Power steering
- Seats: Heated seats for driver and front passenger (Pleasant warmth and therefore high seating and travel comfort. In cooler weather or according to your personal preference, the seat heating quickly brings the seat surfaces and backrests to a comfortable temperature. The intensity can be selected in three levels. Intelligent and convenient: The seat heating switches off automatically.)
- Telephone accessories: Smartphone integration (wirelessly connects the mobile phone to the MBUX multimedia system - display of selected third-party apps - access to current software and data, e.g., for navigation, traffic information, contact data, messaging, telephony, media, IP radio - optimized user interface for driving - control of smartphone functions via voice control)
- Cruise control
- Fully digital instrument display (Freestanding, fully digital instrument display with a 26 cm (10.25") color LCD display and a resolution of 1440 x 540 pixels)
- High-visibility vest for drivers
- Electronic immobilizer
- Package: Luggage compartment comfort (electrically folding rear seat backrests via switches on the right and left in the control panel in the load compartment - electric opening and closing of the load compartment roller blind - 12V socket on the left in the control panel in the load compartment - reversible mat, with a rubberized, non-slip side and a soft velour side)
- Package: Parking package with reversing camera (12 ultrasonic sensors - reversing camera: integrated into the boot lid, display in the central display, trailer mode - Active Parking Assist with PARKTRONIC - detects free parking spaces - assisted parking - visual and acoustic warning of detected obstacles - display of camera and ultrasonic data in the central display - button for Active Parking Assist - cross traffic warning - reverse maneuvering braking - drive-away assist)
- Package: Mirror package (both exterior mirrors electrically folding (button in the driver's door control panel) - interior mirror and exterior mirror on the driver's side automatically dimming continuously - ambient lighting of the exterior mirror to illuminate the entry area with projection of the Mercedes-Benz logo)
- Radio: MBUX multimedia system (instrument display with 17.78 cm (7") diagonal - media display with 17.78 cm (7") diagonal and touch function - touch control buttons on the steering wheel - radio (FM/AM) - USB interface in the center console under the armrest - Bluetooth telephony with contact transfer and audio streaming of music files - display of vehicle functions (driver assistance systems, driving programs and vehicle settings) - favorites storage - smartphone-related voice control)
- Radio accessories: Central display (touchscreen display with LCD technology - 30.2 cm (11.9") screen diagonal - resolution of 1,624 x 1,728 pixels (width x height) - tilted 6° - 7° towards the driver)
- Remote Services (Communication module - Mercedes me services: -Programming of auxiliary heating/ventilation: -Remote door locking and unlocking -Sunroof/windows with remote locking and opening including ventilation function -Personalization -Vehicle location -Vehicle tracking -Geographic vehicle monitoring -Parking service monitoring -Find function (Remote Vehicle Finder))
- Seats: Rear seat backrests foldable
- Lane Keeping Assist, active
- Telephone accessories: Wireless charging system for mobile devices (wireless charging according to Qi standard for compatible mobile phones - fast connection setup between multimedia system and mobile phone via Near Field Communication (NFC) for identification of the mobile device - storage compartment for wireless charging is located in the storage compartment at the front of the center console)
- TIREFIT with tire inflation compressor
- Pre-installation for digital key handover (Share your vehicle key even without personal handover - Decide to whom you open the vehicle and hand over the key - Use the functions conveniently in the Mercedes me app)
- Central locking with remote control

Extra equipment

- Towbar with ESP trailer stabilization
- Chassis: Sport chassis with sport direct steering
- Package: AMG Line Advanced Plus (electrically adjustable driver's seat with memory function - Blind Spot Assist - Illuminated door sills with "Mercedes-Benz" lettering - Traffic Sign Assist)
- Package: ENERGIZING Plus (ENERGIZING Plus comfort programs: warmth, joy, coziness, freshness, vitality, training - ENERGIZING COACH with individual program recommendations through evaluation of driving and vehicle data as well as driver data if required - Multicontour seats for driver and front passenger - Electro-pneumatic 4-way lumbar support - Seat climate control for driver and front passenger - Seat heating - AIR-BALANCE program for fragrance, ionization and purification of the air, active in all ENERGIZING programs - Ambient lighting with program-specific lighting moods)
- Package: Parking package with 360° camera (12 ultrasonic sensors: six each in the front and rear bumpers - 360° camera - Active Parking Assist with PARKTRONIC: detects parking spaces, assisted parking, assisted exiting, visual and acoustic warning of detected obstacles according to distance and position, display of camera and ultrasonic data in the central display, button for Active Parking Assist with PARKTRONIC - cross traffic warning - maneuvering braking - drive-away assist)
- Radio accessories: Pre-installation for MBUX Entertainment (integration of music streaming services (user account required): Spotify, Amazon Music, Apple Music, TIDAL, TuneIn (no user account required) - Extended radio information - Extended radio station tracking - Internet radio - Third-party convenience data volume)
- Wheels: Complete summer wheel sets fitted at the factory
- Wheels: Winter complete set of wheels M+S 4x 45.7 cm (18") multi-spoke alloy wheels (black painted and polished with 225/45 R 18 on 7.5 J x 18 ET 40)
- Heat-insulating dark tinted glass
- Driver assistance package
- Paint finish: MANUFAKTUR graphite grey magno
- Package: AMG Line Premium Plus (Electrically adjustable driver's seat with memory function - Blind Spot Assist - Illuminated door sills with "Mercedes-Benz" lettering - Traffic Sign Assist - DIGITAL LIGHT - Parking Package with 360° camera - MBUX Augmented Reality for navigation - KEYLESS-GO Comfort Package - Panoramic sliding sunroof - Head-up display - DIGITAL LIGHT with projection function - THERMOTRONIC automatic climate control - Burmester 3D surround sound system)
- Package: Night (for T-Model with AMG Line exterior) (Radiator grille with Mercedes-Benz pattern and black, high-gloss louvre (18") AMG light-alloy wheels in 5-spoke design, aerodynamically optimized, black-painted, polished, with front axle 225/45 R18 on 7.5Jx18 ET40, rear axle 245/40 R18 on 8Jx18 ET52 AMG front apron with trim panel (wing) in high-gloss black. Rear bumper with trim panel (wing) in high-gloss black. Belt trim strip and window surrounds in high-gloss black. Exterior mirror housings in high-gloss black. Heat-insulating dark-tinted glass at the rear (from the B-pillar). Roof rails in black.)
- Upholstery: ARTICO black leatherette
- Radio accessories: Sound personalization (A tailor-made listening experience: Personalizing the sound system makes it easy to achieve your perfect sound setup. A setup assistant with an innovative algorithm works with you to determine your music preferences and adjusts the Burmester sound system to your wishes. The result is saved in a personal profile.)
- Wheels: 48.3 cm (19") AMG light-alloy wheels in 5-twin-spoke design (aerodynamically optimized, painted black and high-sheen finish with front axle 225/40 R 19 on 7.5 J x 19 ET 40, rear axle 255/35 R 19 on 9 J x 19 ET 58, 1)
- Auxiliary heater (water heater)
- Heat and noise insulating acoustic glass (for windshield and front doors)
- AMG Carbon trim elements

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.
readiness to drive	The vehicle was roadworthy at the time of inspection.

Value reducing factors

No.	Component group	Description
1	Equipment	Tirefit filler - Empty - Replace
2	Interior	Cargo area floor - Soiled - Clean
3	Door - front left side	Door edge - Scratch(es) - Loss in value
4	Side panel - rear left side	Side panel - dent(s) - Smooth repair work
5	Misc.	Main inspection - Due - Perform
6	2nd wheel set	1 tyre - Broken / torn - Replace
7	Front bumper	Spoiler (Zierleiste) - Broken / torn - Replace
8	Rear bumper	Rear bumper - Scratch(es) - Paint
9	Vehicle glazing	Windscreen - Stone chips - Replace

Wear and tear

No.	Component group	Description
1	2nd wheel set	2 tyres (Über 4mm) - No deduction
2	Wheel / tyres	Alloy rim - front right side - Scratch(es) - No deduction
3	Wheel / tyres	Alloy rim - front left side - Scratch(es) - No deduction
4	Bonnet	Bonnet - Stone chips - No deduction
5	Front bumper	Front bumper - Stone chips - No deduction
6	Wing mirror - right side	Cap - Scratch(es) - No deduction
7	Door - rear right side	Door - Scratch(es) - No deduction
8	Door - rear left side	Door - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Front, Provided by user / customer, from 30 Sept 2026	2.799,98 €
2	Front, Provided by user / customer, from 25 Apr 2024	4.335,97 €

Repainting

No.	Repainting
1	Roof rail - right side, Professionally carried out
2	Side panel - rear right side, Professionally carried out

Paint coat thickness measurement

Roof rail - right side	160 µm	Side panel - rear right side	168 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
Hartmann Fleet Professionals GmbH
Leerenstraße 25
29683 Bad Fallingbostel



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel

Figure 9: Interior 360° view (Online Link)



Figure 10: Cargo area



Figure 11: VIN



Figure 12: Mounted tyres



Figure 13: Documents



Figure 14: Additional tyres



Figure 15: Additional tyres



Figure 16: Navigation



Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.



Figure 22: Misc.



Figure 23: Misc.



Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.




Figure 28: Misc.



Damage 1: Equipment: Tirefit filler - Empty - Replace



Damage 1: Equipment: Tirefit filler - Empty - Replace




Damage 2: Interior: Cargo area floor - Soiled - Clean



Damage 2: Interior: Cargo area floor - Soiled - Clean



Damage 3: Door - front left side: Door edge - Scratch(es) - Loss in value



Damage 3: Door - front left side: Door edge - Scratch(es) - Loss in value



Damage 3: Door - front left side: Door edge - Scratch(es) - Loss in value



Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 4: Side panel - rear left side: Side panel - dent(s) - Smooth repair work



Damage 6: 2nd wheel set: 1 tyre - Broken / torn - Replace



Damage 6: 2nd wheel set: 1 tyre - Broken / torn - Replace



Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace




Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace



Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace



Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace



Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace




Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace



Damage 7: Front bumper: Spoiler (Zierleiste) - Broken / torn - Replace




Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 8: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Damage 9: Vehicle glazing: Windscreen - Stone chips - Replace



Repainting 1: Roof rail - right side



Repainting 1: Roof rail - right side



Repainting 2: Side panel - rear right side



Repainting 2: Side panel - rear right side