Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Wolfgang Denzel
Erdbergstraße 191
1030 Wien

Inspection date: 18 May 2026
Protocol number: 45558897

WBA81DB040CU53957

Vehicle details

Operator		**Inspection condition**	Conditional: Light/moisture/dirt
License number		**Mileage (Read)**	401 km
Manufacturer	BMW	**Next maintenance in**	30,000 km
Type / Model	420i Cabrio Aut	**Main inspection (Report not on hand)**	04/2028
Vehicle Identification number	WBA81DB040CU53957	**Power / Engine displacement**	135 kW / 1,998 ccm
First registration	16 Apr 2025	**Upholstery/Colour**	Leather / Brown
Last maintenance		**Paintwork**	Black
Fuel type	Petrol	**Gearbox**	Automatic

Zustandsbericht

Value reducing factors

No.	Component group	Description
1	Electronic systems	Electronic systems (Batterie leer Kostenfolgen möglich) - Defective - Perform diagnosis
2	Side panel - rear right side	Side panel (Kostenfolgen möglich) - Abrasion - Conditioning
3	Door - front left side	Door - Scratch(es) - Paint
4	Side panel - rear left side	Side panel - Scratch(es) - Repair and paint

Wear and tear

No.	Component group	Description
1	Body	Body (Kostenfolgen möglich) - Soiled - No deduction

Missing parts

Missing part

Detected repainting

No.	Location

Main tyres

Axle	Tyre size	Manufacturer	Type of tyre	Tread depth	Roadworthy	Permissibility
1	225/45 R18	Bridgestone	Summer tyres	7mm - 7mm	Not o.k.	
2	225/45 R18	Bridgestone	Summer tyres	7mm - 7mm	Not o.k.	

The wear and tear condition and possible damages to the tyres are considered in the value.

Equipment

Standard equipment

Code	Description
-	12V power outlet
-	2-year warranty
-	Airbag for driver and front passenger
-	Ambient lighting
-	Anti-lock braking system (ABS)
-	Attention assistant
-	BMW ID
-	BMW iDrive
-	BMW Live Cockpit
-	BMW Live Cockpit Plus with BMW Curved Display
-	Center lock switch
-	Central locking system
-	Centre console - rear
-	convertible top
-	Crash sensor
-	cup holder
-	DAB tuner
-	Door sills
-	Driving experience switch
-	Dynamic Stability Control (DSC) with extended features
-	Electric seat adjustment with memory
-	electric window regulator
-	Electrically adjustable and heated exterior mirrors
-	Exhaust tips visible
-	Hands-free device with USB interface
-	Headlight range control
-	Heat/sun protection glazing
-	Heated seats for driver and front passenger
-	Home lights
-	Illuminated glove box with separate small compartment
-	Interior and exterior mirror package
-	Interior trim strips 'Dark Graphite' matt
-	ISOFIX child seat attachment
-	Lashing eyes in the luggage compartment
-	LED headlights
-	LED license plate lights
-	LED taillights
-	luggage compartment light
-	M High Gloss Shadow Line
-	Model lettering

Code	Description
-	Multifunction for steering wheel
-	Oil level and quality sensor
-	Otto particulate filter (OPF)
-	Park Distance Control (PDC)
-	Parking Assistant, 17" alloy wheels V-spoke 778 Reflex Silver
-	Rain sensor
-	Sensatec perforated padding
-	Servotronic
-	Shift point indicator
-	Side airbag for driver and front passenger
-	Solid color paint
-	Speaker system with 6 speakers
-	Speed Limiter
-	Sports steering wheel
-	Standard seats for driver and front passenger in sports seat geometry
-	Standard suspension
-	Steering column adjustment
-	through-loading system
-	Tire pressure monitoring
-	Tire Pressure Monitoring System (RPA)
-	tire repair kit
-	Tool set
-	Traction control
-	Transmission: Steptronic Sport transmission
-	Velour floor mats
-	Warning triangle with first aid kit
-	Welcome light
-	Widescreen Display

Extra equipment

Code	Description
05AQ	Active Guard Plus
08TF	Active pedestrian protection
A090	AGM battery 90 Ah
0302	Alarm system
04UR	Ambient interior lighting
0534	Automatic air conditioning
0491	Backrest width adjustment driver
04NE	Blow-by heater
06U3	BMW Live Cockpit Professional
01HX	BMW LM wheel double sp. 848M HOURS SO BIC
01CB	CO2 scope
08R3	COC ADDITIONAL PACKAGES
0322	Comfort access
06AK	Connected Drive Services
06C4	Connected Package Professional
08WM	Control D
08WD	Control of driver assistance systems
0544	Cruise control with braking function
0654	DAB tuner (DAB+ capable)
05AS	Driving Assistant
0230	EU-specific additional scopes
01DF	EU6 rde II emissions standard
0851	German language version
07LG	Guidance Package
0688	Harman/Kardon surround sound system
0494	Heated seats for driver and passenger
0760	High-gloss Shadow Line
06VB	Infotainment controls
07A2	Innovation Package II
04LN	INT. PERFORMS. ALU. RHOMBICLE ANTHR.
0431	Interior mirror automatically dimming
0430	Interior/exterior mirrors with automatic dimming
06AF	Legal emergency number
0488	Lumbar support for driver and front passenger
04NW	LUXURY INSTRUMENT PANEL
0715	M Aerodynamics Package
0710	M leather steering wheel
0337	M Sport Package
0704	M Sport suspension
04NH	Neck warmer
0548	odometer
08KA	Oil change interval: 24 months/30,000 km

Code	Description
0879	Onboard literature in German
05DN	Parking Assistance System Plus
05DA	Passenger airbag deactivation
06PA	Personal eSIM
09QX	Preparation for Driver Assistance I
08R9	Refrigerant R1234yf
02TB	Sport automatic transmission
0493	Storage package
06NX	Storage tray wireless charging
06AE	Teleservices
02VB	Tire pressure gauge
02VC	Tyre repair kit
02VL	Variable sport steering
0428	Warning triangle and first aid kit
02PA	Wheel bolt lock
0387	Windbreak

Comments

Dieses Gutachten wurden in Verantwortung von Ing. Martin Lennes, allgemein beeideter und gerichtlich zertifizierter Sachverständiger, erstellt.

Die o.a. Serienausstattung des Fahrzeuges basiert auf Angaben der Firma Eurotax und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Die o.a. Sonderausstattung des Fahrzeuges stammt aus dem BMW System Myair und Macadam Austria übernimmt daher für deren Inhalt keine Haftung.

Macadam Austria GmbH
Europaplatz 2/1/2
1150 Wien

Inspection location
Wolfgang Denzel
Erdbergstraße 191
1030 Wien

Inspection date: 18 May 2026
Protocol number: 45558897

Vehicle details

Manufacturer	BMW	**Inspection condition**	Conditional: Light/moisture/dirt
Type / Model	420i Cabrio Aut	**Mileage (Read)**	401 km
Vehicle Identification number	WBA81DB040CU53957	**First registration**	16 Apr 2025

Details of the order:
In accordance with the contract, the evaluation of vehicle's condition was performed without the vehicle being disassembled.

This product is based on the Austrian standard ÖNORM V5080. The expert makes the explicit findings in each individual case objectively within the framework of the specified standards based on their own expertise.

Vehicle identification:
The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.

Inspection conditions:
A proper visual inspection of the paintwork and bodywork was only possible to a limited extent due to insufficient lighting conditions/dampness or dirt.

General condition:
The vehicle shows traces of wear and tear corresponding to its age and purpose

Overview pictures



Figure 1: Diagonal front



Figure 2: Diagonal front



Figure 3: Diagonal rear



Figure 4: Diagonal rear




Figure 5: Interior




Figure 6: Interior



Figure 7: Interior




Figure 8: Interior



Figure 9: Interior




Figure 10: Interior



Figure 11: Interior




Figure 12: Interior



Figure 13: Misc.




Figure 14: Misc.



Figure 15: Misc.




Figure 16: Misc.




Figure 17: Misc.



Figure 18: Misc.



Figure 19: Misc.



Figure 20: Misc.




Figure 21: Misc.


Pictures of damage



Damage Electronic systems: Electronic systems: Electronic systems (Batterie leer Kostenfolgen möglich) - Defective - Perform diagnosis




Damage Electronic systems: Electronic systems: Electronic systems (Batterie leer Kostenfolgen möglich) - Defective - Perform diagnosis



Damage Side panel - rear right side: Side panel - rear right side: Side panel (Kostenfolgen möglich) - Abrasion - Conditioning




Damage Side panel - rear right side: Side panel - rear right side: Side panel (Kostenfolgen möglich) - Abrasion - Conditioning



Damage Side panel - rear right side: Side panel - rear right side: Side panel (Kostenfolgen möglich) - Abrasion - Conditioning




Damage Side panel - rear right side: Side panel - rear right side: Side panel (Kostenfolgen möglich) - Abrasion - Conditioning




Damage Door - front left side: Door - front left side: Door - Scratch(es) - Paint



Damage Door - front left side: Door - front left side: Door - Scratch(es) - Paint




Damage Door - front left side: Door - front left side: Door - Scratch(es) - Paint




Damage Door - front left side: Door - front left side: Door - Scratch(es) - Paint



Damage Side panel - rear left side: Side panel - rear left side: Side panel - Scratch(es) - Repair and paint



Damage Side panel - rear left side: Side panel - rear left side: Side panel - Scratch(es) - Repair and paint



Damage Side panel - rear left side: Side panel - rear left side: Side panel - Scratch(es) - Repair and paint