TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Expertise

Protocol number: 48463061
Order No. / Reference: 27205403
Inspection date: 2 Nov 2026

Manufacturer: Audi	Model: A6 Avant 55 TFSI e quattro S tronic sport
VIN: WAUZZZF26PN018636	





Vehicle details

Manufacturer / Type / Model / Equipment	
Audi A6 Avant 55 TFSI e quattro S tronic sport	
Vehicle Identification number	WAUZZZF26PN018636
Mileage (Read)	75,692 km
First registration	19 Oct 2022
Number of holders	1
Next periodical technical inspection (Report on hand)	11/2027
Fuel type	Hybr.B/E ext.aufl
Engine displacement / Cylinder	1,984 ccm / 4
Power	195 kW
Gearbox / Number of gears	Automatic / 7
Type of drive	All-wheel drive
Type of vehicle	Station wagon
Colour / colour code	Gletscherweiss Metallic
Doors / Seats	5 / 5
Upholstery type	Cloth / leather combination
Colour of upholstery	Black-Red

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt

Vehicle details

Maintenance booklet / proof	digital proof / complete	**Next maintenance in**	1,800 km
Last service on / at	08/2025 at 55,635 km		
Key is / should be	2 / 2	**FZG documents**	ZB#2 (B) was available (copy), ZB#1 (S) was not available.
		Letter No.	GM797544
Previous damage / Accident	Detectable	**Repainting**	Detectable
Inspection conditions	sufficient	**Lifting equipment / pit**	No
Test drive	Not performed	**Engine function test**	Performed
Manufacturer key number/ type code number	0588 / BZF 00442		
Emission standard	EURO6	**fine dust sticker**	
Permitted total weight	2,675 kg	**Empty weight**	

Tyres

Mounted tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	255/40 R20 104Y	Summer tyres on Light alloy	Goodyear	6mm / 6mm
2)	255/40 R20 104Y	Summer tyres on Light alloy	Goodyear	6mm / 6mm

Additional tyres

#	Tyre size	Type of tyre	Manufacturer	Tread depth
1)	245/45 R19 102V	Winter tyres on Light alloy	Pirelli	5mm / 5mm
2)	245/45 R19 102V	Winter tyres on Light alloy	Pirelli	5mm / 5mm

Legend: Tread depth information for the left tire is listed first, for the right tire it is listed second on the axle in the direction of travel.

Equipment

Standard equipment

- Airbag for driver and front passenger
- Acoustic vehicle warning system
- Anti-lock braking system (ABS)
- Audi connect emergency call & service m.connect Remote & Control (TFSI e)
- Audi virtual cockpit
- Exterior mirror housings in black
- Brake calipers, painted red
- Decorative inlay in dark, matt brushed aluminum
- e-tron compact charging system
- Electronic Stability Control (ESC)
- Chassis: Sport chassis (with firmer spring and damping for more direct road contact and sportier handling, lowered by 20 mm compared to standard chassis, shock absorbers and coil springs on front and rear axles)
- Interior lighting
- ISOFIX child seat attachment and Top Tether for the outer rear seats
- AC Type 2 charging socket
- Steering wheel: Sport contour leather steering wheel in 3-spoke design, multifunction and shift paddles, flattened at the bottom.
- Steering column, manually adjustable in height and axis
- MMI Navigation with MMI touch response (10.1-inch color display (1,540 × 720) additional display of the navigation map or arrow display in the driver information system map update 3D map display efficiency assistant online traffic information MMI search MMI touch response for quick, intuitive operation easy operation of the infotainment system via natural language interaction detailed route information input of up to 10 waypoints selected portfolio Audi connect Navigation & Infotainment)
- Seats: 4-way lumbar support
- Seats: Split-folding rear seat backrest Avant
- Seats: Front sports seats
- Sun visor on driver and passenger side
- Lane Departure Warning
- Stationary air conditioning
- Start-stop system
- Glazing: Windscreen in heat-insulating glazing
- Electronic immobilizer
- Central locking
- Airbag: Front side airbags and head airbag system
- "quattro" all-wheel drive with ultra technology
- Audi connect navigation & infotainment
- Audi drive select
- Audi pre sense front
- Electrically adjustable and heated exterior mirrors
- third brake light
- Fabric headliner
- Tachometer
- Door sills with aluminum inlay, front and rear, illuminated
- Driver information system with color display
- key fob
- Luggage compartment lid, electrically opening and closing
- Cruise control system including speed limiter
- Transmission: S tronic 7-speed
- Interior mirror dimming
- 4-zone automatic climate control
- Headrests (4)
- Mode 3 charging cable (charging cable for charging at public AC charging stations (Type 2). The cable connects the charging station to the vehicle's AC charging port and enables a charging power of up to 7.4 kW at your vehicle.)
- front center armrest
- Otto particulate filter
- Non-smoking package
- Black Optics Package
- Pedals and footrest in stainless steel
- Progressive steering
- Wheel: Tire pressure monitoring system
- Wheel: Tire repair kit
- Rail system with fixing set
- Seat covers in Dinamica Frequency microfiber/leather combination with S embossing (center section of the front seats and the two outer rear seats in Dinamica Frequency microfiber - side bolsters, headrest center sections and center armrest in black or rotor grey leather with contrasting stitching - with S embossing in the backrests of the front seats)
- Phone: Audi smartphone interface
- Glazing: Privacy glazing (tinted windows)
- Thermal insulation glazing on the sides and rear

Extra equipment

- Business Package (Assistance Package Tour: Adaptive Driving Assistant supports the driver with acceleration, braking, maintaining speed and distance, and lane keeping. Adaptive Cruise Control, Speed Limiter. Efficiency Assistant supports the driver with predictive driving. Parking Aid Plus, 4-zone automatic climate control, heated front seats, Audi phone box, automatically dimming interior mirror, automatically dimming exterior mirrors, adaptive windscreen wipers with integrated washer nozzles, high-beam assistant)
- Comfort key with sensor-controlled luggage compartment unlocking (The vehicle can be opened by operating the door handle without actively using the key. To lock the vehicle from the outside, simply touch one of the sensor buttons on the door handles. The drive authorization is also activated without actively using the comfort key. The driver must be inside the vehicle and have the comfort key with them. The engine is started and stopped using the engine start/stop button in the center console.)
- Comfort stationary climate control (cools or heats the interior as needed before driving for a high level of climate comfort right from the moment you get in. Stationary climate control can be programmed or activated via the MMI or smartphone app, regardless of whether the vehicle is charging at the time. A "short climate control" cycle can be started when unlocking the vehicle with the remote key. Additional seat heating and ventilation, steering wheel and glass surface heating can be activated if these optional equipment has been selected.)
- Decorative inlays in carbon fiber body structure (for dashboard, door panels and center console; including aluminum-look trim)
- Electric steering wheel adjustment (adjustable in height and distance, with automatic entry and exit)
- Glazing: Windscreen in climate comfort/acoustic glazing, wirelessly heated (heated windscreen made of climate comfort/acoustic glass, facilitates rapid defrosting and ensures fog-free operation through surface heating without obstructing heating wires; with heated wiper blade rest; with viewing window for telepass devices)
- ISOFIX child seat attachment for the front passenger seat (with deactivation switch for passenger airbag including electric child safety lock for the rear doors)
- LED headlights: HD Matrix LED headlights with dynamic turn signals (daytime running lights, low beam, high beam, position lights, turn signals, cornering lights, all-weather lights, motorway lights, adaptive headlights, automatic headlight range control, intersection lights, headlight cleaning system, LED taillights with dynamic light display and dynamic turn signals)
- Package: Ambient lighting package plus (contour lighting front/rear doors, color-matched - ambient fabric lighting front/rear doors, color-matched - ambient lighting front center console, color-matched - contour lighting front center console, color-matched - contour lighting with illuminated quattro lettering (for all-wheel drive) on the instrument panel on the passenger side, color-matched - ambient lighting of the instrument panel)
- Assistance Package Plus (Parking Assistance Package with Remote Parking Assist Plus (surround view cameras, Remote Parking Assist Plus) - City Assistance Package (Intersection Assist, Lane Change Warning, Exit Warning, Rear Cross Traffic Assist, Audi pre sense 360°) - Tour Assistance Package (Adaptive Driving Assist, Adaptive Speed Assist, Speed Limiter, Efficiency Assist, Turn Assist, Evasive Steering Assist, Camera-based Traffic Sign Recognition, Emergency Assist, High Beam Assist))
- Black fabric headliner
- Electrically adjustable, heated, and folding exterior mirrors, automatically dimming on both sides, with memory function (including curb view function for the passenger-side exterior mirror with integrated LED turn signal, including heated windshield washer nozzles, aspherical mirror glass. The curb view function tilts the passenger-side exterior mirror downwards when reverse gear is engaged, providing the driver with a better view of the curb.)
- Entry-level LED Audi rings
- Front seat heating (heats seat and backrest center panels; with leather upholstery, sport seats and sport seats plus also seat side bolsters - individually adjustable in multiple stages for driver and front passenger side via the climate control unit)
- Glazing: Acoustic glazing for the side windows (improved external noise insulation through double glazing)
- Head-up display (projects speed and other driver-relevant information from optional equipment such as assistance systems and navigation, as well as warnings, into the driver's direct field of vision; height-adjustable; enables high-contrast, multi-colored display with reduced eye strain from the road)
- Headrests: variable headrests for front seats (with manual adjustment of headrest height and distance)
- Instrument panel and door trim, two-piece, single/multi-color
- Interior elements in synthetic leather (top and bottom) (instrument panel and door sills in synthetic leather black or granite grey; armrest in the doors; center console trim in synthetic leather black, okapi brown, pearl beige; in conjunction with S line sport package: black with contrast stitching in rock grey or rotor grey with contrast stitching in anthracite; in conjunction with Audi design selection: black with contrast stitching in rock grey or pearl beige with contrast stitching in agate grey or sardine brown with contrast stitching in steel grey)
- Manual sunshade (for the rear door windows)
- Package: Storage package (2 cup holders in the rear center armrest, luggage compartment net for fixing to the lashing eyes on the luggage compartment floor)
- Paint finish: Metallic

- Red stitching, Audi Sport GmbH (Valcona leather seat covers, black; front center armrest, black leather with Express Red contrast stitching; Dinamica door panel inserts, black; 3-spoke leather steering wheel with Express Red contrast stitching; black gearshift/ selector lever knob; black leather selector lever boot with Express Red contrast stitching; black seat belts with red edging; dark brushed matte aluminum trim; illuminated aluminum door sills with S logo)
- Seats: Electrically adjustable front seats including memory function for the driver's seat (electric adjustment of seat height, seat longitudinal position, seat and backrest tilt with memory function for driver's side, 2 memory locations per personal user profile for the electrically adjustable front seats and the exterior mirrors, electric 4-way lumbar support)
- Swiveling towbar with electric release (with swiveling ball head, trailer stabilization via electronic stability control (ESC), release via button in the luggage compartment, the integrated swiveling system socket allows continuous operation of electrical devices in the trailer or caravan while driving)
- Radio accessories: Bang & Olufsen Premium Sound System with 3D sound (sound reproduction via 16 speakers including 3D sound speakers, center speaker and subwoofer, 15-channel amplifier with a total output of 705 watts; spatial sound reproduction thanks to the 3D sound feature for the front seats. This is created by additional speakers in the A-pillars, the midrange speakers and Fraunhofer Symphoria technology. The 3D sound can be played back with all sources.)
- Steering wheel: Leather steering wheel in 3-spoke design with multifunction plus, shift paddles and steering wheel heating (height and distance of the steering wheel are manually adjustable - leather of the steering wheel and gear selector knob is color-matched to the selected color of the dashboard top - 12 multifunction buttons for convenient operation of the available infotainment features - shift paddles for manual changing of the driving modes)
- Telephone: Audi Phone Box (Up to two smartphones can be paired with the vehicle simultaneously via Bluetooth, allowing you to play music through the vehicle or make phone calls from either smartphone. The universal smartphone holder connects to the vehicle's antenna, improving both reception and call quality. The smartphone can also be charged wirelessly using the Qi standard or via USB.)
- Wheel: Alloy wheels, 5-V-spoke star design, titanium grey matt (gloss-turned - 8.5 J x 20 with tires 255/40 R 20)

Brief expert findings

Documents submitted	At the time of the inspection, the vehicle registration certificate Part 2 (title) was available, but the vehicle registration certificate Part 1 (document) was not. (Copy)
VIN comparison	The vehicle identification number (VIN) was read from the vehicle and its conformity with the submitted documents was confirmed by the undersigned during the inspection.
Inspection	The inspection conditions were sufficient for the assessment of the vehicle. No lifting equipment or pit was available for inspecting the vehicle. Therefore, inspection of the vehicle's underside was only possible to a limited extent.
Test drive	No test drive/shunting maneuver was carried out during the inspection of the vehicle.
Engine function test	An engine test run was performed.

Value reducing factors

No.	Component group	Description
1	Rear bumper	Rear bumper - Scratch(es) - Paint

Wear and tear

No.	Component group	Description
1	Bonnet	Bonnet - Stone chips - No deduction
2	Front bumper	Front bumper - Stone chips - No deduction
3	Vehicle glazing	Windscreen - Stone chips - No deduction
4	Interior	Interior - Scratch(es) - No deduction
5	Sill - left side	Sill - Scratch(es) - No deduction

The vehicle shows signs of wear and tear commensurate with its age and use.

Previous damages

No.	Previous damage	Extent of damage (Net)
1	Side - left, Provided by user / customer, from 7 Jul 2023	1.386,91 €
2	Front, Provided by user / customer, from 6 Dec 2023	1.763,20 €

Repainting

No.	Repainting
1	Side panel - rear left side, Professionally carried out, Invoice of repair done Non-existent
2	Door - rear left side, Professionally carried out, Invoice of repair done Non-existent

Paint coat thickness measurement

Side panel - rear left side	169 µm	Door - rear left side	189 µm

Order/Scope of Order

An order was placed to prepare a sales report for the described vehicle. This report includes the following:

- Description of key vehicle information
- Documentation of equipment features
  (Delivery by third-party service providers)
- Documentation of damage, defects, missing parts
- Documentation of prior damage, unrepaired prior damage, repainting
- A brief visual or functional inspection of the equipment details, if possible.
  (Functional testing of driver assistance systems is not included in the scope of services!)
- a photographic documentation of the vehicle

Basis for the order

This product is based on the guidelines for vehicle returns and valuations published by Alphabet Fleet GmbH. The expert makes the specific findings in each individual case objectively, within the framework of the prescribed standards, based on their own expertise.

The vehicle inspection takes place in a fully assembled, unassembled state.

Damage or defects that can only be detected during disassembly/diagnostic work or through further investigation remain within the realm of prognostic risk. An increased risk exists due to concealed defects caused by fraudulent misrepresentation and which were not identifiable by the expert.

Damage or defects resulting from normal use or wear and tear of the vehicle will be accepted in accordance with the applicable standard.

There was no explicit identification or monetary consideration of the expected features within the product.

Features which, in their nature and extent, slightly exceed normal use but do not constitute unacceptable damage, will be documented and indicated as signs of wear, if applicable.

Damage or defects that, according to the applicable standard, can no longer be attributed to normal use or wear and tear are listed under "Value Reducing Factors" in the product description.

Depending on the product specification, a monetary ID can be provided. If this takes place, the costs can be 100% d or pro rata depending on the vehicle's age and mileage.

Previous damages

According to available information previous damages were repaired at the vehicle. Traces of repairs, which allow conclusions about the area of repair, were not recognizable during the inspection.

Comments

- Die Unterbodenbesichtigung war nur ebenerdig & eingeschränkt möglich. Mehrkosten sind möglich.

- Winterradsatz ist kein Bestandteil des Auslieferumfangs.

TÜV SÜD Auto Partner GmbH
Wiesenring 2
04159 Leipzig

Inspection location
ARS Altmann AG Automobillogistik
Römerstraße 3
64560 Riedstadt



Figure 1: Diagonal front (left)



Figure 2: Diagonal front (right)



Figure 3: Diagonal rear (left)



Figure 4: Diagonal rear (right)



Figure 5: Interior - front



Figure 6: Interior - rear



Figure 7: Instrument cluster



Figure 8: Instrument panel



Figure 9: Cargo area




Figure 10: VIN



Figure 11: Mounted tyres




Figure 12: Documents



Figure 13: Documents




Figure 14: Documents



Figure 15: Documents




Figure 16: Additional tyres




Figure 17: Navigation



Figure 18: Misc.




Figure 19: Misc.



Figure 20: Misc.



Figure 21: Misc.




Figure 22: Misc.




Figure 23: Misc.




Figure 24: Misc.



Figure 25: Misc.



Figure 26: Misc.



Figure 27: Misc.



Figure 28: Misc.



Figure 29: Misc.



Figure 30: Misc.



Figure 31: Misc.



Figure 32: Misc.




Figure 33: Misc.



Figure 34: Misc.




Figure 35: Misc.



Figure 36: Misc.




Figure 37: Misc.



Figure 38: Misc.



Figure 39: Misc.



Figure 40: Misc.



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Paint



Damage 1: Rear bumper: Rear bumper - Scratch(es) - Paint




Damage 1: Rear bumper: Rear bumper - Scratch(es) - Paint




Repainting 1: Side panel - rear left side



Repainting 1: Side panel - rear left side



Repainting 2: Door - rear left side



Repainting 2: Door - rear left side