APPRAISAL REPORT



IDENTIFICATION VEHICLE

Driver name:	ASSE I
Make:	BMW
Model / version:	X5
Vin:	WBATA610209R40689
Plate:	2DMF189
Mileage:	102849
SOH:	
First registration:	25/04/2023
Color:	

ADDITIONAL INFORMATION


Category:	
Transmission:	
Interior color:	
Metallic paint:	?
Type of lining:	
Board computer reset:	?

DOCUMENTS


Certificate of conformity:	✓
Registration certificate:	✓
Registration certificate 2:	✓
Insurance certificate:	✗
Maintenance book:	
Number of keys:	2
Original key:	✓


PICTURES





















































VIN INFORMATION

Transmission automatique	8 rapports	4 roues motrices
Matière : alliage	Lettre repère (J)	Diamètre avant 19
Diamètre arrière 19	Largeur avant 9,0	Largeur arrière 9,0
Diamètre avant 19	Diamètre arrière 19	Hauteur avant 50
Hauteur arrière 50	Indice de vitesse avant W	Indice de vitesse arrière W
Largeur avant 265	Largeur arrière 265	Climatisation automatique 4 zones
Climatisation réfrigérant 1234YF	Finition intérieure Aluminium	Hybride essence
2998 cm3	3.00 litres	210 kw
285 ch	Euro 6	Métallisée vernissée
Rétroviseur gauche jour/nuit automatique	Rétroviseur droit jour/nuit automatique	Siège avant gauche chauffant
Sièges avant chauffants	Siège avant gauche à réglage électrique	Sièges avant à réglage électrique
Siège avant gauche à réglage mémorisé	Sièges avant à réglage mémorisé	Sièges avant sport

Suspension pneumatique	Aide au stationnement avant	Aide au stationnement arrière
Assistance au parking	Caméra avant	Caméra arrière de recul
Alarme	Appel de secours	Attelage avec boule rétractable électrique
Fixotoit aluminium satiné	Protection piéton	Assistant maintien de la voie
Freinage d'urgence assistée autonome (urbain)	Avertisseur d'angle mort	Avertisseur de collision avant
Contrôle pression des pneus	depuis 01.23	éclairage d'ambiance
mesures CO2 étendues	Teleservices	tuner DAB
BMW Live Cockpit Professional	protection acoustique des piétons	spécifique Europe

EQUIPMENT

Board computer:	?	**Central locking:**	?
Compressor:	×	**Cruise control:**	?
Gps:	?	**Power steering:**	?
Rear parking sensor:	?	**Repair kit:**	×
Front seats heated:	?	**Steering wheel:**	?
Electric windows:	?	**Climate control type:**	
Headlighting type:		**Tow bar type:**	
Charging cables:	0	**Fast charging cables:**	0

TIRES

Position	Depth	Brand	Dimensions	Type	Rims	Runflat
Front left	5 mm	Pirelli	265/50/R19/118V	Winter	Aluminium	×
Front right	5 mm	Pirelli	265/50/R19/118V	Winter	Aluminium	×
Rear left	5 mm	Pirelli	265/50/R19/118V	Winter	Aluminium	×
Rear right	5 mm	Pirelli	265/50/R19/118V	Winter	Aluminium	×

DAMAGES SUMMARY

NOT ACCEPTABLE / TO BE INVOICED

#	Location	Damage type
1	Windscreen	Stone chip(s)
2	Wing FL	Dent(s) and scratch(es)
3	Bumper R	Dent(s) and scratch(es)

Total: 3

ACCEPTABLE / NOT TO BE INVOICED

#	Location	Damage type	Renta®	Repaired	Already invoiced
4	Bodywork	Dent(s) and scratch(es)	✓	×	×

Total: 1

DAMAGES DETAILS

1 - Windscreen - Stone chip(s)





2 - Wing FL - Dent(s) and scratch(es)





3 - Bumper R - Dent(s) and scratch(es)






4 - Bodywork - Dent(s) and scratch(es) - Renta®








SIGNATURE - IN AGREEMENT WITH THE RECORDED DAMAGES

Expert

10/09/2026 15:30

